

**UNITED STATES  
DEPARTMENT OF LABOR  
MINE SAFETY AND HEALTH ADMINISTRATION  
Metal and Nonmetal Mine Safety and Health**

**REPORT OF INVESTIGATION**

**Surface Nonmetal Mine  
(Sand and Gravel)**

**Fatal Electrical Accident  
September 13, 2011**

**Plant #1  
DeAtley Crushing Co.  
Oakesdale, Whitman County, Washington  
Mine ID No. 10-01658**

**Investigators**

**Gary W. Hebel  
Supervisory Mine Safety and Health Inspector**

**Merlin J. McMullen  
Mine Safety and Health Inspector**

**Maxwell A. Clark  
Electrical Engineer**

**Originating Office  
Mine Safety and Health Administration  
Western District  
991 Nut Tree Road, Second Floor  
Vacaville, California 95687  
Wyatt S. Andrews, District Manager**

UNITED STATES  
DEPARTMENT OF LABOR  
MINE SAFETY AND HEALTH ADMINISTRATION  
Metal and Nonmetal Mine Safety and Health

REPORT OF INVESTIGATION

Surface Nonmetal Mine  
(Sand and Gravel)

Fatal Electrical Accident  
September 13, 2011

Plant #1  
DeAtley Crushing Co.  
Oakesdale, Whitman County, Washington  
Mine ID No. 10-01658

Investigators

Gary W. Hebel  
Supervisory Mine Safety and Health Inspector

Merlin J. McMullen  
Mine Safety and Health Inspector

Maxwell A. Clark  
Electrical Engineer

Originating Office  
Mine Safety and Health Administration  
Western District  
991 Nut Tree Road, Second Floor  
Vacaville, California 95687  
Wyatt S. Andrews, District Manager



## **OVERVIEW**

James Hussey, quality control person, age 38, was killed on September 13, 2011, while working on an energized electrical circuit. Hussey was attempting to reverse the polarity on an energized power cable at a control trailer when he received a fatal electrical shock.

The accident occurred because management procedures failed to ensure that persons de-energize an electrical circuit prior to performing work on it. The system was not locked out, tagged out, or tested to verify it was de-energized.

## **GENERAL INFORMATION**

Plant #1, owned and operated by DeAtley Crushing Co., is a portable operation producing construction sand and gravel. The principal operating official is Brien DeAtley, President. At the time of the accident, Plant #1 was located approximately 5 miles east of Oakesdale, Washington on State Route 27. The mine operates one shift per day, five days a week. Total employment is 10 persons.

The last regular inspection at this operation was completed on August 21, 2011.

## **DESCRIPTION OF THE ACCIDENT**

On the day of the accident, September 13, 2011, James Hussey (victim) reported for work at 6:00 a.m. Hussey, Andy Heitzman, Superintendent, and Brian Goedhart, Nicholas Kress, Jeff Graybill, and Jason Bentley, crew members, replaced two Caterpillar SR4B generators with two new generators of the same type and size for the portable crushing plant.

At approximately 9:20 a.m. the newly installed generators were started for rotation testing of the motors. While testing, they found the motor rotation from one generator was reversed, requiring two phase conductors to be swapped. Hussey hand signaled to Bentley to turn off the generator and then began working on the cable connections located on the opposite side of the MCC trailer. He placed a metal wrench onto the exposed connections and was electrocuted when he contacted an energized conductor. Heitzman called for Emergency Medical Services. (EMS). Cardiopulmonary Resuscitation (CPR) was performed until local paramedics arrived on scene.

## **INVESTIGATION OF THE ACCIDENT**

The Mine Safety and Health Administration (MSHA) was notified at 10:30 a.m. PST, by a telephone call from Michael Osburn, estimator/safety manager, to MSHA's emergency call center. Kevin G. Hirsch, Assistant District Manager, was notified and an investigation was started the same day. An order was issued pursuant to section 103(j) of the Mine Act to ensure the safety of miners.

MSHA's investigators traveled to the mine, made a physical inspection of the accident scene, interviewed employees, and reviewed documents and work procedures relevant to the accident. MSHA conducted the investigation with the assistance of mine management and employees.

## DISCUSSION

### Location of the Accident

The accident occurred at the MCC trailer, which was located at ground level about 30 feet from the primary plant and 50 feet from the generators. The MCC trailer was a metal trailer with a wooden floor. The electrical feeder box was located outside the trailer on the side opposite the generators.

### Electrical Equipment

#### Generators

Two generators of the same type were involved in the accident, gen 1 and gen 2. They were three phase wye configured Caterpillar SR4B generators with 480 volt line to line rating at 60 Hertz with a supply capacity of 1091 amps. Gen 1 and gen 2 were located on top of a single generator trailer. Each generator had one 1200 amp breaker.



Trailer mounted Generator

### Physical Layout and Events that Led to the Accident

The generators, gen 1 and gen 2 ran independently. Gen 1 and gen 2 exclusively fed a separate main fused switch at the MCC, main switch 1 and main switch 2 respectively.



Main Switches Located Inside MCC

The terminations which fed the line side of the two main switches, line side 1 and line side 2, were located at opposite sides of the MCC.




Power Entrance Line Side 1



Power Entrance Line Side 2

Referring to the Physical Layout figure below, line side 1 was facing the generator trailer with the generator trailer in view. Line side 2 was on the opposite side; therefore, the MCC was blocking the view of the generator trailer.



Physical Layout

At the time of the accident, James Hussey was wiring the two Caterpillar SR4B generators, gen 1 and gen 2, to the two independent main switches, main switch 1 and main switch 2, at the MCC power entrance line side 1 and line side 2. During motor rotation testing, it was discovered that two of the phases were reversed on load side 2. One of the generators was de-energized, gen 1. Gen 2 was not de-energized. Hussey started to swap phase conductors fed from gen 2 at the power entrance line side 2 to the MCC. Unaware, Hussey started working on the energized line, line side 2, and received a fatal electrical shock.

### **Training and Experience**

James Hussey had 3 years, 22 weeks and 6 days of experience all working for this mine operator. Investigators reviewed the training records for the victim and found the task training and annual refresher training records to be up-to-date. However, the investigators found that the training provided did not specifically address the hazards resulting in the accident. After the accident, management established policies and procedures to ensure that persons safely perform work on electrical circuits. All persons were trained regarding these new policies and procedures.



## **ROOT CAUSE ANALYSIS**

A root cause analysis was conducted and the following root cause was identified:

*Root Cause:* Management policies and procedures failed to ensure that persons were specifically trained to verify that electrical circuits were de-energized and locked out prior to performing work on them.

*Corrective Action:* Mine management implemented a Standard Operating Program including a new lock out, tag out, and verification system for all of their portable operations. All persons have been trained regarding the new policies and procedures. A company electrician will be at the site any time a plant is set-up, taken down, or when electrical work is performed to ensure that all safety procedures are followed.

## **CONCLUSION**

The accident occurred because management procedures failed to ensure that persons de-energize an electrical circuit prior to performing work on it. The system was not locked out, tagged out, or tested to verify it was de-energized.

## **ENFORCEMENT ACTIONS**

### **Issued to DeAtley Crushing Co.**

**ORDER No. 8605548** was issued September 13, 2011; it is under the provisions of Section 103(j) of the Mine Act:

An accident occurred at this location on September 13, 2011, at 9:30 a.m. This order is being issued to prevent the destruction of any evidence which would assist in the investigation of the cause or causes of the accident. It prohibits all activity at the Mine Switch Van, Quality Control Van, Generator Trailer and the Diesel Storage tank area, except to the extent necessary to prevent or eliminate an imminent danger, until MSHA has determined that it is safe to resume normal mining operations in this area. This order was issued verbally to the mine operator at 11:05 a.m. on September 13, 2011, and is now been reduced to writing.

This order was modified to a 103(k) order when investigators arrived at the mine. It was terminated on September 20, 2011, after conditions that contributed to the accident no longer existed.

**CITATION No. 8608406** was issued September 18, 2011, under the provisions of Section 104(a) of the Mine Act for a violation of 30 CFR 56.12017:

A fatal accident occurred at this operation on September 13, 2011, when a miner contacted an energized electrical conductor while attempting to reverse polarity on an energized power cable at the control trailer. The power circuits were not de-energized and locked out before work to change the polarity began. Suitable warning signs were not posted and suitable hot line tools were not being used.

This citation is a "Rules to Live By" priority standard and was terminated on September 18, 2011, after all persons at this mine were retrained to lock-out, tag-out, and test electrical circuits prior to performing work on them.

Approved By:



Wyatt S. Andrews  
District Manager



Date

## APPENDIX A

### Persons Participating in the Investigation

#### **DeAtley Crushing Co.**

Michael Osburn..... Estimator / Safety Manager

Andrew Heitzman..... Plant 1 Superintendent

#### **Mine Safety and Health Administration**

Gary W. Hebel..... Supervisory Mine Safety and Health Inspector

Merlin J. McMullen .....Mine Safety and Health Inspector

Maxwell A. Clark ..... Electrical Engineer

## APPENDIX B

### Victim Data Sheet

Accident Investigation Data - Victim Information

**U.S. Department of Labor**  
Mine Safety and Health Administration



Event Number:

Victim Information: <input type="text" value="1"/>															
1. Name of Injured/Ill Employee: <i>James C. Hussey</i>			2. Sex: <i>M</i>		3. Victim's Age: <i>38</i>		4. Degree of Injury: <i>01 Fatal</i>								
5. Date(MM/DD/YY) and Time(24 Hr.) Of Death: <i>a. Date: 09/13/2011 b. Time: 9:30</i>						6. Date and Time Started: <i>a. Date: 09/13/2011 b. Time: 9:30</i>									
7. Regular Job Title: <i>199 Quality Control Worker</i>				8. Work Activity when Injured: <i>020 Electrical Work</i>				9. Was this work activity part of regular job? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No							
10. Experience			a. This			b. Regular			c. This			d. Total			
Years	Weeks	Days	Years	Weeks	Days	Years	Weeks	Days	Years	Weeks	Days	Years	Weeks	Days	
Work Activity:	<i>3</i>	<i>22</i>	<i>6</i>	Job Title:	<i>3</i>	<i>22</i>	<i>6</i>	Mine:	<i>3</i>	<i>22</i>	<i>6</i>	Mining:	<i>3</i>	<i>22</i>	<i>6</i>
11. What Directly Inflicted Injury or Illness? <i>042 Energized Conductors</i>						12. Nature of Injury or Illness: <i>210 Electrocutation</i>									
13. Training Deficiencies															
Hazard:		New/Newly-Employed				Experienced Miner:				Annual:		Task:			
14. Company of Employment: (If different from production operator) <i>Operator</i>						Independent Contractor ID: (if applicable)									
15. On-site Emergency Medical Treatment															
Not Applicable:		First-Aid:		CPR:		EMT:		Medical Professional:		None:					
		<input checked="" type="checkbox"/>				<input checked="" type="checkbox"/>									
16. Part 50 Document Control Number: (form 7000-1) <i>220112720021</i>						17. Union Affiliation of Victim: <i>9999 None (No Union Affiliation)</i>									