


LEGEND	
	PLASTERED CONCRETE BLOCK STOPPING
	PLASTERED OMEGA BLOCK STOPPING
	STOPPING WITH MANDOOR
	DAMAGED VENTILATION CONTROLS
	REGULATOR
	PERMANENT SEAL LOCATION
	DAMAGED SEAL LOCATION
	CHECK CURTAIN
	OVERCAST
	DAMAGED OVERCAST
	FAN HOUSE
	EQUIPMENT DOOR
	STOPPING DEBRIS
	FALL
	WATER
	CRIBS
	CONVEYOR BELT
	TRACK
	BOTTOM MINING AREA
	OMEGA BLOCK
	PARTIAL OMEGA BLOCK
	CONCRETE BLOCK
	PARTIAL CONCRETE BLOCK
	HALF HEADER
	OVERCAST DECKING
	WEDGE
	CRIB BLOCK
	I-BEAM
	ELONGATED OBJECT
	FLYBOARD
	FIRE EXTINGUISHER
	KENNEDY STOPPING PANEL
	PAGER LOCATION
	PAGER LINE CONNECTION
	CO SENSOR LOCATION



See Appendix H-2

See Appendix H-5

(Inby direction) Few damaged pie pans bent inby between xcuts in #8 entry
 Roof fall
 Outby fall shown on map, roof fall visible location inby xcut appears dark dust covered outby end of fall just inby bottom cut
 Approx. inby end of bottom cut