

Working Around Bins, Hoppers, and Draw-Off Tunnels



Best Practice Series

BP-64

Fatalities in the anthracite industry have occurred around bins, hoppers, or draw-off tunnels where miners were using a bar to break frozen lumps that were in the loads being transported from frozen stockpiles.

When working around bins, hoppers, and draw-off tunnels, **REMEMBER:**

- Establish safe work procedures for any work conducted in these areas.
- Communicate frequently with other miners.
- Never work over frozen material feeding into bins, hoppers, and draw-off tunnels.
- Disconnect and lock out the circuits controlling the feed before entering.
- Always wear a safety belt, lanyards, and/or tag lines when entering these areas, with a second person attending the tag line.
- Avoid working around draw holes to feeders and draw-off tunnels on foot, and if necessary, do not work with your back to steep stockpiled material which could shift and slide without warning.
- Be especially conscious of these hazards during winter months.

Don't Be the Next Miner Suffocated!!

Visit the MSHA home page at www.msha.gov

U.S. Department of Labor
Mine Safety and Health Administration

August 2000