

PR001
11-Jun-13

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 05/17/2013 01:30 AM		4. Date/Time of Death 05/17/2013 03:40 AM		5. Fatal Case No 7				
6. Mine Information :												
a) Mining Company Name Chevron Mining Inc			b) Mine Name Questa Mine & Mill			c) Parent of Mining Company Chevron Corporation						
7. Mine Location :		a) City Questa		b) County Taos		c) State NM		8. Mine ID Number: 29-01267		9. Union: YES		
10. Primary Mineral Mined: MOLYBDENUM ORE MINING			11. Number of Mine Employees:		a) Total 310		b) Underground 122		c) Open Pit/Quarry 46		d) Mill/Prep Plant 142	
12. Contractor Name:						13. Union		14. Contractor ID Number:				
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code				
16. Number of Contractor Employees:		a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other		
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:						
a) Mine Employees: 168		b) Contractor Employees:				a) Mine Employees: 0		b) Contractor Employees:				
19) Location of Accident										20. Mining Height:		
<input checked="" type="checkbox"/> 01-Underground		<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet Inches		
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility						
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1										
23. Victim Information :												
a) Name Issac A. Garcia				b) Age 22								
c) Regular Job Title: Mucker				d) Activity at Time of Accident: Checking derailed ore car				<input checked="" type="checkbox"/> Mine Employee				
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days				
a) Total:		0 28		b) at the mine: 0 28		c) at activity (23d) 0 28		d) with Contractor				
25. Autopsy Performed: If Yes, Location YES Albuquerque, NM								26. Mine Telephone No.: (575) 586-7507				
27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations): The victim was checking a derailed ore car when he was pinned between it and another ore car.												
The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.												
28. Equipment Manufacturer: ASEA Inc.						29. Model: 10-ton ore car						
30. District: M5000 South Central				32. Field Office: Albuquerque NM				33. Event Number: 6609622				
34. Accident Investigator: William D. Odell				35. MSHA Person Notified: Elwood M. Burriss				Date 05/17/2013		Time 01:41 A		
36. Type of Report: Amended				37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>				Date 05/17/2013				
38. Reason For Amendment: Amendment No. 1 Items 3, 4, and 35												