05/14/2014

lk)
W/

PR001	P	Preliminary Report of Accident U.S. Department of Labor Mine Safety and Health Administration								
04-Aug-14	-			Port	110010101	Min	e Safety an	d Health Administr	ation	
1. Accident Type:	2. Accident C	ident Classification			3. Date/Time	3. Date/Time of Accident 4. Date/			5. Fatal Case No	
Fatal Injury	Machinery	Machinery			05/14/20	14 02:15 PM	05/14	/2014 04:12 PM	6	
6. Mine Information :							-			
a) Mining Company Name			b) Mine Name			•	c) Parent of	Mining Company		
M-Class Mining LLC			MC#1 Mine	C#1 Mine			Coalfield Transport Inc			
7. Mine Location :	a) City		b) County		c) State	c) State 8.		Number:	9. Union:	
Ma	cedonia		Franklin		IL		11-	03189	NO	
10. Primary Mineral Mined: BITUMINOUS COAL UN	NDERGROU		Number of Mine Employees:	a) Total 330	b) Underground 275	c) Open Pit	/Quarry	d) Mill/Prep Pla 55	e) Other	
12. Contractor Name:						13. Ur	nion	14. Contr	ractor ID Number:	
15. Contractor Address:	a) Ci	ty			b) County	<u> </u>	c) Stat	e d)	Zip Code	
16. Number of Contractor En	nployees:	a) Tot	cal b)	Underground	c) Op	en Pit/Quarry	ď) Mill/Prep Plant	e) Other	
					1					
17. Number of Persons in Min				0		of Persons Unac			- 0	
a) Mine Employees: 19) Location of Accident	131	b) Con	tractor Employee	s: 0	a) Mine I	Employees:	0	b) Contractor E	1 1	
X 01-Underground	3	03-Ope		=	nce Mining	30-Mill/Prej		Other (specify)	20. Mining Height: Feet Inches	
02-Surface at Undergroo 21. Nonfatal Injuries:		Fatal Inju	dge Mining	U8-Retre	eat Mining	99-Office Fa	icility		9 3	
21. Nomatai mjuries:	0	. Fatai iijt	1							
23. Victim Information :	Wi	a) Nan Iliam-Dan	ne niel H. Payne		b) Age 25					
c) Regular Job Title:	***	man bar		at Time of A				X	Mine Employee	
Roof Bolter					Tramming	Roof Bolter				
24. Experience : Years W	eeks Days		Years Wee	ks Days		Years Weel	ks Days		Years Weeks Days	
a) Total: 2	15 0	b) at the	mine: 2 15	0 c	at activity (23d)	2 15	0	d) with Contractor		
25. Autopsy Performed:	If Yes, Loca						26. Mine	Telephone No.:		
VEC Franklin Co										
YES Franklin Co	unty Hospital							(618) 435-942	3	
27. Description of Accident (i	nclude equipm	ent involve	,		*):		
	include equipm 2014, at app s walking alor	ent involve roximateling side of	y 2:15 p.m., a rof the roof bolter.	oof bolter op This accid	perator was fata ent occurred on	lly injured. The the roadway to	victim was): s pinned between	a roof bolting machine	
27. Description of Accident (i On Wednesday, May 14, and the coal rib as he was The section equipment was The information provided in	include equipm 2014, at app s walking alor as in the proc	ent involver roximatel ng side of eess of be	y 2:15 p.m., a ref the roof bolter. eing removed fr	oof bolter op This accid om the long	perator was fata ent occurred on wall set up roor	lly injured. The the roadway to ns.	victim was): s pinned between g Portal No. 1 long	a roof bolting machine gwall tailgate section.	
27. Description of Accident (i On Wednesday, May 14, and the coal rib as he was The section equipment was	this notice is bacident.	ent involver roximatel ng side of cess of be	y 2:15 p.m., a ref the roof bolter. eing removed fr	oof bolter op This accid om the long	perator was fata ent occurred on wall set up roor	lly injured. The the roadway to ns.	victim was	e nature of the incid	a roof bolting machine gwall tailgate section.	
27. Description of Accident (i On Wednesday, May 14, and the coal rib as he was The section equipment was The information provided in regarding the cause of the acc 28. Equipment Manufacturer	this notice is bacident.	ent involver roximatel ng side of eess of be	y 2:15 p.m., a ref the roof bolter. eing removed from the	oof bolter op This accid om the long	perator was fata ent occurred on wall set up roor	lly injured. The the roadway to as.	victim was): s pinned between g Portal No. 1 long	a roof bolting machine gwall tailgate section.	
27. Description of Accident (i On Wednesday, May 14, and the coal rib as he was The section equipment was The information provided in regarding the cause of the acc 28. Equipment Manufacturer 30. District:	this notice is bacident.	ent involver roximatel ng side of cess of be	y 2:15 p.m., a ref the roof bolter. eing removed fr	oof bolter op This accid om the long	erator was fata ent occurred on wall set up roor	lly injured. The the roadway to as.	victim was	be nature of the incid DDR-17 33. Event Number:	a roof bolting machine gwall tailgate section.	
27. Description of Accident (i On Wednesday, May 14, and the coal rib as he was The section equipment was The information provided in regarding the cause of the acc 28. Equipment Manufacturer 30. District:	this notice is bacident.	ent involver roximatel ng side of cess of be	y 2:15 p.m., a ref the roof bolter. eing removed from the	cof bolter of This accid om the long LY and does Ee: Mario	erator was fata ent occurred on wall set up roor	lly injured. The the roadway to as.	victim was	be nature of the incid DDR-17 33. Event Number:	a roof bolting machine gwall tailgate section.	
27. Description of Accident (i On Wednesday, May 14, and the coal rib as he was The section equipment was The information provided in regarding the cause of the acc 28. Equipment Manufactures 30. District: C0800 Vince	this notice is bacident.	ent involver roximatel ng side of cess of be	y 2:15 p.m., a ref the roof bolter. eing removed from the	Coof bolter op This accid om the long LY and does Mario 35. MSHA I	ent occurred on wall set up roor mot represent final	lly injured. The the roadway to as.	victim was	DDR-17 33. Event Number:	a roof bolting machine gwall tailgate section. ent or conclusions	

Harry Wilcox

38. Reason For Amendment:

Update experience and location of autopsy.

Amended