

Preliminary Report of Accident



1. Accident Type: Fatal Injury	2. Accident Classification Electrical	3. Date/Time of Accident 08/20/2014 10:55 AM	4. Date/Time of Death 08/20/2014 12:29 PM	5. Fatal Case No 09
6. Mine Information :				
a) Mining Company Name CONSOL Buchanan Mining Company LLC		b) Mine Name Buchanan Mine #1		c) Parent of Mining Company CONSOL Energy Inc
7. Mine Location :			8. Mine ID Number:	9. Union:
a) City Raven		b) County Buchanan		c) State VA
			44-04856	NO
10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND	11. Number of Mine Employees:		d) Mill/Prep Plant 41	e) Other
		a) Total 398	b) Underground 357	
12. Contractor Name:			13. Union	14. Contractor ID Number:
15. Contractor Address:				
a) City		b) County		c) State
d) Zip Code				
16. Number of Contractor Employees:				
a) Total 13		b) Underground 13		c) Open Pit/Quarry
17. Number of Persons in Mine at Time of Accident:			18. Number of Persons Unaccounted For:	
a) Mine Employees: 82		b) Contractor Employees: 13		
			a) Mine Employees: 0	b) Contractor Employees: 0
19) Location of Accident				20. Mining Height:
<input checked="" type="checkbox"/> 01-Underground		<input type="checkbox"/> 03-Open Pit		Feet Inches 7 9
<input type="checkbox"/> 02-Surface at Underground		<input checked="" type="checkbox"/> 07-Advance Mining		
		<input type="checkbox"/> 06-Dredge Mining		
		<input type="checkbox"/> 08-Retreat Mining		
		<input type="checkbox"/> 09-Office Facility		
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1		
23. Victim Information :				
a) Name Michael J. Justice			b) Age 41	
c) Regular Job Title: Maintenance Supervisor				
d) Activity at Time of Accident: Maintenance Supervisor				<input checked="" type="checkbox"/> Mine Employee
24. Experience :				
Years Weeks Days		Years Weeks Days		Years Weeks Days
a) Total: 19 3 4		b) at the mine: 4 3 4		c) at activity (23d) 2 15 0
				d) with Contractor
25. Autopsy Performed: YES Richmond, VA				26. Mine Telephone No.: (276) 498-6027

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was fatally electrocuted while troubleshooting a Fletcher DDR-15A roof bolting machine on 24 Right section. The panel cover was removed from the machine and the victim was working inside the energized panel when the accident occurred.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Fletcher		29. Model: DDR-15A	
30. District: C0500 Norton		32. Field Office: Vansant VA	
33. Event Number: 4412976			
34. Accident Investigator: Dennis A. Shortt		35. MSHA Person Notified: Scott M. Beverly	
		Date 08/20/2014	Time 11:10 A
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Rhonda Hays	
		Date 08/21/2014	
38. Reason For Amendment:			