PR001 17-Jan-14

## **Preliminary Report of Accident**

U.S. Department of Labor

Mine Safety and Health Administration

1. Accident Type: 2. Accident Class			ation	3. Date/Tim	3. Date/Time of Accident		4. Date/Time of Death			
Fatal Injury	ry Powered Hau		e		01/16/20	01/16/2014 09:05 PM		01/16/2014 09:05 PM		
6. Mine Information :										
a) Mining Company I	Name		b) Mine Name				c) Parent of Mining	Company		
Mettiki Coal WV,	LC		Mountain Vie	w Mine			Alliance Resource	e Partners L	P	
7. Mine Location :	a) (	City	b) C	ounty	c) State	!	8. Mine ID Numbe		9. Union:	
	Davis		Tucker		WV		46-09028		NO	
10. Primary Mineral BITUMINOUS CO		ROUN	11. Number of Mine Employees:	a) Total	b) Underground	l c) Open P	- •	Aill/Prep Plant	•	
12. Contractor Name:		100.1		180	156	13 1	O Jnion	24	ctor ID Number:	
								1 comma		
15. Contractor Addre	ss:	a) City			b) County		c) State	d) Z	ip Code	
16. Number of Contractor Employees: a) Total b) Underground c) Open Pit/Quarry d) Mill/Prep Plant e) Other										
17. Number of Persons in Mine at Time of Accident: 18. Number of Persons Unaccounted For:										
a) Mine Employees: 55 b) Contractor Employees: 0 a) Mine Employees: 0 b) Contractor Employees: 0										
19) Location of Accide			. This	07.11			m .		20. Mining Height:	
X 01-Underground 02-Surface at Underground		03-Open Pit 06-Dredge Mining					ill/Prep Plant Other (specify)  Fice Facility		Feet Inches	
02-Surface at Underground 06-Dredge Mining 08-Retreat Mining 99-Office Facility 7  21. Nonfatal Injuries: 22. Fatal Injuries:								, ,		
ar. Homean injures.	0		1	<u> </u>						
23. Victim Informatio	•	a) Name b) Age lel Lambka 20								
c) Regular Job Title: d) Activity at Time of Accident:										
General Inside Laborer General Inside Laborer										
•	ears Weeks Day 2 24 0		Years We ne mine: 17	_	-444 (22.4)	Years We		C	Years Weeks Days 0 0 0	
a) Total:  25. Autopsy Performe		, Location	le mine: 17	0 6)	at activity (23d)	<u> </u>	26. Mine Teleph	Contractor		
	antown, WV	,						1) 259-4910		
27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):										
On Thursday, January 16, 2014, at approximately 9:00 PM, a general inside laborer was fatally injured. The victim was standing between the coal rib and the feeder on the F-Main Section. The securing post (jill-poke) became dislodged and allowed the feeder to shift and pin the victim between the rib and the frame of the feeder. The victim had just finished connecting a chain between the feeder and the tail piece when the accident occurred.										
The information provi regarding the cause of		is based on p	oreliminary data O	NLY and does	not represent fin	al determination	s regarding the natu	re of the incide	nt or conclusions	
28. Equipment Manufacturer:  Joy Machinery Co. (Joy Manufacturing C					Co)	29. Model:	BF	-14-37-74C		
30. District: C0300	32. Field Offi	ce: McHe	nry		33. Eve	nt Number:				
34. Accident Investigator:			35. MSHA Pers					nte	Time	
Franklin D. Tho		Gregory			[DataTrac]	01/16/	2014	09:15 P		
36. Type of Report:	Initial	37.	Name of Preparer	and Date Prepa LS for Bob I	red E. Cornett, DN	KOR NE		Date 01/17/201	4	
38. Reason For Amen						70. 1.0		01/11/201		