

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Machinery		3. Date/Time of Accident 12/02/2016 11:00 AM		4. Date/Time of Death 12/02/2016 11:00 AM		5. Fatal Case No 9							
6. Mine Information :															
a) Mining Company Name Oak Grove Resources LLC			b) Mine Name Oak Grove Mine			c) Parent of Mining Company Virginia Conservation Legacy Fund (VCLF)									
7. Mine Location :		a) City Hueytown		b) County Jefferson		c) State AL		8. Mine ID Number: 01-00851		9. Union: YES					
10. Primary Mineral Mined: BITUMINOUS COAL UNDERGROUND			11. Number of Mine Employees:		a) Total 414	b) Underground 377	c) Open Pit/Quarry		d) Mill/Prep Plant	e) Other 37					
12. Contractor Name: Zhengzhou Coal Mining Mach (Group) Ltd America						13. Union NO		14. Contractor ID Number: B5251							
15. Contractor Address:		a) City Pittsburgh		b) County Butler		c) State PA		d) Zip Code 16002							
16. Number of Contractor Employees:		a) Total 2		b) Underground 2		c) Open Pit/Quarry 0		d) Mill/Prep Plant 0		e) Other 0					
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:										
a) Mine Employees: 68		b) Contractor Employees: 2			a) Mine Employees: 0		b) Contractor Employees: 0								
19) Location of Accident									20. Mining Height:						
<input checked="" type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)			Feet	Inches				
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input checked="" type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility						7	5			
21. Nonfatal Injuries:			22. Fatal Injuries: 1												
23. Victim Information :															
a) Name Yujun Qian					b) Age 36										
c) Regular Job Title: Shield Designer/Engineer				d) Activity at Time of Accident: Installation of Longwall Shields						<input checked="" type="checkbox"/> Contractor Employee					
24. Experience :		Years		Weeks		Days		Years		Weeks		Days			
a) Total:	0	1	0	b) at the mine:	0	0	0	c) at activity (23d)	10	0	0	d) with Contractor	2	0	0
25. Autopsy Performed: If Yes, Location NO								26. Mine Telephone No.: (205) 436-7172							

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

During set-up procedures for a new longwall installation, two technical representatives for the shield manufacturer were in the process of adding components to the hydraulic system of a longwall shield. One technician was positioned inside the shield near the hinge point when the shield collapsed, crushing the victim. Responders were able to raise the shield to recover the victim. The victim was transported to the surface where he was pronounced dead.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Zhengzhou Coal Mining Machinery				29. Model: ZY10580/12.2/24.4D					
30. District: C1100 Birmingham		32. Field Office: Bessemer AL				33. Event Number: 6492528			
34. Accident Investigator: Timothy R. Stockman				35. MSHA Person Notified: Ronald D. Caudill		Date 12/02/2016		Time 11:05 AM	
36. Type of Report: Amended		37. Name of Preparer and Date Prepared: Timothy R. Stockman				Date 12/05/2016			
38. Reason For Amendment: Addition of Contractor Information									