

## Fatality Alert

MINE FATALITY – On November 1, 2021, an electrician with 25 years of mining experience was fatally injured while traveling down a mine slope. He lost control of a four-passenger rubber-tired personnel carrier, and the vehicle crashed at the bottom of the slope, pinning the victim underneath.



### Best Practices

- **Immediately remove equipment** from service when defects affecting safety are found.
- **Conduct adequate preoperational checks and weekly examinations of mobile electrical equipment.** Correct any defects affecting safety prior to operating mobile equipment.
- **Maintain control** and stay alert when operating mobile equipment.
- **Maintain roadways free of excessive water, mud, and other conditions** that impact an equipment operator's ability to control mobile equipment.
- **Operate mobile equipment at speeds consistent with the conditions** of roadways, grades, clearance, and visibility.
- **Never rely on Regenerative Braking** as a substitute for keeping brakes properly maintained.

This is the 31st fatality reported in 2021, and the 14th classified as “Powered Haulage.”

---

The information provided in this notice is based on preliminary data only and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.

**Report accidents and hazardous conditions: 1-800-746-1553**

[msha.gov](https://www.msha.gov) | [askmsha@dol.gov](mailto:askmsha@dol.gov) | [@MSHA\\_DOL](https://twitter.com/MSHA_DOL)