



## **Fatality Alert**

MINE FATALITY – On October 7, 2022, a mechanic was fatally injured when he was engulfed in material after he entered an air separator to clear a blockage.



## **Best Practices**

- Install mechanical flow-enhancing devices, such as mechanical vibratory devices, that can maintain material flow and prevent the need for miners to enter a confined space.
- Mine operators should establish procedures to clear blockages and train all miners in the procedures.
- Make sure miners wear a safety belt or harness equipped with a lifeline when entering a confined space, and that a second miner, similarly equipped, is attending the lifeline.

This is the 24th fatality reported in 2022, and the first classified as "Confined Space."

The information provided in this notice is based on preliminary information only and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.

Report accidents and hazardous conditions: 1-800-746-1553