

## Fatality Alert

MINE FATALITY – On April 20, 2023, a contract laborer died while removing the side plate off a shaker screen. The unsupported side plate fell over and struck him.



### Best Practices

- Block machinery components against motion before beginning maintenance or repairs.
- Ensure blocking material is installed correctly and is of adequate size and strength to support and stabilize the load.
- Ensure miners position themselves in a safe location and away from potential pinch point areas.
- Train miners in safe work procedures and hazard recognition. Monitor personnel routinely to ensure they follow safe work procedures.

This is the 17th fatality reported in 2023, and the sixth classified as “Machinery.”

---

The information provided in this notice is based on preliminary information only and does not represent final determinations regarding the nature of the accident or conclusions regarding the cause of the fatality.

**Report accidents and hazardous conditions: 1-800-746-1553**

[msha.gov](https://www.msha.gov) | [askmsha@dol.gov](mailto:askmsha@dol.gov) | [@MSHA\\_DOL](https://twitter.com/MSHA_DOL)