Preliminary Report of Accident

U.S. Department of Labor Mine Safety and Health Administration

PR001 02/28/2023

1. Accident Type	2. Accident Classification		Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
F - Fatal Injury	17 - Machinery		02/26/2023 3:50 PM	02/26/2023 3:50 PM	FAI-7033338-1
Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	Appalachian Resource W Grapevine South Surface Appalachian Resource Co	Mine	TC		
7. Mine Location Information a) City Thacker	b) County Mingo		c) State WV	8. Mine ID Number 46-08930	9. Union No
10. Primary Mineral Mined 11. Number of Employees					
Bituminous			a) Total b) Underg	round c) Open Pit/Quarry 48	d) Mill/Prep Plant e) Other 0
12. Contractor Name LMS Excavating				13. Contractor Union No	14. Contractor ID Number A7147
15. Contractor Address a) City Freeburn	b) County		c) State KY	d) Zip Code 41528	
16. Number of Contractor Employ a) Total 2	ees b) Underground 0		c) Open Pit/Quarry	d) Mill/Prep Plant 0	e) Other 0
17. Number of Persons in Mine at Time of Accident a) Mine Employees b) Contractor Employees 0 2 18. Number of Persons Unaccounted for a) Mine Employees b) Contractor Employees 0 0					
19. Accident Location 00 - Other Idle Access Road	1				20. Mining Height 0 Feet 0 Inches
21. Nonfatal Injuries	22. Fatal Injuries				
23. Victims Information					
Billy Mapes					
a) First Name a) MI a) Last Name b) Age c) Regular Job Title d) Activity at Time of Accident Employee Billy Mapes 73 Equipment Operator Tramming Bulldozer Contractor Employee					
24. Mining Experience a) Total Experience b) Experience at the Mine 53 Years 0 Weeks 0 Days 0 Years 0 Weeks 1 Days 53 Years 0 Weeks 0 Days 0 Years 0 Weeks 1 Days 53 Years 0 Weeks 0 Days 0 Years 0 Weeks 1 Days 53 Years 0 Weeks 0 Days 10 Years 0 Weeks Days					
25. Autopsy Performed No	If Yes, Location				
26. Mine Telephone No. (681) 308-0015					
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A contractor employee died when the bulldozer he was operating left the haul road and rolled down a hill. The contractor employee was not wearing a seat belt and was ejected from the bulldozer.					
The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.					
28. Equipment Manufacturer John Deere		29	. Model 850K		
30. District C1200 - Pineville District		32	. Field Office C1203 - Logan WV Field Office		33. Event Number 7033338
34. Accident Investigator First Name Paul	MI Last I J Milum	Name			
35. MSHA Person Notified First Name Tracy	MI Last I	Name way	Date/Time Not 02/26/2023 4:4:		
36. Type of Report Initial	37. Name of Preparer Full Name Paul J Milum		Date Prepared 02/26/2023		
38. Reason for Amendment	1				