



## Fatality Alert

**MINE FATALITY** – On January 6, 2026, a contractor was fatally struck by the motor and gearbox assembly while removing a baghouse slide gate.



### Best Practices

- Block machinery or equipment against hazardous motion before beginning maintenance or repairs. Verify miners are in a safe location and away from potential “red zone” areas.
- Secure assemblies to prevent unexpected movement and use proper tools.
- Identify and control all stored energy sources, including gravity.
- Train miners in safe work procedures and hazard recognition.

This is the first fatality reported in 2026, and the first classified as “Machinery.”

---

The information provided in this notice is based on preliminary information only and does not represent final determinations regarding the nature of the accident or conclusions regarding the cause of the fatality.

**Report accidents and hazardous conditions: 1-800-746-1553**

[msha.gov](http://msha.gov) | [askmsha@dol.gov](mailto:askmsha@dol.gov) | [@MSHA\\_DOL](https://twitter.com/MSHA_DOL)