





**METAL/NONMETAL MINE FATALITY** – On November 25, 2014, a 67-year-old truck driver with 10½ years of experience was killed at a sandstone mine. The victim backed a haul truck to the edge of the overburden dumpsite and started to raise the truck's bed to dump a load of material. The bank failed, causing the truck to overturn and fall 30 feet below. The victim died en route to the hospital.



## **Best Practices**

- Task train all persons to understand safe job procedures.
- Establish and discuss safe work procedures before beginning work.
- Identify and control all hazards associated with the work to be performed.
- Conduct adequate pre-operational checks prior to operating mobile equipment.
- Always wear a seat belt when operating self-propelled mobile equipment.
- Examine dumping locations for stability prior to dumping the first load and as ground conditions warrant during the work shift. Where trucks are loaded out of the stockpile or ground conditions may fail to support the weight of the truck, dump loads a safe distance back from the edge.
- Maintain berms or similar impeding devices at dumping locations where there is a hazard of overtravel or overturning.
- Travel in a straight line when backing a truck toward a dump location. Do not approach on a turn.
- Monitor persons routinely to determine safe work procedures are followed.

This is the 22<sup>nd</sup> fatality reported in calendar year 2014 in metal and nonmetal mining. As of this date in 2013, there were 18 fatalities reported in metal and nonmetal mining. This is the 6<sup>th</sup> Powered Haulage fatality in 2014. There were 7 Powered Haulage fatalities in the same period in 2013.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.