Preliminary Report of Accident

U.S. Department of Labor Mine Safety and Health Administration

PR001 01/07/2020

1. Accident Type	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fat	tal Case No	
F - Fatal Injury	17 - Machinery	11/16/2019 12:37 PM	11/16/2019 12:37 PN	1 22		
6. Mine Information						
a) Mining Company Name:	US Silica Company					
b) Mine Name:	EP Engineered Clays Corpora	tion				
c) Parent of Mining Company	USS Holdings Inc					
7. Mine Location Information			8. Mine ID Number	9. Un	ion	
a) City	b) County	c) State	22-00415	Ye	s	
Jackson	Hinds	MS				
10. Primary Mineral Mined		11. Number of Employees	•	•		
Clay, Ceramic & Refractory Mi	nerals Mining, N.E.C.		nderground c) Open Pit/	Quarry d) Mi	II/Prep Plant e) (Other
		78		78		
12. Contractor Name			13. Contractor Union	14. C	ontractor ID Number	
Caney Creek Limestone LLC			No	С	0242	
15. Contractor Address						
a) City	b) County	c) State	9	d) Zip Code		
Jackson		MS		39212		
16. Number of Contractor Emplo	pyees					
a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep	Plant	e) Other	
5					5	
17. Number of Persons in Mine a	at Time of Accident	18. Number of Persons Unac	counted for			
a) Mine Employees	b) Contractor Employees	a) Mine Employees	b) Contractor Employee	s		
10	4	0	0			
19. Accident Location				20. M	lining Height	
30 - Mill/Prep Plant					eet Inches	
21. Nonfatal Injuries	22. Fatal Injuries			I		
21. Nomatai injunes	1					
23. Victims Information	·					
23. Victims information						
Johnnie E Twiner						

Johnnie E Twind	er						
a) First Name Johnnie	a) MI E	a) Last Name Twiner	b) Age 77	c) Regular Owner	r Job Title	d) Activity at Time of Accident Spotting a dump truck	Employee Contractor Employee
24. Mining Expe a) Total Expe 50 Years 0	rience	, .	rience at the		, .	nce at the Activity at the Time of the Accident s 0 Weeks 0 Days	d) Experience with Contractor 25 Years 0 Weeks 0 Days
25. Autopsy Per No	formed	If Yes, L	ocation				

26. Mine Telephone No.

(601) 985-4862

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)

Contractors were making repairs to the impoundment dam. Contractor (owner) came back to site with lunch. The dozer had seen the owner's truck pull up and assumed the owner had stayed in the cab as he was backing up the hill to retrieve his lunch. The owner(victim) had gotten out of the truck withe the lunches and stopped to spot the dump truck. The victim stepped to the side to allow the truck to dump and stepped directly into the path of the dozer. The dozer operator realized he had run over the victim when he saw the pant leg and boot in the dozer tracks.

The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer Case			29. Model 1650	
30. District			32. Field Office	33. Event Number
M5000 - South Central District - Dallas		M5871 - Little Rock AR Field Office	6809081	
34. Accident Investigator				·
First Name	MI	Last Name		
Gregory	Р	Sensibaugh		
35. MSHA Person Notified				
First Name	MI	Last Name	Date/Time Notified	
Robert		Dreyer	11/16/2019 4:36 PM	
36. Type of Report	37. Name of Pre	parer		
Initial	Full Name	-	Date Prepared	
	Elwood Burris	SS	11/18/2019	