Preliminary Report of Accident



PR001 06/17/2020

	Accident Type F - Fatal Injury	2. Accident Classifi 17 - Machinery		3. Date/Time of Accident 06/13/2020 10:00 AM	4. Date/Time of Death 06/13/2020 10:00 AM	5. Fatal Case No 6784356-1
a k	Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	Salt River Sand & Fast Pak Crusher Salt River Pima-Ma		ommunity		
	Mine Location Information a) City Scottsdale	b) County Maricopa		c) State AZ	8. Mine ID Number 02-02320	9. Union No
10.	Primary Mineral Mined Construction Sand & Gravel Mini	ng, N.E.C.		11. Number of Employees a) Total b) Un 1	derground c) Open Pit/Quarry 1	d) Mill/Prep Plant e) Other 0 0
12.	Contractor Name Carl's Dragline Service				13. Contractor Union	14. Contractor ID Number K439
	Contractor Address a) City Suprise	b) Coun	ity	c) State AZ	d) Zip Cod 85387	9
	Number of Contractor Employe a) Total 1	ees b) Underground		c) Open Pit/Quarry 1	d) Mill/Prep Plant 0	e) Other 0
	Number of Persons in Mine at 7 a) Mine Employees b 0	Time of Accident) Contractor Employ 1	ees	18. Number of Persons Unacc a) Mine Employees 0	ounted for b) Contractor Employees 0	
19.	Accident Location 03 - Open Pit					20. Mining Height Feet Inches
21.	Nonfatal Injuries 0	22. Fatal Injuries				
23.	Victims Information	·				
	Blayke Davis					
		.ast Name b) Age	e c) Regular	Job Title d) Activity at Tin	a of Accident	Employee
	Blayke	Davis 25	Operato			Contractor Employee
	24. Mining Experience a) Total Experience 2 Years 48 Weeks 0 Days	b) Experience at 2 Years 48 We		c) Experience at the Activity a 2 Years 48 Weeks 0 Days		Experience with Contractor Years 48 Weeks 0 Days
	25. Autopsy Performed	If Yes, Location				
26.	Mine Telephone No. (602) 525-5988					
	(602) 525-5988 Description of Accident (includ				nd recovery operations) d in 25 feet of water. After two days, the	e dragline was extricated from the pond
	(602) 525-5988 Description of Accident (includ The victim was operating a dragli and the victim was located.	ine to remove material	from a pond. T	he dragline was found submerge		
27.	(602) 525-5988 Description of Accident (includ The victim was operating a dragli and the victim was located. <i>The information provided in this r</i>	ine to remove material	from a pond. T	he dragline was found submerge	d in 25 feet of water. After two days, the	
27. 28.	(602) 525-5988 Description of Accident (includ The victim was operating a dragli and the victim was located. The information provided in this r cause of the accident. Equipment Manufacturer	ine to remove material	from a pond. T	he dragline was found submerger ILY and does not represent final of 29. Model	d in 25 feet of water. After two days, the	
27. 28. 30. 34.	(602) 525-5988 Description of Accident (includ The victim was operating a dragli and the victim was located. The information provided in this r cause of the accident. Equipment Manufacturer American Hoist and Derrick Co. District	ine to remove material	from a pond. T	he dragline was found submerger ILY and does not represent final of 29. Model 599C Dragline 32. Field Office	d in 25 feet of water. After two days, the	incident or conclusions regarding the 33. Event Number
 27. 28. 30. 34. 35. 	(602) 525-5988 Description of Accident (includ The victim was operating a dragli and the victim was located. The information provided in this r cause of the accident. Equipment Manufacturer American Hoist and Derrick Co. District M6000 - Denver District Accident Investigator First Name	ine to remove material notice is based on prel	from a pond. T iminary data ON Last Name	he dragline was found submerger ILY and does not represent final of 29. Model 599C Dragline 32. Field Office	d in 25 feet of water. After two days, the ietermination regarding the nature of the d Office Notified	incident or conclusions regarding the 33. Event Number
27. 28. 30. 34. 35.	(602) 525-5988 Description of Accident (includ The victim was operating a dragli and the victim was located. The information provided in this r cause of the accident. Equipment Manufacturer American Hoist and Derrick Co. District M6000 - Denver District Accident Investigator First Name Lee MSHA Person Notified First Name	ine to remove material notice is based on pref MI A.	from a pond. T iminary data ON Last Name Hughes Last Name Hughes	he dragline was found submerger ILY and does not represent final of 29. Model 599C Dragline 32. Field Office M6861 - Mesa North AZ Fie Date/Time	d in 25 feet of water. After two days, the ietermination regarding the nature of the d Office Notified	incident or conclusions regarding the 33. Event Number