PR001
30-Jun-11

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

1. Accident Type:	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
Fatal Injury	Fall of Face, Rib, Pillar or Highwall	06/29/2011 11:15 AM	06/29/2011 12:53 PM	9

6. Mine Information :

a) Mining Company Name	b) Mine Name	c) Parent of Mining Company
Manalapan Mining Co., Inc.	P-1	Ben Bennett

7. Mine Location : a) City	b) County	c) State	8. Mine ID Number:	9. Union:
Pathfork	Harlan	KY	15-19102	NO

10. Primary Mineral Mined:	11. Number of Mine Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
BITUMINOUS COAL UNDERGROUND	48	45			3

12. Contractor Name:	13. Union	14. Contractor ID Number:

15. Contractor Address: a) City	b) County	c) State	d) Zip Code

16. Number of Contractor Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other

17. Number of Persons in Mine at Time of Accident: a) Mine Employees:	b) Contractor Employees:	18. Number of Persons Unaccounted For: a) Mine Employees:	b) Contractor Employees:
34		0	

19) Location of Accident
- [X] 01-Underground
- [ ] 02-Surface at Underground
- [ ] 03-Open Pit
- [ ] 06-Dredge Mining
- [X] 07-Advance Mining
- [ ] 08-Retreat Mining
- [ ] 30-Mill/Prep Plant
- [ ] 99-Office Facility
- [ ] Other (specify)

20. Mining Height: Feet 6 Inches 0

21. Nonfatal Injuries:	22. Fatal Injuries:
0	1

23. Victim Information : a) Name	b) Age
David A. Partin	49

c) Regular Job Title:	d) Activity at Time of Accident:	[X] Mine Employee
Dollyman	Dollyman	

24. Experience :	Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days
a) Total:	16	b) at the mine:	44	c) at activity (23d)	1	d) with Contractor	

25. Autopsy Performed: If Yes, Location	26. Mine Telephone No.:
	(606) 573-3188

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

At approximately 11:15 A.M. the continuous haulage cable attendant (dollyman) was standing beside the bridge dolly when he was struck by a section of the rib that measured approximately 82 by 36 by 11 inches. The rock knocked him into the dolly striking his head and chest on the dolly. The continuous haulage was backing up so the continuous miner could set over while mining the number 4 Heading. The action of the continuous haulage backing up, pushing the dolly outby down the belt dragged the victim from under the rock. The operator of the outby continuous haulage unit (bridge carrier) noticed that he couldn't see the dollyman. He shut off the continuous haulage units and the belt and traveled outby down the belt to where he had last seen the victim. He found the victim on the narrow side of the belt near the rigid belt structure. The Mine Emergency Technician was called to the scene and treatment began. The victim was semi-conscious, with his eyes open and was moving his arms and legs. The victim's neck was stabilized and he was placed on a back board and transported to the surface aboard the section mantrip. His vital signs weakened on the way to the surface and he was found to be not breathing shortly after arrival on the surface. CPR was started but was not successful. The Harlan County Deputy Coroner pronounced the victim at 12:53 P.M..

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:	29. Model:

30. District:	32. Field Office:	33. Event Number:
C0700 Barbourville	Barbourville KY	4451857

34. Accident Investigator:	35. MSHA Person Notified:	Date	Time
Jack Harris	Eddie Sparks	06/29/2011	12:08 P

36. Type of Report:	37. Name of Preparer and Date Prepared	Date
Initial	Kevin Doan	06/29/2011

38. Reason For Amendment: