PR001
28-Mar-11

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

1. Accident Type:	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
Fatal Injury	Machinery	03/25/2011 08:10 AM	03/25/2011 09:01 AM	4

6. Mine Information :

a) Mining Company Name	b) Mine Name	c) Parent of Mining Company
Matrix Energy LLC	No. 1	James H Booth

7. Mine Location : a) City	b) County	c) State	8. Mine ID Number:	9. Union:
Lovely	Martin	KY	15-18575	NO

10. Primary Mineral Mined:	11. Number of Mine Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
BITUMINOUS	200	190			10

12. Contractor Name:	13. Union	14. Contractor ID Number:

15. Contractor Address: a) City	b) County	c) State	d) Zip Code

16. Number of Contractor Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other

17. Number of Persons in Mine at Time of Accident:		18. Number of Persons Unaccounted For:	
a) Mine Employees: 80	b) Contractor Employees:	a) Mine Employees: 0	b) Contractor Employees:

19) Location of Accident

- [X] 01-Underground
- [ ] 03-Open Pit
- [ ] 07-Advance Mining
- [ ] 30-Mill/Prep Plant
- [ ] Other (specify)
- [ ] 02-Surface at Underground
- [ ] 06-Dredge Mining
- [ ] 08-Retreat Mining
- [ ] 99-Office Facility

20. Mining Height: Feet 6 Inches 0

21. Nonfatal Injuries:	22. Fatal Injuries:
	1

23. Victim Information : a) Name: Robert L. Cook b) Age: 54

c) Regular Job Title: Scoop Operator d) Activity at Time of Accident: Continuous Miner Operator [X] Mine Employee

24. Experience :

	Years	Weeks	Days
a) Total:	35	0	0
b) at the mine:	7	0	0
c) at activity (23d)	30	0	0
d) with Contractor			

25. Autopsy Performed:	If Yes, Location	26. Mine Telephone No.:
NO		(606) 298-2597

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

At approximately 0810, a fatal accident occurred at this mine. The continuous miner operator was setting up the miner in the No. 2 left crosscut and was pinned between the coal rib and the boom of the machine.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:	29. Model:
Joy Machinery Co. (Joy Manufacturing Co)	14/15

30. District:	32. Field Office:	33. Event Number:
C0600 Pikeville	Martin KY	4192439

34. Accident Investigator:	35. MSHA Person Notified:	Date	Time
Dwight Bostic	Billy Meddings	03/25/2011	08:50 A

36. Type of Report:	37. Name of Preparer and Date Prepared:	Date
Initial	Joseph Armstrong	03/25/2011

38. Reason For Amendment: