PR001
07-Dec-11

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

1. Accident Type:	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
Fatal Injury	Other Accident	10/28/2011 05:45 PM	10/28/2011 06:51 PM	11

6. Mine Information :

a) Mining Company Name	b) Mine Name	c) Parent of Mining Company
Newmont USA Limited	SOUTH AREA	Newmont Mining Corp

7. Mine Location : a) City	b) County	c) State	8. Mine ID Number:	9. Union:
Carlin	Eureka	NV	26-00500	YES

10. Primary Mineral Mined:	11. Number of Mine Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
GOLD ORE MINING, N.E.C.	1119	0	480	349	290

12. Contractor Name:	13. Union	14. Contractor ID Number:
Purcell Tire Co	NO	LMD

15. Contractor Address: a) City	b) County	c) State	d) Zip Code
Elko	Elko	NV	89801

16. Number of Contractor Employees: a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
3	0	0	0	3

17. Number of Persons in Mine at Time of Accident:
a) Mine Employees: 250 b) Contractor Employees: 1

18. Number of Persons Unaccounted For:
a) Mine Employees: 0 b) Contractor Employees: 0

19) Location of Accident
- [ ] 01-Underground
- [ ] 02-Surface at Underground
- [x] 03-Open Pit
- [ ] 06-Dredge Mining
- [ ] 07-Advance Mining
- [ ] 08-Retreat Mining
- [ ] 30-Mill/Prep Plant
- [ ] 99-Office Facility
- [ ] Other (specify)

20. Mining Height: Feet Inches

21. Nonfatal Injuries: 0

22. Fatal Injuries: 1

23. Victim Information : a) Name: Joe M. Ashdown b) Age: 21

c) Regular Job Title: Tireman Repair Tech

d) Activity at Time of Accident: Patching Haul Truck Tire

[x] Contractor Employee

24. Experience :

	Years	Weeks	Days
a) Total:	0	37	3
b) at the mine:	0	37	3
c) at activity (23d)	0	37	3
d) with Contractor	0	37	3

25. Autopsy Performed: YES If Yes, Location: Washoe County Medical Examiner's Office

26. Mine Telephone No.: (775) 778-4000

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was working in a shop repairing a haul truck tire. He was inside the tire, applying glue, when he was overcome by the fumes from the glue.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:	29. Model:
Bridgestone	VRDP

30. District:	32. Field Office:	33. Event Number:
M7000 Western	Elko NV	1148600

34. Accident Investigator:	35. MSHA Person Notified:	Date	Time
Joel Dozier	Randy Cardwell	10/28/2011	06:13 P

36. Type of Report:	37. Name of Preparer and Date Prepared:	Date
Amended	Mike Hancher MH	11/01/2011

38. Reason For Amendment:
Item #3 -Time of Accident