Longwall Construction

PRESHIFT - ONSHIFT
and
DAILY REPORT

Started 12-9-09
Full 1

Company PERFORMANCE COAL

Mine UBB

SECTION LONG WALL CONSTRUCTION

LOCATION NAOMA RALEIGH WV
Post Office County State

Finished 12-30-09

Form 6-1489
(March 1970)

Budget Bureau No. 42-R1589

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# MS-014

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-9 2009 Section or Area Examined LW Canal

Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power Centers	0%	None Observed	Reported
2.	D-Boxes		" "	"
3.	Chargers		" "	"
4.	Work Area		" "	"
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: Track Travelways OK
0% CH4 20.8% O2 0 CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey (Preshift-Mine Examiner) 27085 (Certificate No.) _____ (Assistant Foreman) _____ (Certificate No.)

Countersigned Rick Foster (Mine Manager—Mine Foreman) 28736

_____ (Assistant Foreman) _____ _____ (Superintendent or Assistant) _____

John A. Bickford 26176

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-9 2009 Section or Area Examined Longwall Construction

Time of Examination: from 12:00 a.m. or p.m. to 3:04 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Bickford Time A.M 2:50 P.M.

Report received by Scott Halstead 37567 (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH_4	Violation or Hazardous Condition	Action Taken
1.	Power Centers	0%	None observed	None
2.	D-Boxes	0%	None observed	None
3.	Chargers	0%	None observed	None
4.	Work Area	0%	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH_4 0% Co 20.8% O_2
Track & Travelways OK at Toe

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John Bickford (Preshift-Mine Examiner) Certificate No. 28176 Assistant Foreman Certificate No.

Countersigned [signature] (Mine Manager—Mine Foreman) 52041

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-9 20__ Section or Area Examined Longwall, Contstruct

Time of Examination: from 830 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes____ no____

By whom Drought out Time ____A.M ____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	Power Centers OZ Ch4	None Observed	none
2.	D-Box OZ	none Observed	none
3.	Chargers OZ	none Observed	none
4.	Work Area OZ	none observed	none
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airmount			

Remarks: OZCh4 OZCO 20.8302

Track, Travelways, OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 1539A Certificate No. _____ Assistant Foreman _____ Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 26041

_____ Assistant Foreman _____ _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-10-09 20___ Section or Area Examined L/Wall Constr.

Time of Examination: from 3:00 a.m. or p.m. to 9:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom Brought out Time 5:25 A.M. _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Work Area	ok	None observed	None
2.	Power Center	ok	None observed	None
3.	Chargers	ok	None observed	None
4.	D-Boxes	ok	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks: ok CH4, open cu, 20.8% oz detected at time of exam

Track & Travelway's ok at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 15 [illegible] — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — 26 [illegible]

Assistant Foreman

Superintendent or Assistant

John A. Bickford 26176

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12.10.09 20__ Section or Area Examined L/W Const.

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes ✓ no____

By whom J Bickford Time ____ A.M 2:50 P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	WORK ARE	0%	None Observed	None
2.	Power Center	0%	None Observed	None
3.	Chargers	0%	None Observed	None
4.	D-Boxs	0%	None Observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0ppm CO. Detected at EXAM
Powercenters, D-Boxs track & travelways Clear at EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford 26176
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.

Countersigned [signature] 26041
Mine Manager—Mine Foreman

Assistant Foreman [signature] 15397

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-10-09 20____ Section or Area Examined L/w construction

Time of Examination: from 830 a.m. or p.m. to 100 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom Brought out Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	work Area Ch4 O2	none observed	none
2.	Power centers O2	none observed	none
3.	Chargers O2	none observed	none
4.	O Boxes O2	none observed	none
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airmount			

Remarks: O2 Ch4 O2 CO 20.8 O2

Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] 1539A
Preshift-Mine Examiner — Certificate No.

Countersigned [signature] 26041
Mine Manager—Mine Foreman

Assistant Foreman — Certificate No.

Assistant Foreman — Certificate No.

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-11-09 20___ Section or Area Examined L/WALL Constr.

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no_____

By whom Brought out Time 5:20 A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CHY	Violation or Hazardous Condition	Action Taken
1.	Power Center	OK	None observed	None
2.	D- Boxes	OK	None observed	None
3.	Chargers	OK	None observed	None
4.	Work Area	OK	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: OK CHY, Oppm CO, 20.8% O2 detected at time of exam

Track & Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 15397A Certificate No. _____ Assistant Foreman _____ Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 26041

_____ Assistant Foreman _____ _____ Superintendent or Assistant _____

John A. Bickford 26176

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-11 2009 Section or Area Examined Longwall Construction

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes ____ no ✓

By whom ____ Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power Centers	0%	None Observed	None
2.	D. Boxes	0%	None observed	None
3.	Chargers	0%	None observed	None
4.	Work Area	0%	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4 0% Co 20.8%
Track & Travelways OK at Toe

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead — Preshift-Mine Examiner — Certificate No. 37567

Countersigned [signature] — Mine Manager—Mine Foreman — Certificate No. 26021

Assistant Foreman — Certificate No.

Nick Bailey — Assistant Foreman — Certificate No. 27085

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-11-09 20__ Section or Area Examined Long wall const.

Time of Examination: from 830 a.m. or p.m. to 1130 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no____

By whom Baily Time ____A.M ____P.M.

Report received by Dan Ullmann 15394 (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	Power center CH4 O2	None observed	none
2.	D-Box O2	none observed	none
3.	Charger O2	none observed	none
4.	Work Area O2	none observed	none
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airmovement			

Remarks: O2 CH4, CO, 20.8 O2

Track, Travelways clear.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey (Preshift-Mine Examiner) Certificate No. 27085 ____ Assistant Foreman ____ Certificate No. ____

Countersigned [illegible] (Mine Manager—Mine Foreman) 26041 ____

____ (Assistant Foreman) ____ ____

____ (Superintendent or Assistant) ____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-12 20 09 Section or Area Examined LW Canal.

Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ✓

By whom ____ Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	Power Centers	None Observed	Reported
2.	D Boxes	" "	"
3.	Charger	" "	"
4.	Work Area	None Observed	Reported
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Crosscut Air Measurement			

Remarks: 0% CH_4 20.8% O_2 0 CO
Track Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey (Preshift-Mine Examiner) Certificate No. 27085 ____ (Assistant Foreman) Certificate No. ____

Countersigned [illegible] (Mine Manager—Mine Foreman) 22241 ____

____ (Assistant Foreman) ____ ____ (Superintendent or Assistant) ____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-12-09 20___ Section or Area Examined LW Construction

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____ A.M _____ P.M.

Report received by Brought out (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power Center	0%	None Observed	None
2.	D-Boxs	0%	None Observed	None
3.	Charger	0%	None Observed	None
4.	Work Area	0%	None Observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH^4, 20.8% O^2, 0ppm CO Detected at Exam
Track & Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead (Preshift-Mine Examiner) 37567 (Certificate No.) _____ (Assistant Foreman) _____ (Certificate No.)

Countersigned [signature] (Mine Manager—Mine Foreman) 96041

_____ (Assistant Foreman)

Mike Bailey 27085 _____ (Superintendent or Assistant)

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-12-09 20__ Section or Area Examined Wall construction

Time of Examination: from 830 a.m. or p.m. to 1130 a.m. or p.m.

Was this report phoned to outside: Yes ___ no ___

By whom Daily Time ___ A.M. 10 P.M.

Report received by [signature] 1539A (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	Power Centers OE CH4	none Observed	none
2.	O-Box OE	None Observed	none
3.	Charger OE	none Observed	none
4.	Work Area OE	None observed	none
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airmovement			

Remarks: OE CH4 OZCO 20.8202

Travelways OK Track

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 27085 Certificate No. ___ Assistant Foreman ___ Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 26041

___ Assistant Foreman

___ Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-13 20-09 Section or Area Examined L W Canot

Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ✓

By whom ____ Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	Power Center	None Observed	Reported
2.	D Bases	" "	"
3.	Charger	" "	"
4.	Work Area	None Observed	Reported
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Movement			

Remarks: Track Tramways OK
0% CH4 20.8% O2 0 CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Nick Bailey (Preshift-Mine Examiner) 27085 (Certificate No.) ____ (Assistant Foreman) ____ (Certificate No.)

Countersigned [illegible] (Mine Manager—Mine Foreman) [illegible]

____ (Assistant Foreman) ____

____ (Superintendent or Assistant) ____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-13-09 20__ Section or Area Examined LW Construction

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____A.M _____P.M.

Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power Center	0%	NONE OBSERVED	NONE
2.	D-Box's	0%	NONE OBSERVED	NONE
3.	Charger	0%	NONE OBSERVED	NONE
4.	WORK AREA	0%	NONE OBSERVED	NONE
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH^4, 20.8% O^2, 0ppm CO Detected at EXAM
TRACK & TRAVELWAYS - OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead — Preshift-Mine Examiner — Certificate No. 37567 — Assistant Foreman — Certificate No.

Countersigned [signature] — Mine Manager—Mine Foreman — 21041

Mike Bailey — Assistant Foreman — 27085 — Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-13-09 20 09 Section or Area Examined L.W. construction

Time of Examination: from 8:30 a.m. or (p.m.) to 11:30 a.m. or (p.m.)

Was this report phoned to outside: Yes_____ no_____

By whom Mike Bailey Time _____A.M 11:00 P.M.

Report received by [illegible] 1247-A
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power center	0%	None observed	None
2.	D-Boxes	0%	None observed	None
3.	Chargers	0%	None observed	None
4.	work area	0%	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good AIR Movement			

Remarks: 0% CH4, 20.8% O2, 0PPM C.O. Detected At Time OF Exam
Track, Travelways, OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey 27085
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.

Countersigned [illegible] 26041
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-14 20 02 Section or Area Examined NW Canal.

Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ✓

By whom ____ Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4 0%	Violation or Hazardous Condition	Action Taken
1.	Power Center		None Observed	Reported
2.	D-Boxes		" "	"
3.	Charger		" "	"
4.	Work Area		None Observed	Reported
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4 20.8% O2 0 CO

Track Travelway OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 27085 — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — 260401

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-14 2009 Section or Area Examined 4/wall cost

Time of Examination: from 1200 a.m. or (p.m.) to 300 a.m. or (p.m.)

Was this report phoned to outside: Yes ✓ no

By whom R Gunnoe Time A.M 240 P.M.

Report received by George Curry 27429 (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	Power Center 0% CH4	none observed	none
2.	D-Boxes 0% CH4	none observed	none
3.	Chargers 0% CH4	none observed	none
4.	Work Area 0% CH4	none observed	none
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Track, travelways clean at ellen

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnoe (Preshift-Mine Examiner) 1536-A (Certificate No.) Assistant Foreman Certificate No.

Countersigned [signature] (Mine Manager—Mine Foreman) 26041

Assistant Foreman

Mike Bailey 27085 Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-14 20 9 Section or Area Examined L wall con't

Time of Examination: from 8:30 a.m. or ~~p.m.~~ to 11:00 a.m. or ~~p.m.~~

Was this report phoned to outside: Yes ✓ no

By whom M. Bailey Time A.M P.M.

Report received by T. Peterson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	Power Center 0% CH4	none observed	
2.	D. Boxs 0%	none observed	
3.	Charger 0%	none observed	
4.	Work Area 0%	none observed	
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good air movement			

Remarks: No CH4 dect - 0% 20.8 oz CO 0%
Track + Traveleways clear at exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____ Preshift-Mine Examiner Certificate No. _____ Assistant Foreman Certificate No.

Countersigned E Hazen Mine Manager—Mine Foreman 26041

Assistant Foreman

Superintendent or Assistant

Ray Peterson 29611

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-15-09 20___ Section or Area Examined LW Construction

Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	Power Centers Ch4-0%	None Observed	None
2.	D-Box's	None Observed	None
3.	Chargers	None Observed	None
4.	Work Area	None Observed	None
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks: 0% CH^4, 20.8% O^2, 0ppm CO Detected at Exam
Track & Travelways Clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead — Preshift-Mine Examiner — Certificate No. 37567 — Assistant Foreman — Certificate No.

Countersigned [signature] — Mine Manager—Mine Foreman — Certificate No. 26001 — [signature] — Certificate No. 13544

Mike Bailey — Assistant Foreman — 27085 — Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-15-09 2009 Section or Area Examined LW Construction

Time of Examination: from 4:30 a.m. or p.m. to 11:30 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Billy Campbell Time A.M 11:10 P.M.

Report received by Greg Cole 1947-A
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	O2	Action Taken
1.	Power centers	0%	None observes	20.8%	None
2.	D-Boxes	0%	None observed	20.8%	None
3.	Work Area	0%	None observed	20.8%	None
4.	Chargers	0%	None observes	20.8%	None
5.					
6.					
7.					
8.					
9.					
10.					

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks: 0% CH4, 20.8% O2, 0PPM C.O. Detected At Time OF exam
Track, Travelways, OK At Time OF exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] 1354-A
Preshift-Mine Examiner — Certificate No. — Assistant Foreman — Certificate No.

Countersigned [signature]
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Greg Cole 1947-A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-16 20 09 Section or Area Examined LW Canal

Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ✓

By whom ____ Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power Center	0%	None Observed	Reported
2.	D Bypass		" "	"
3.	Chargers		" "	"
4.	Work Area		None Observed	Reported
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: Track Travelways OK

0% CH4 20.8% O2 0 CO

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 13549A — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — 26041

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12:16:09 20___ Section or Area Examined LW Construction

Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH^4	*Violation or Hazardous Condition*	*Action Taken*
1.	Power Center	0%	None OBSERVED	None
2.	D-Box's	0%	None OBSERVED	None
3.	Chargers	0%	None OBSERVED	None
4.	Work Area	0%	None OBSERVED	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Movement			

Remarks: Track & Travelways - Clear
0% CH^4, 20.8% O^2, 0ppm CO Detected at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead — Preshift-Mine Examiner — Certificate No. 37567

Countersigned [signature] — Mine Manager—Mine Foreman — Certificate No. 26011

[signature] — Assistant Foreman — Certificate No. 135410

_____ — Assistant Foreman

_____ — Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-16 20 9 Section or Area Examined LW Const.

Time of Examination: from 8:30 a.m. or ~~p.m.~~ to 11:00 a.m. or ~~p.m.~~

Was this report phoned to outside: Yes ✓ no

By whom B. Conduer Time A.M 11:00 ~~P.M.~~

Report received by T. Peterson 29611 (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location		Violation or Hazardous Condition	Action Taken
1.	Power Center	0% CH4	none observed	Rep.
2.	D. Box's	0%	none observed	Rep.
3.	Charger	0%	none observed	Rep.
4.	Work Area	0%	none observed	Rep.
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good air movement			

Remarks: No CH4 dect. 0% 20.8 oz CO 0%
Travelways & Track clear at exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By W. C. Campbell 1354-A
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.

Countersigned [signature] 26041
Mine Manager—Mine Foreman

Assistant Foreman

Ray Peterson 29611

Superintendent or Assistant

W. C. Campbell 1354-A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-17 2009 Section or Area Examined 2W Construction

Time of Examination: from 300 a.m. or p.m. to 330 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ✓

By whom ____ Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	*Violation or Hazardous Condition*	*Action Taken*
1.	Power Center	0%	none observed	
2.	D Box's	0%	none observed	
3.	Charger	0%	none observed	
4.	Work Area	0%	none observed	
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Movement			

Remarks: 20.8% O^2, CH4 0%, CO 0% Detected at Exam
Travelways + Track clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 13544 — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — 260CM

Assistant Foreman — Superintendent or Assistant

John A. Bickford 26176

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-17-09 20____ Section or Area Examined L.W. Construction

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes ✓ no____

By whom J Bickford Time ____ A.M 2:54 P.M.

Report received by Scott Halsted 37567 (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH^4	Violation or Hazardous Condition	Action Taken
1.	Power Center	0%	None OBSERVED	None
2.	D-Box's	0%	None OBSERVED	None
3.	Chargers	0%	None OBSERVED	None
4.	Work Area	0%	None OBSERVED	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 20.8% O^2, 0% CH^4, 0ppm CO Detected at Exam
track & Travelways Clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford 26176
Preshift-Mine Examiner — Certificate No. — Assistant Foreman — Certificate No.

Countersigned [signature] 2601
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-17-09 20___ Section or Area Examined LW Construction

Time of Examination: from 830 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes_____ no_____

By whom Brought Out Time _____A.M _____P.M.

Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	Power center CH4 0%	None Observed	none
2.	O-Box 0%	none Observed	none
3.	Charger 0%	none Observed	none
4.	Work Area 0%	none Observed	none
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airment			

Remarks: 0% CH4 0% CO 20% O2
Track, Trave lways 0%

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 15392 — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — Certificate No. [illegible]

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-18-01 20___ Section or Area Examined L/Wall Constr.
Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.
Was this report phoned to outside: Yes_____ no ✓
By whom Drought out Time 5:30 A.M. _____ P.M.
Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power Center	OK	None observed	None
2.	D-Boxes	OK	None observed	None
3.	Chargers	OK	None observed	None
4.	Work Area	OK	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: OK CH4, open co, 20.8% oz detected at time of exam
Track & Travelways ok at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 15544 Certificate No. _____ Assistant Foreman _____ Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359 _____ Assistant Foreman _____ Superintendent or Assistant _____

John A. Bickford 26173

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-18-09 20___ Section or Area Examined L-W Construction

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes ✓ no_____

By whom J. Bickford Time _____A.M 2:40 P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*CH4*	*Violation or Hazardous Condition*	*Action Taken*
1.	Power Center	0%	None Observed	None
2.	D. Box's	0%	None Observed	None
3.	Chargers	0%	None Observed	None
4.	Work Area	0%	None Observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0ppm CO Detected at Exam
Track + Travelways Clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John Bickford (Preshift-Mine Examiner) Certificate No. 26172 _____ (Assistant Foreman) Certificate No. _____

Countersigned Terry W. Moore (Mine Manager—Mine Foreman) 33359 _____

_____ (Assistant Foreman) _____ _____

Mike Bailey 27085 _____ (Superintendent or Assistant)

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-18-09 20 09 Section or Area Examined Longwall construction

Time of Examination: from 8:30 a.m. or p.m. to 11:30 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no X

By whom Mike Bailey Time A.M 11:00 P.M.

Report received by [signature] CSM
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Powercent	0%	None observed	None
2.	D-Boxes	0%	None observed	None
3.	Chargers	0%	None observed	None
4.	work AREA	0%	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0 PPM C.O. Detected At TOE
Track, Travelways, ok At Time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey (Preshift-Mine Examiner) Certificate No. 27085 Assistant Foreman Certificate No.

Countersigned [signature] (Mine Manager—Mine Foreman) Certificate No. 33559

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-21 20 09 Section or Area Examined L W Construction

Time of Examination: from 1200 a.m. or p.m. to 300 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Russel Gunnoe Time A.M 300 P.M.

Report received by Tim Williams (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	Power centers 0% CH4	None observed	None
2.	D-Boxes 0% CH4	None observed	None
3.	Chargers 0% CH4	None observed	None
4.	Work area 0% CH4	None observed	None
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good air movement			

Remarks: 0% CH4 20.8% O2 0% CO
Track at travelways clear at F.O.K.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnoe (Preshift-Mine Examiner) 15364 (Certificate No.) [illegible] (Assistant Foreman) 1354-A (Certificate No.)

Countersigned [illegible] (Mine Manager—Mine Foreman) 33357

[illegible] (Assistant Foreman) 1659-A

(Superintendent or Assistant)

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination ~~12-22~~ 12-21-09 20 9 Section or Area Examined Hwall

Time of Examination: from 8:30 a.m. or ~~p.m.~~ to 11:00 a.m. or ~~p.m.~~

Was this report phoned to outside: Yes ✓ no

By whom M. Bailey Time A.M 11:00 ~~P.M.~~

Report received by [signature] (Signed) T. Peterson 29611

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition			Action Taken
1.	Power Center	0% CH4	20.8 oz	none observed	none
2.	P. Box	0% CH4	20.8 oz	none observed	none
3.	Charger	0% CH4	20.8 oz	none observed	none
4.	Work Area	0% CH4	20.8 oz	none observed	none
5.					
6.					
7.					
8.					
9.					
10.					

Air Measurements

Location	CFM	Location	CFM
good air movement			

Remarks: No CH4 dect. 0% 20.8 oz CO 0%
Track & Travelways clear at exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey 27085
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.

Countersigned Troy W. Moore 33359
Mine Manager—Mine Foreman

Assistant Foreman

[signature] 29611 Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-22-09 20___ Section or Area Examined L/WALL Constr.

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom Brought out Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power Center	OX	None observed	None
2.	Charger's	OX	None observed	None
3.	Work Area	OX	None observed	None
4.	D-Boxe's	OX	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: OX CH4, open co, 20.8% O2 detected at time of exam

Track & Travelway's ok

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey 27085
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.

Countersigned Terry W. Moore 33399
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-22 20 9 Section or Area Examined 4/wall Coast

Time of Examination: from 8:30 a.m. or ~~p.m.~~ to 11:00 a.m. or ~~p.m.~~

Was this report phoned to outside: Yes ✓ no

By whom M. Bailey Time A.M P.M.

Report received by T. Peterson (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location		Violation or Hazardous Condition	Action Taken
1.	Power Center	O2 CH4	none observed	none
2.	Charger	O2 CH4	none observed	none
3.	Work Area	O2 CH4	none observed	none
4.	D. Boxs	O2 CH4	none observed	none
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good air movement			

Remarks: No CH4 dect. O2 20.8% CO O2
Track & Travelways clear at exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey (Preshift-Mine Examiner) Certificate No. 27085 Assistant Foreman Certificate No.

Countersigned [illegible] (Mine Manager—Mine Foreman) 33339

Assistant Foreman

T. Peterson 29611 Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12 23 2009 Section or Area Examined LW Canal.

Time of Examination: from 3 a.m. or p.m. to 6 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power Center	0%	None Observed	Reported
2.	Charger		" "	"
3.	Work Area		" "	"
4.	D Bases	0%	None Observed	Reported
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: Track Travelways OK
0% CH4 0 CO 20.8% O2

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Mike Bailey (Preshift-Mine Examiner) 27085 (Certificate No.) _____ (Assistant Foreman) _____ (Certificate No.)

Countersigned [illegible] (Mine Manager—Mine Foreman) 33359 _____ (Assistant Foreman) _____

_____ (Superintendent or Assistant) [illegible] 1334

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-23 2009 Section or Area Examined LW Const.

Time of Examination: from 12:00 ~~a.m. or~~ p.m. to 3:00 ~~a.m. or~~ p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power Center	0%	None Observed	Reported
2.	Charger	0%	None Observed	Reported
3.	Work Area	0%	None Observed	Reported
4.	D-Boxes	0%	None Observed	Reported
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: Track + Travelway clear at time of exam
0% CH4, 0ppm CO, 20.8% O2 detected at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnoe (Preshift-Mine Examiner) 1536-A (Certificate No.) [illegible] (Assistant Foreman) 1354-A (Certificate No.)

Countersigned [illegible] (Mine Manager—Mine Foreman) 33359

[illegible] (Assistant Foreman)

Mike Bailey 27085 (Superintendent or Assistant)

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-25-09 20 09 Section or Area Examined Longwall Construction

Time of Examination: from 4:30 a.m. or p.m. to 11:30 a.m. or p.m.

Was this report phoned to outside: Yes_____ no_____

By whom _____ Time _____A.M _____P.M.

Report received by Brought out
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power center	0%	None observed	None
2.	D-Boxes	0%	None observed	None
3.	Chargers	0%	None observed	None
4.	Work Area	0%	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks: 20.8% O^2, 0% CH4, 0PPm C.O.,
Track, Travelways, OK At time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] 1534A
Preshift-Mine Examiner — Certificate No. — Assistant Foreman — Certificate No.

Countersigned [signature] 33354
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-26-09 20___ Section or Area Examined Llwall const.

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ___

By whom Brought out Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Ch4	Violation or Hazardous Condition	Action Taken
1.	Power centers	0%	none Observed	none
2.	D-Box	0%	none Observed	none
3.	Chargers	0%	none Observed	none
4.	work Area	0%	none observed	none
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Airmt			

Remarks: 0% Ch4 0% CO 208602

Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 1539A Certificate No. _____ Assistant Foreman _____ Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359

_____ Assistant Foreman _____

_____ Superintendent or Assistant _____

John A. Bickford 26176

[signature] 1354-A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-26-09 20____ Section or Area Examined LW Construction

Time of Examination: from 1200 a.m. or (p.m.) to 1245 a.m. or (p.m.)

Was this report phoned to outside: Yes ✓ no____

By whom Bill Campbell Time ____ A.M 250 P.M.

Report received by Tim Williams (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	Power Centers 0% CH4	None observed	None
2.	D-Box's 0% CH4	None observed	None
3.	Chargers 0% CH4	None observed	None
4.	Work Area 0% CH4	None observed	None
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
good air movement			

Remarks: 0% CH4, 20.8% O2, 0% CO
Track & travelways clear at face.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 13544 — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — 33359 — [signature] — 16594

Assistant Foreman

Superintendent or Assistant

[signature] 15394

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-26-09 20____ Section or Area Examined L/wall cont.

Time of Examination: from 8:30 a.m. or p.m. to 1:30 a.m. or p.m.

Was this report phoned to outside: Yes____ no ✓

By whom Brought out Time ____A.M ____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	PL's OZ CH4	none Observed	none
2.	O-Box's OZ CH4	none Observed	none
3.	Chargers OZ CH4	none observed	none
4.	Work Area OZ CH4	none Observed	None
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air			

Remarks: OZ CH4, OZ CO, 20.8 OZ
Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 15394 — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — 33339

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-27-09 20___ Section or Area Examined L/wall const.

Time of Examination: from 800 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom Freight out Time _____A.M _____P.M.

Report received by _____
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	PC's CB Chy	none	none
2.	O-Box	none	none
3.	Charger	none	none
4.	walk Area	none	none
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airmnt			

Remarks: CB Chy - CB CO 20.8 O2
Travelways ok

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] 15399
Preshift-Mine Examiner — Certificate No. — Assistant Foreman — Certificate No.

Countersigned [signature] 33359
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

[signature] 1354-A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-27 2009 Section or Area Examined L/W Const

Time of Examination: from 12 a.m. or p.m. to 3 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Bill C Time A.M 230 P.M.

Report received by Joey Stewart 39199
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	PC's	0%	None observed	None
2.	D-Boxes	0%	None observed	None
3.	Charger	0%	None observed	None
4.	Work Area	0%	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks:

0% CH4, 0% CO, 20.8%
Traveling Clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 1354A (Certificate No.) _____ (Assistant Foreman) _____ (Certificate No.)

Countersigned Troy Williams (Mine Manager—Mine Foreman) 33359 _____ (Assistant Foreman) _____ _____ (Superintendent or Assistant) _____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-27-09 20 09 Section or Area Examined L.W. Construction

Time of Examination: from 8:30 a.m. or p.m. to 11:30 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____

By whom Steve Campbell Time ____ A.M 11:10 P.M.

Report received by [signature] Col 1447-A (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	P.C's	0%	None observed	None
2.	D-Boxes	0%	None observed	None
3.	Chargers	0%	None observed	None
4.	Work Area	0%	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks: 0% CH4, 20.8% O2, 0PPm C.O. Detected
Track, Travelway ok At time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Col (Preshift-Mine Examiner) 1447-A (Certificate No.) [signature] (Assistant Foreman) 31092 (Certificate No.)

Countersigned [signature] (Mine Manager—Mine Foreman) 33359

(Assistant Foreman)

(Superintendent or Assistant)

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-28-09 20__ Section or Area Examined L.W. Constr.

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes____ no ✓

By whom Brought out Time 5:30 A.M. ____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Chargers	OX	None observed	None
2.	Work Area	OX	None observed	None
3.	D. Boxes	OX	None observed	None
4.	Power Centers	OX	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks: OX CH4, 0ppm CO, 20.85 O2 detected at time of exam

Track & Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 37042 — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-28-09 20___ Section or Area Examined LW Const.

Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Chargers	0%	None OBSERVed	None
2.	D-Box's	0%	None OBSERVed	None
3.	PowerCenters	0%	None OBSERVed	None
4.	WORK AREA	0%	None OBSERVed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH^4, 20.8% O^2, 0ppm CO. Detected at Exam
TRACK + TRAVELWAYS-Clear.

Steve Cogleh 39042 Michael Ferrell 37942

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead 37567
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.

Countersigned [signature] 33359
Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-28-09 20 09 Section or Area Examined L.W. Const.

Time of Examination: from 8:30 a.m. or p.m. to 11:30 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom Steve Campbell Time A.M 11:00 P.M.

Report received by Gary Cole 1947-A
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Chargers	0%	None observed	None
2.	D-Boxes	0%	None observed	None
3.	Power center	0%	None observed	None
4.	Work Area	0%	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0PPM C.O. Detected
Track, Travelways, OK At time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. [signature] — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — 33359

Assistant Foreman

Superintendent or Assistant

Gary Cole 1947-A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-29-09 20___ Section or Area Examined Intake Rooms

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom Brought out Time 5:25 A.M. _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power Center's	OK	None observed	None
2.	D- Boxe's	OK	None observed	None
3.	Charger's	OK	None observed	None
4.	Work Area	OK	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: OK CH4 0ppm CO, 20.8% O2 detected at time of exam

Track & Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 390442 Certificate No. _____ Assistant Foreman _____ Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 37359

_____ Assistant Foreman _____

_____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-29-09 20__ Section or Area Examined LW Const.

Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power Centers	0%	None OBSERVED	None
2.	D-Boxs	0%	None OBSERVED	None
3.	Chargers	0%	None OBSERVED	None
4.	Work Area	0%	None OBSERVED	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH^4, 20.8% O^2, 0ppm CO Detected at Exam
Track & Travelways Clear.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead (Preshift-Mine Examiner) 37567 (Certificate No.) _____ (Assistant Foreman) _____ (Certificate No.)

Countersigned Troy W. Mauer (Mine Manager—Mine Foreman) 33359 _____

_____ (Assistant Foreman) _____ _____ _____

_____ _____ _____ (Superintendent or Assistant) _____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-29-09 20___ Section or Area Examined LW const.

Time of Examination: from 830 a.m. or p.m. to 1130 a.m. or p.m.

Was this report phoned to outside: Yes_____ no___

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Ch4	Violation or Hazardous Condition	Action Taken
1.	PC's	06	None Observed	none
2.	D-Box	06	none Observed	none
3.	Charger	02	none Observed	none
4.	Work Area	06	none Observed	none
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Airmount			

Remarks: 02 Ch4 06 CO2 0 08 2 02

Travelways ok

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 15797 Certificate No. _____ Assistant Foreman _____ Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359 _____

_____ Assistant Foreman _____ _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-30-09 20___ Section or Area Examined L/WALL Constr.

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom Brought out Time 5:25 A.M. _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Power Center's	ox	None observed	None
2.	D. Boxe's	ox	None observed	None
3.	Charger's	ox	None observed	None
4.	Work Area	ox	None observed	None
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: ox CH4, 0 ppm CO, 20.8x O2 detected at time of exam

Track & Travelway's ok at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 15 3[illegible] Certificate No. _____ Assistant Foreman _____ Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359

_____ Assistant Foreman _____

_____ Superintendent or Assistant

Wetto Campbell 13544

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 12-30-09 20___ Section or Area Examined LW Construction

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes ✓ no ___

By whom Billy Campbell Time ___ A.M 2:50 P.M.

Report received by George Curry (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	Power Centers	None OBSERVED	None
2.	D-Box	None OBSERVED	None
3.	WORK AREA	None OBSERVED	None
4.	Chargers	None OBSERVED	None
5.	timber work area	None observed	Reported
6.	inby mouth of Longwall	" "	" "
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Measured			

Remarks: 0% CH_4, 20.8% O_2, 0ppm CO Detected at Exam
track & travelways-Clear
went over page 4 & 5 of Roof control plan

Michael Farrell 37942

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By ___ Preshift-Mine Examiner ___ Certificate No. ___ Assistant Foreman ___ Certificate No.

Countersigned ___ Mine Manager—Mine Foreman ___ ___

___ Assistant Foreman ___ ___

___ Superintendent or Assistant ___