Intake Rooms

PRESHIFT - ONSHIFT
and
DAILY REPORT

Started 2-15-10

Full

Company Performance Coal Co.

Mine UBB

SECTION Intake Rooms

LOCATION Naoma (Post Office) Raleigh (County) WV (State)

Form 6-1489
(March 1970)

Budget Bureau No. 42-R1589

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# MS-014

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-15 20 10 Section or Area Examined Intake Rooms

Time of Examination: from _____ a.m. or p.m. to _____ a.m. or p.m.

Was this report phoned to outside: Yes_____ no_____

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	North Mains CH4	NONE OBSERVED	NONE
2.	Glory hole	NONE OBSERVED	NONE.
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air Flow			

Remarks: O^2 20.8%, 0% CH4, 0% CO, Detected at Exam
Track/Travelways D-Box, Pump —

[signature] 15 Jan 99

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32476

Countersigned T. Mann Mine Manager—Mine Foreman — 33359

Assistant Foreman

Assistant Foreman — Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-16-10 20 10 Section or Area Examined Intake Rooms

Time of Examination: from 1200 a.m. or p.m. to 2000 a.m. or p.m.

Was this report phoned to outside: Yes ____ no X

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	North Mains OZ Cuy	none	None
2.	Gary Hole OZ Cuy	none	none
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airmt			

Remarks: OZ Cuy OZ CO 20.8 OZ

Travel ways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 1534A Certificate No. ____ Assistant Foreman ____ Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33359

____ Assistant Foreman ____ ____ Superintendent or Assistant ____

Scott Halstead 37567

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-16-10 20___ Section or Area Examined Intake Rooms

Time of Examination: from 7:00 a.m. or p.m. to 7:30 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None OBSERVed	None
2.	Glory Hole	0%	None OBSERVed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH^4, 20.8% O^2, 0ppm CO Detected at Exam time
TRACK & TRAVELWAYS Clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead (Preshift-Mine Examiner) 37567 (Certificate No.) _____ (Assistant Foreman) _____ (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359 _____

_____ (Assistant Foreman) _____ _____ _____

_____ _____ _____ (Superintendent or Assistant)

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-17-10 20 Section or Area Examined Intake Rooms

Time of Examination: from 8:00 a.m. or p.m. to 11:00 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____

By whom ____ Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	North Mains	None Observed	None
2.	Glory Hole	None Observed	None
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Air Movement Good.			

Remarks: 0% CH4 0% CO 20.9% OR AT TIME OF EXAM.
TRAVELWAYS & TRACK clear AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 32476 Certificate No. ____ Assistant Foreman ____ Certificate No. ____

Countersigned T. Moore Mine Manager—Mine Foreman 33359

____ Assistant Foreman ____ ____ Superintendent or Assistant ____

John Richard 26176

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-17-10 20__ Section or Area Examined Intake Rooms

Time of Examination: from 10:50 a.m. or p.m. to 12:00 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no____

By whom John Bickford Time ____ A.M 2:30 P.M.

Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% Ch4, O2 20.8%, 0 ppm CO at time of exam
Travelways OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford (Preshift-Mine Examiner) 26176 (Certificate No.) John [signature] (Assistant Foreman) 33476 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 15359

Assistant Foreman

Superintendent or Assistant

[signature] 15394

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-17-10 2010 Section or Area Examined Intake Rooms

Time of Examination: from 710 a.m. or p.m. to 735 a.m. or p.m.

Was this report phoned to outside: Yes ____ no X

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	North Mains CH4 O3	none	none
2.	Glory Hole CH4 O6	none	none
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Aim			

Remarks: O6 CH4 O6 CO 20.83 O2

Travel Ways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 1539A Certificate No. [signature] Assistant Foreman 32476 Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-18-10 20 Section or Area Examined INTAKE ROOM

Time of Examination: from 100 a.m. or p.m. to 1:30 a.m. or p.m.

Was this report phoned to outside: Yes ____ no X

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	NORTH MAINS	NONE OBSERVED	
2.	Glory Hole	NONE OBSERVED	
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4 0% CO 20.8% O2 AT Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 18394 Certificate No. ____ Assistant Foreman ____ Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33359

____ Assistant Foreman ____ ____ Superintendent or Assistant ____

John A. Bickford 261 Th

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-18- 2010 Section or Area Examined Intake Rooms

Time of Examination: from 10:30 a.m. or p.m. to 11:45 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Bickford Time A.M 2:30 P.M.

Report received by Russell Dunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks:

0% CH4, 20.8% O2, 0 ppm CO at time of exam

Travelways Ok at Time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford 26176 Assistant Foreman Certificate No.

Preshift-Mine Examiner Certificate No.

Countersigned T. Moore 33352

Mine Manager—Mine Foreman

Assistant Foreman

Superintendent or Assistant

[signature] 153 [illegible]

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-18-10 20.... Section or Area Examined Intake Rooms

Time of Examination: from 730 a.m. or p.m. to 860 a.m. or p.m.

Was this report phoned to outside: Yes..... no X

By whom Brought out Time ..... A.M ..... P.M.

Report received by ..... (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	North Mains 06 Ch4	n/o	none
2.	Glory Hole 06 Ch4	n/o	none
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air [illegible]			

Remarks: 06 CO 02 Ch4 20.8 O2

Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 15394 — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-19-10 20___ Section or Area Examined Intake Rooms

Time of Examination: from 100 a.m. or p.m. to 130 a.m. or p.m.

Was this report phoned to outside: Yes_____ no X

By whom Brought out Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	N Mains Chy OB	none	none
2.	6 bry Hole OB	none	none
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airment			

Remarks: OB Chy OB CO 20.8 OB

Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 15397 Certificate No. [signature] Assistant Foreman 32476 Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359

Assistant Foreman

Superintendent or Assistant

John R. Bickford 21171

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-19- 20 10 Section or Area Examined Intake Rooms

Time of Examination: from 10:50 a.m. or p.m. to 11:30 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Bick Sard Time A.M 2:30 P.M

Report received by Russell Dunmoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelway OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford (Preshift-Mine Examiner) Certificate No. 2617 Assistant Foreman Certificate No.

Countersigned T. Moore (Mine Manager—Mine Foreman) 33389

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-19-10 20__ Section or Area Examined INTAKE ROOMS

Time of Examination: from 8:00 a.m. or p.m. to 11:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	NORTH MAINS	NONE OBSERVED	NONE
2.	GORY HOLE	NONE OBSERVED	NONE
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Movement			

Remarks: 20.8% O_2, 0% CH_4 0% CO AT TIME OF EXAM.
TRANSLWAYS, TRACK OK AT TIME OF EXAM.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift Mine Examiner — Certificate No. 32476

Countersigned [signature] Mine Manager—Mine Foreman — Certificate No. 3335-9

Assistant Foreman — Certificate No.

Assistant Foreman

[signature] Superintendent or Assistant — 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-20-10 20____ Section or Area Examined INTAKE ROOMS

Time of Examination: from 2:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	*Violation or Hazardous Condition*	*Action Taken*
1. NORTH MAINS	NONE OBSERVED	
2. GLORY HOLE	NONE OBSERVED	
3.		
4.		
5.		
6.		
7.		
8.		
9.		
10.		

Air Measurements

Location	*CFM*	*Location*	*CFM*
GOOD AIR MOVEMENTS			

Remarks: 20.8% O_2 0% CH_4 0% CO AT TIME OF EXAM
TRAVELWAYS, TRACK OK AT TIME OF EXAM.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32476 — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — Certificate No. 28359

Assistant Foreman — Certificate No.

Superintendent or Assistant

John R. Bickford 2-20-10

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____ Assistant Mine	_____ Certificate No.	_____ Mine Foreman-Mine Manager	_____ Certificate No.	_____ Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-20 20 10 Section or Area Examined Intake Rooms

Time of Examination: from 830 a.m. or p.m. to 930 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom J. Neely Time A.M 230 P.M.

Report received by John A. Bickford (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	ch4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% ch4, 0% CO & 20.8% O_2 detected at time of exam

Track & travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____ Preshift-Mine Examiner Certificate No. _____ Assistant Foreman Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33357 John A. Bickford 26176

Assistant Foreman Johnny Neely 33472

Superintendent or Assistant

William Campbell 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-20 20 10 Section or Area Examined Intake Rooms

Time of Examination: from 8:00 a.m. or p.m. to 11:00 a.m. or p.m.

Was this report phoned to outside: Yes X no

By whom Campbell Time A.M 1100 P.M.

Report received by Olen Millman 1539A (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4%	Violation or Hazardous Condition	Action Taken
1.	North Mains	06	none	none
2.	Glory Hole	06	none	none
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Airment			

Remarks: CH4 06, CO 06, O2 20.8% Detected

Track/Travelways, D-Box's, Pumps, — all OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 1354A (Certificate No.) Assistant Foreman Certificate No.

Countersigned T. Moore (Mine Manager—Mine Foreman) 33309

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-21 20 10 Section or Area Examined Intake Rooms

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	none	none
2.	Glory Hole	0%	none	none
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: CH4 0%, CO 0%, O^2 20.8% Detected

Track/Travelways, D-Box's, Pumps - all clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 1354-A (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33309

Assistant Foreman

Assistant Foreman

Johnny Reddy (Superintendent or Assistant) 33472

John A. Bichford 2617

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-21 20 10 Section or Area Examined Intake Rooms

Time of Examination: from 800 a.m. or p.m. to 900 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____

By whom S. Neely Time ____ A.M 225 P.M.

Report received by John A. Bickford (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	<64	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH_4, 0% CO + 20.8% O_2 detected

Track + travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely (Preshift-Mine Examiner) 33472 (Certificate No.) [signature] (Assistant Foreman) 32476 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

Assistant Foreman

John A. Bickford 2617

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-21-10 20____ Section or Area Examined INTAKE ROOMS

Time of Examination: from 8:00 a.m. or p.m. to 11:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no_____

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	NORTH MAINS	NONE OBSERVED	NONE
2.	GLORY HOLE	NONE OBSERVED	NONE
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Air Flow Good. At Time of Exam.			

Remarks: 0% CH4 0% CO 20.8% O2 At Time of Exam.
Track & Travelways ok At Time of Exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32476

Countersigned T. Moore Mine Manager—Mine Foreman — 33259

Assistant Foreman — Certificate No.

Assistant Foreman

[signature] Superintendent or Assistant — 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-22-10 20____ Section or Area Examined INTAKE ROOMS

Time of Examination: from 2:00 (a.m) or p.m. to 6:30 (a.m) or p.m.

Was this report phoned to outside: Yes_____ no_____

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	North Mains	NONE OBSERVED	NONE
2.	Glory Hole	NONE OBSERVED	NONE
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Flow At Time of Exam			

Remarks: 0% CH4 0% CO 20.7% O2 At Time of Exam
Travelways & Track OK At Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32476 — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359 — Johnny Neely 33472

Assistant Foreman — Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-22- 2010 Section or Area Examined Intake Rooms

Time of Examination: from 10:50 a.m. or p.m. to 11:20 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Weely Time A.M 2:40 P.M.

Report received by Russell Gunnel (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	North Mains CH4 0%	None Observed	None
2.	Glory Hole 0%	None Observed	None
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0 ppm CO at time of exam
Travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely — Preshift-Mine Examiner — 33472 Certificate No. — Assistant Foreman — Certificate No.

Countersigned T. Moore — Mine Manager—Mine Foreman — 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-22-16 20__ Section or Area Examined Intake Rooms

Time of Examination: from 9:00 a.m. or ~~p.m.~~ to 11:30 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom Brought out Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None observed	None
2.	Glory Hole	0%	none observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O^2 Detected
Track/Travelways, D-Box, Pumps all clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift Mine Examiner — Certificate No. 32476 — Assistant Foreman — Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman — 3307

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____ Assistant Mine	Certificate No.	_____ Mine Foreman-Mine Manager	Certificate No.	_____ Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-23-10 20____ Section or Area Examined INTAKE ROOMS

Time of Examination: from 2:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	NORTH MAINS	NONE OBSERVER	NONE
2.	GLORY HOLE	NONE OBSERVED	NONE
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
GOOD AIR MOVMENT			

Remarks: 0% CH4 0% CO 20.9% O2 AT TIME OF EXAM
TRACK & TRAVELWAYS OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____ Preshift-Mine Examiner 32476 Certificate No. _____ Assistant Foreman _____ Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33339 _____

_____ Assistant Foreman _____ _____ Superintendent or Assistant _____

Johnny Reely 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-23- 2010 Section or Area Examined Intake Rooms

Time of Examination: from 10:45 a.m. or p.m. to 11:30 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Neely Time A.M 2:40 P.M.

Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0ppm CO at time of exam

Travelways ok at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____ Preshift-Mine Examiner — Certificate No. 33359

Countersigned T. Moore Mine Manager—Mine Foreman

_____ Assistant Foreman

_____ Assistant Foreman — Certificate No. 32476

Johnny Neely — Certificate No. 33472

_____ Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-23 20 10 Section or Area Examined Intake Rooms

Time of Examination: from 800 a.m. or ~~p.m.~~ to 1100 a.m. or ~~p.m.~~

Was this report phoned to outside: Yes_____ no_____

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*CH4*	*Violation or Hazardous Condition*	*Action Taken*
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Movement			

Remarks: 0% CH_4, 0% CO, 20.8% O_2 Detected
Track / Travelways OK at Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32476 — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — Certificate No. 3335-7

Assistant Foreman — Certificate No.

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____ Assistant Mine	_____ Certificate No.	_____ Mine Foreman-Mine Manager	_____ Certificate No.	_____ Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-24-10 20____ Section or Area Examined ENTRY ROOMS

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	NORTH MAINS	NONE OBSERVED	NONE
2.	GLORY HOLE	NONE OBSERVED	NONE
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
GOOD AIR MOVEMENT			

Remarks: 0% CH4 0% CO 20.8% O2 AT TIME OF EXAM
TRAVELWAYS & TRACK O/K AT TIME OF EXAM.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32476

Countersigned [signature] Mine Manager—Mine Foreman — Certificate No. 33359

Assistant Foreman — Certificate No.

Assistant Foreman — Certificate No.

Superintendent or Assistant [signature] — Certificate No. 33472

John A. Bickford 26174

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-24- 2010 Section or Area Examined Intake Rooms
Time of Examination: from 12:30 a.m. or p.m. to 1:00 a.m. or p.m.
Was this report phoned to outside: Yes ✓ no
By whom John Neely Time A.M 2:35 P.M.
Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelways OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John Neely (Preshift-Mine Examiner) 33472 (Certificate No.) [signature] (Assistant Foreman) 32476 (Certificate No.)
Countersigned [signature] (Mine Manager—Mine Foreman) 33359
Assistant Foreman
Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-24-10 20__ Section or Area Examined Intake Rooms

Time of Examination: from 700 a.m. or p.m. to 230 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no ____

By whom SKAGGS Time ____ A.M 1100 P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	North Mains OZ Ch4	NO	none
2.	66 my Hole OZ	n/O	none
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airmont			

Remarks: OZ Ch4 OZ CO 20.8 OZ

Travel ways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift Mine Examiner 32476 Certificate No. ____ Assistant Foreman ____ Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359

____ Assistant Foreman ____ ____ Superintendent or Assistant ____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-25-10 20___ Section or Area Examined INTAKE ROOM

Time of Examination: from 3:00 ~~a.m.~~ or p.m. to 6:00 ~~a.m.~~ or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	NORTH MAINS	NONE OBSERVED	NONE
2.	Glory Hole	NONE OBSERVED	NONE
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Movement			

Remarks: 0% CH4 0% CO 20.8% O2 AT TIME OF EXAM

TROLLEYS & TRACK OK AT TIME OF EXAM.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32476 — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — Certificate No. 33359

Assistant Foreman

Superintendent or Assistant

John A. Bickford 2617b

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-25- 2010 Section or Area Examined Intake Rooms

Time of Examination: from 10:30 a.m. or p.m. to 11:30 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Bickford Time A.M 2:30 P.M.

Report received by Russell Dunmyer (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0 ppm CO at time of exam
Travelways OK at time of exam

Dan Ullman 1539A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford 2616
Preshift-Mine Examiner — Certificate No.

Countersigned Terry W. Moore 33359
Mine Manager—Mine Foreman

Assistant Foreman — Certificate No.

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-25-10 20___ Section or Area Examined Intake Rooms

Time of Examination: from 700 a.m. or p.m. to 745 a.m. or p.m.

Was this report phoned to outside: Yes_____ no X

By whom Drought out Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location LLY	Violation or Hazardous Condition	Action Taken
1.	N. Mains OK	none	none
2.	Gobby Hole OK	none	none
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air			

Remarks: OK CH4 OK CO 20.86 OK

Travelings OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 1539A Certificate No. _____ Assistant Foreman _____ Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33359

_____ Assistant Foreman _____

_____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-26-10 20____ Section or Area Examined Intake Rand

Time of Examination: from 115 a.m. or p.m. to 200 a.m. or p.m.

Was this report phoned to outside: Yes____ no X

By whom Straightout Time ____A.M ____P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	N. Main Ch4 O6	none	none
2.	Crosscut O6	none	none
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Airway			

Remarks: O2 Ch4 O6 CO 20 P6 O2

Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 15794 — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — 33389

Assistant Foreman

Superintendent or Assistant Scott Halstead 37567

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-26 2010 Section or Area Examined Intake Rooms

Time of Examination: from 7:00 (a.m.) or p.m. to 7:30 (a.m.) or p.m.

Was this report phoned to outside: Yes ____ no ✓

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH^4, 20.8% O^2, 0ppm CO Detected at Exam time
track + Travelways Clear time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Scott Halstead (Preshift-Mine Examiner) Certificate No. 37547

Countersigned T. Moore (Mine Manager—Mine Foreman) Certificate No. 3335-2

Assistant Foreman William Campbell Certificate No. 125974

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-26 20 10 Section or Area Examined Intake Rooms

Time of Examination: from 800 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom B. Campbell Time A.M P.M.

Report received by Dan Allen (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	none observed	none
2.	Glory Holes	0%	none observed	none
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
C7000 Air Movement			

Remarks: 0% CH4, 20.8% O2, 0% CO - Detected
Tench/Travelways, D-Box + Pump all clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____ Preshift-Mine Examiner — Certificate No. 33359 — Assistant Foreman — Certificate No.

Countersigned _____ Mine Manager—Mine Foreman

Assistant Foreman — Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-27 2010 Section or Area Examined Intake Rooms

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ✓

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	N/O	none
2.	Glory Hole	0%	N/O	none
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
Track/Travelways Clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 1384-A (Certificate No.) ____ Assistant Foreman ____ Certificate No.

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

____ Assistant Foreman

____ Superintendent or Assistant Johnny Neely 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-27 2010 Section or Area Examined Intake Rooms

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes ✓ no

By whom John Neely Time A.M 2:30 P.M.

Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks:

0% CH4, 20.8% O2, 0 ppm CO at time of exam

Travelways OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely (Preshift-Mine Examiner) 33472 (Certificate No.) Assistant Foreman Certificate No.

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359 William Campbell 13544

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made.

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-27 2010 Section or Area Examined Intake Rooms

Time of Examination: from 800 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes X no

By whom Cambell Time A.M 1100 P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	North Mains CH4	none	none
2.	Glory Hole CH4	none	none
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air [illegible]			

Remarks: CH4, CH4 : CO, 20.8% O2 Detected

Track/Travelways all clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 1354-A (Certificate No.) Assistant Foreman Certificate No.

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-28 2010 Section or Area Examined Intake Rooms

Time of Examination: from 300 am or p.m. to 600 am or p.m.

Was this report phoned to outside: Yes_____ no_____

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	N/O	None
2.	Glory Hole	0%	N/O	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected

Track / Travelways all - clean at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 1354-A (Certificate No.) _____ Assistant Foreman _____ Certificate No.

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

_____ Assistant Foreman _____

_____ Superintendent or Assistant

John A. Bickford 26176 Johnny Neely 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-28 20 10 Section or Area Examined Intake Rooms

Time of Examination: from 930 a.m. or p.m. to 1010 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom J. Neely Time 0 A.M 210 P.M.

Report received by John A. Bickford (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	ch4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% ch4 0% CO & 20.8% O2 detected

Track & travelways clear at time exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely (Preshift-Mine Examiner) 33472 (Certificate No.) [signature] (Assistant Foreman) 32476 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359 John A. Bickford 26176

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-28 2010 Section or Area Examined Intake Rooms

Time of Examination: from 900 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes_____ no_____

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	*Violation or Hazardous Condition*	*Action Taken*
1.	North Mains	0%	NONE OBSERVED	NONE
2.	Glory Hole	0%	NONE OBSERVED	NONE
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
Tenck/Travelways clean at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____ Preshift-Mine Examiner 38476 Certificate No. _____ Assistant Foreman _____ Certificate No.

Countersigned _____ Mine Manager—Mine Foreman 33359

_____ Assistant Foreman _____ _____ Superintendent or Assistant _____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-1 2010 Section or Area Examined Intake Rooms

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom J Scaggs Time 530 A.M. P.M.

Report received by Willis Campbell 13544 (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	North Mains CH4	NONE OBSERVED	NONE
2.	Glory Hole	NONE OBSERVED	NONE
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
Travelways, Pump + D-Box Clearout Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 32476 Certificate No. Assistant Foreman Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33389

Assistant Foreman

Superintendent or Assistant Johnny Reely 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-1 2010 Section or Area Examined Intake Rooms

Time of Examination: from 11:30 a.m. or p.m. to 11:52 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Neely Time A.M 2:40 P.M.

Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH_4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH_4, 20.8% O_2, 0ppm CO at time of exam
Travelways OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Johnny Neely (Preshift-Mine Examiner) 33472 Certificate No. [signature] (Assistant Foreman) 32476 Certificate No.

Countersigned T. Moore (Mine Manager—Mine Foreman) 33389

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-1 2010 Section or Area Examined Intake Rooms

Time of Examination: from 900 a.m. or p.m. to 9:30 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom J. Skaggs Time A.M 1005 P.M.

Report received by Witto Campbell 1354-A (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	N/O	
2.	Glory Hole	0%	N/O	
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
Track/Travelways, D-Box's, Pump all clean At Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 32476 Certificate No. Assistant Foreman Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33357

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-2-10 20___ Section or Area Examined Injaries Rooms

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no✓

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	North Mains	None Observed	None
2.	Glory Hole	None Observed	None
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4 0% CO 20.8% O2 At Time of Exam

Track & Travelway OK At Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32476

Countersigned [signature] Mine Manager—Mine Foreman — Certificate No. 33359

Assistant Foreman

Assistant Foreman — Certificate No.

Superintendent or Assistant [signature] 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-2- 2010 Section or Area Examined Intake Rooms

Time of Examination: from 11:30 a.m. or p.m. to 11:57 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____ Time ____ A.M 2:40 P.M.

By whom John Neely

Report received by Russell Dunmore (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH_4	Violation or Hazardous Condition	Action Taken
1.	North MAINS	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks: 0% CH_4, 20.8% O_2, 0 ppm CO at time of exam
TRAVELWAYS OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John Neely Preshift-Mine Examiner — Certificate No. 33472

Assistant Foreman — Certificate No. 32476

Countersigned T. Moore Mine Manager—Mine Foreman — Certificate No. 33397

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-2-10 20___ Section or Area Examined Intake Rams

Time of Examination: from 800 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no ___

By whom SKAGGS Time ___ A.M 1100 P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	N. Mains OK	None	None
2.	Gooy Hole OK	None	None
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air Mount			

Remarks: OK CWY OK CO 20.8 OZ

Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 32476 Certificate No. ___ Assistant Foreman ___ Certificate No.

Countersigned T. Mann Mine Manager—Mine Foreman 33357

___ Assistant Foreman ___ ___ Superintendent or Assistant ___

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____ Assistant Mine	_____ Certificate No.	_____ Mine Foreman-Mine Manager	_____ Certificate No.	_____ Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-3-16 20___ Section or Area Examined INTAKE Rooms

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	NORTH MAINS	NONE OBSERVED	NONE
2.	Glory Hole	NONE OBSERVED	NONE
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
GOOD AIR MOVEMENT			

Remarks: 0% CH4 0% CO 20.8% O2. AT Time of EXAM
TRAVELWAYS & TRACK OK AT Time of EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____ Preshift-Mine Examiner — 32476 Certificate No. — Assistant Foreman — Certificate No.

Countersigned _____ Mine Manager—Mine Foreman — 33367

Assistant Foreman

Superintendent or Assistant — Johnny Neely

33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-3 2010 Section or Area Examined Intake Rooms

Time of Examination: from 11:25 a.m. or [illegible] to 11:50 a.m. or [illegible]

Was this report phoned to outside: Yes ____ no ✓

By whom Brought Outside Time ____ A.M ____ P.M.

Report received by Charles Semenske (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	5BK Intake Rooms	None observed	None
2.	4North Head Intake Rooms	None Observed	None
3.	North Mains 0% CH4	None Observed	None
4.	Glory Hole 0%	None Observed	None
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 20.8% 0% CH4 0% CO

Travelways OK at time of exam

Weekly

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Charles Semenske (Preshift-Mine Examiner) 31292 (Certificate No.) [signature] (Assistant Foreman) 32476 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33331

Assistant Foreman

Johnny Neely (Superintendent or Assistant) 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 8-3-10 20____ Section or Area Examined INTAKE ROOM

Time of Examination: from 800 a.m. or ~~p.m.~~ to 1130 a.m. or ~~p.m.~~

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	NORTH MAINS	NONE OBSERVED	NONE
2.	Glory Hole	NONE OBSERVED	NONE
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Movement			

Remarks: 0% CH4 0% CO 20.8% O2 AT TIME OF EXAM
TRAVELWAY & TRACK OK AT TIME OF EXAM

This is to certify that (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32476 — Assistant Foreman — Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman — Certificate No. 33357

Assistant Foreman — Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-4-16 20____ Section or Area Examined Intake Rooms

Time of Examination: from 330 a.m. or p.m. to 200 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	N. Mains CH4 OK	none	none
2.	Gary Hole CH4 OK	none	none
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air			

Remarks: OK CH4 OK CO 20.86 O2
Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 15398

[signature] Assistant Foreman — Certificate No. 38476

Countersigned T. Mark Mine Manager—Mine Foreman — Certificate No. 33339

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-4- 2010 Section or Area Examined Intake Rooms

Time of Examination: from 10:30 a.m. or p.m. to 11:15 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Bickford Time A.M 2:30 P.M.

Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	N. Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.				
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelways OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford (Preshift-Mine Examiner) 2617 (Certificate No.) [signature] (Assistant Foreman) 32476 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

Assistant Foreman

Superintendent or Assistant