• Started 2-16-10 •

Pumps

PRESHIFT - ONSHIFT
and
DAILY REPORT

Pumps
Full

Company Performance Coal

Mine UBB

SECTION North Pumps

LOCATION Naoma (Post Office) Raleigh (County) WV (State)

Form 6-1489
(March 1970)

Budget Bureau No. 42-R1589

When this book is completed it shall be retained at the mine for a period of one year after the date of the last entry in the book, regardless of change of ownership. When a mine is temporarily closed or abandoned, the operator shall retain this book in a safe place during the period of closure or for a period of one year after the mine is abandoned. **Do not** mail this book to the Bureau of Mines.

REORDER FROM CHAPMAN PRINTING COMPANY • (800) 824-6620

FORM# MS-014

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-16 20 10 Section or Area Examined Pump

Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no_____

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0 ppm CO at time of exam
Travelways, Power Centers, D-Boxes clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnoe (Preshift-Mine Examiner) 1536-A (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

Assistant Foreman Scott Halstead Certificate No. 37567

Assistant Foreman

Examiner's Signature

William Campbell 1354-A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-16 2010 Section or Area Examined Pumps

Time of Examination: from 8:30 a.m. or p.m. to 11:30 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ✓

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	none observed	none
2.	Glory Hole	0%	none observed	none
3.	Ellis	0%	none observed	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected

Track/Travelways, D-Box's + Pumps all clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 13547A (Certificate No.) ____ (Assistant Foreman) ____ (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

____ (Assistant Foreman) ____ Gen [signature] 15394

____ (Superintendent or Assistant) ____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-10-10 2010 Section or Area Examined Pumps

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom Brought out Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	none observed	none
2.	Glory Hole	0%	None Observed	none
3.	Ellis	0%	none observed	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
Travel Haulageways, D-Box's + Pump Clean at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) Certificate No. 13544 _____ (Assistant Foreman) Certificate No. _____

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359 _____

_____ (Assistant Foreman) _____ _____ _____

_____ _____ _____ (Superintendent or Assistant)

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-17-10 20.... Section or Area Examined Pumps

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes..... no ✓

By whom ..... Time ..... A.M ..... P.M.

Report received by .....
(Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	North Mains	None Observed	None
2.	Glory Hole	None Observed	None
3.	Ellis	None Observed	None
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Movement At Time of Exam			

Remarks: 0% CO 0% CH4 20.8% O2 At Time of Exam
Trads, And Travelways O.K. At Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 5384 — [signature] Assistant Foreman — Certificate No. 32476

Countersigned [signature] Mine Manager—Mine Foreman — Certificate No. 33359

..... Assistant Foreman

..... Superintendent or Assistant

John A. Bickford 26171 Russell Dunmoe 1536-A Scott Hatstead 37347

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-17- 2010 Section or Area Examined Pumps

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes ✓ no

By whom John Bickford Time A.M 2:30 (P.M)

Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0ppm CO at time of exam
Traveluays, Power Centers, D-Boxes, OK at time of exam

Glen Allman 1539

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnoe (Preshift-Mine Examiner) 1536-A (Certificate No.) [signature] (Assistant Foreman) 32476 (Certificate No.)

Countersigned [signature] (Mine Manager—Mine Foreman) 33337 Scott Halstead 31567

(Assistant Foreman) John A. Bickford (Superintendent or Assistant) 2617b

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-17-10 20 10 Section or Area Examined Pumps

Time of Examination: from 830 a.m. or p.m. to 1130 a.m. or p.m.

Was this report phoned to outside: Yes ____ no X

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	N. MAINS CH4 O2	none	none
2.	Gbry Hole O2	none	none
3.	Ellis O2	none	none
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airmount			

Remarks: O2 CH4 O2 CO 20.8202

Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 1534A

Countersigned T. Moore Mine Manager—Mine Foreman — Certificate No. 33359

Assistant Foreman William Campbell — Certificate No. 1354-A

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-18- 20 10 Section or Area Examined Pumps

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ✓

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	none observed	none
2.	Glory Hole	0%	none observed	none
3.	Ellis	0%	none observed	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 detected
Travelways/Trackall clearout Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 13544 (Certificate No.) — (Assistant Foreman) 32476 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

(Assistant Foreman) — 15394

(Superintendent or Assistant)

John A. Bickford 26176 Russell Dunne 15364 Scott Halstead 32567

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-18- 2010 Section or Area Examined Pumps

Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Bickford Time A.M 2:30 P.M.

Report received by Russell Dunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH_4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH_4, 20.8% O_2, 0ppm CO at time of exam
Travelways, power Centers, D-Boxes OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Dunnoe — Preshift-Mine Examiner — Certificate No. 1536-14

Countersigned T. Moore — Mine Manager—Mine Foreman — 33334

Assistant Foreman — Scott Halstead — Certificate No. 32476

Superintendent or Assistant — John A. Beckford — 37507

Dan Allen 15394 — 26176

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-18-10 20___ Section or Area Examined Pumps

Time of Examination: from 830 a.m. or p.m. to 1130 a.m. or p.m.

Was this report phoned to outside: Yes X no___

By whom SKAGGS Time ___ A.M 1100 P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	N. MAINS CH4 OB	N/O	None
2.	Gary Hole OB	N/O	none
3.	Ellis OB	NCO	none
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airmount			

Remarks: OB CH4 OBCO 20.8602

TRAVEL WAYS OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 1539A — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — 33359 — William Campbell — 1354A

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-19-10 20__ Section or Area Examined Pumps

Time of Examination: from 3:00 a.m. or p.m. to 6:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no_____

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action Taken*
1.	NORTH MAINS	NONE OBSERVED	NONE
2.	GLORY HOLE	NONE OBSERVED	NONE
3.	ELLIS	NONE OBSERVED	NONE
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Movement			

Remarks: 0% CH4 0% CO 20.8% O2. At Time of Exam Track and Travelways ok.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32476 — Willie Campbell Assistant Foreman — Certificate No. 1334-A

Countersigned [signature] Mine Manager—Mine Foreman — 33359

Assistant Foreman

Superintendent or Assistant

John A. Bickford 26176 Russell Dunne 1536-A Scott Holstead 37567

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-19- 20 10 Section or Area Examined Pumps

Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Bickford Time A.M 2:30 P.M.

Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air movement			

Remarks: 0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelways, Power Centers, D-Boxes clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnoe (Preshift-Mine Examiner) Certificate No. 1536-A

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

Assistant Foreman Scott Halstead Certificate No. 37567

Assistant Foreman John A. Bickford 26176

Superintendent or Assistant William Campbell 1354-A

[illegible] 1539A

Use Indelible
Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be
signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-19-10 2010 Section or Area Examined Pumps

Time of Examination: from 830 a.m. or (p.m.) to 1130 a.m. or (p.m.)

Was this report phoned to outside: Yes_____ no X

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	*Violation or Hazardous Condition*	*Action Taken*
1. North Mains Ch4 O2	none	none
2. Glory Hole Ch4 O2	none	none
3. Ellis Ch4 O2	none	none
4.		
5.		
6.		
7.		
8.		
9.		
10.		

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Airway			

Remarks: O2 Ch4 CO 20.8202

Traveways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 153917

[signature] Assistant Foreman — Certificate No. 32476

Countersigned [signature] Mine Manager—Mine Foreman — Certificate No. 33357

[signature] Assistant Foreman — Certificate No. 135440

_____ Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-20-10 20-10 Section or Area Examined Pumps

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes_____ no X

By whom Brought out Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	N. Mains OK	none	none
2.	Ellis OK	none	none
3.	Glory Hole OK	none	none
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airment			

Remarks: OK CH4 OK CO 20.8 OK
Trackways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 13594

[signature] Assistant Foreman — Certificate No. 13594A

Countersigned [signature] Mine Manager—Mine Foreman — 33554

[signature] Assistant Foreman — 32476

Johnny Neely Superintendent or Assistant — 33472

John R. Bickford 26176

Scott Halstead 37567

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-20 10 Section or Area Examined Pumps

Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Neely Time A.M 2:30 P.M.

Report received by John A. Bickford (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	ch4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% ch4, 0% CO & 20.8% O2 detected at time of exam

Travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford 26171
Preshift-Mine Examiner — Certificate No.

Countersigned T. Mauer 33559
Mine Manager—Mine Foreman

Assistant Foreman

Assistant Foreman — Certificate No.

Scott Halstead 37567

Johnny Neely 33472

Superintendent or Assistant

Walter Campbell 13894

Glen Wilson 15394

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-20 2010 Section or Area Examined Pumps

Time of Examination: from 8:00 a.m. or p.m. to 11:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no_____

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4%	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	none	none
2.	Glory Hole	0%	none	none
3.	Ellis	0%	none	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air			

Remarks: CH4 0%, CO 0%, O2 20.8% Detected
Travelways, D-Boxes, Pumps — OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 1530A — William Campbell Assistant Foreman — Certificate No. 1354A

Countersigned [signature] Mine Manager—Mine Foreman — 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-21 20 10 Section or Area Examined Pumps

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes ____ no X

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4%	Violation or Hazardous Condition	Action Taken
1.	North Mains	06	n/o	none
2.	Glory Hole	06	n/o	none
3.	Ellis	06	n/o	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air ment			

Remarks: CH4, 06, CO 06, O2 20.8% Detected
Travelways, D-Box, Pumps - OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 15 SA Certificate No. William Campbell Assistant Foreman 13544 Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33369 Johnny Reely 33472

Assistant Foreman Superintendent or Assistant

Johnny Bickford 26171

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-21 20 10 Section or Area Examined Pumps

Time of Examination: from 1200 a.m. or p.m. to 300 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____

By whom S. Neely Time ____ A.M 225 P.M.

Report received by John A. Buckford (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	ch4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% ch4, 0% CO & 20.8% detected at time of exam

Travelways clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Buckford (Preshift-Mine Examiner) 26176 (Certificate No.) [signature] (Assistant Foreman) 32426 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

(Assistant Foreman)

Johnny Reely (Superintendent or Assistant) 33472

William Campbell 33542

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-21-10 20__ Section or Area Examined Pumps

Time of Examination: from 8:00 a.m. or p.m. to 11:00 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement At Time of Exam			

Remarks: 0% CH4 0% CO 20.7% O2 At Time of Exam
Travelways OK At Time of Exam.

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32476

Countersigned T. Moore Mine Manager—Mine Foreman — Certificate No. 33359

Assistant Foreman

William Campbell Assistant Foreman — Certificate No. 1354-A

Johnny Neely Superintendent or Assistant — 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-22 2010 Section or Area Examined Pumps

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	none observed	none
2.	Gloryhole	0%	none observed	none
3.	Ellis	0%	none observed	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
Travelways, D-Box's, Pumps all clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 1354A (Certificate No.) [signature] (Assistant Foreman) 32476 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

Assistant Foreman

Johnny Neely (Superintendent or Assistant) 33472

Russell Gunnoe 1536-A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible
Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be
signed when made

Date of Examination 2-22- 20.10 Section or Area Examined Pumps
Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)
Was this report phoned to outside: Yes ✓ no
By whom John Neely Time A.M 2:40 P.M.
Report received by Russell Dunmore (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks:
0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelways, Power centers,

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Dunmore — Preshift-Mine Examiner — Certificate No. 1536-A
Countersigned T. Moore — Mine Manager—Mine Foreman — Certificate No. 33339
Assistant Foreman — Certificate No.
Scott Halstead — Assistant Foreman — Certificate No. 32426
Johnny Neely — Assistant Foreman — Certificate No. 37567
Superintendent or Assistant — Certificate No. 33472
Walter Cardell 1354-A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-22-10 20___ Section or Area Examined Pumps

Time of Examination: from 8:00 a.m. or p.m. to 11:30 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom Brought out Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	none observed	none
2.	Glory Hole	0%	none observed	none
3.	Ellis	0%	none observed	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected, Track/Travelways, D-Box's & Pumps all clear at Time of Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) Certificate No. 13544 [signature] (Assistant Foreman) Certificate No. 32456

Countersigned [signature] (Mine Manager—Mine Foreman) 3357

_____ (Assistant Foreman)

_____ (Superintendent or Assistant)

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____ Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-23-1 20.10 Section or Area Examined Pumps

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes ____ no —

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	none observed	none
2.	Glory Hole	0%	none observed	none
3.	Ellis	0%	none observed	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
Travelways, D-Box, Pumps Clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 1354-A (Certificate No.) ____ (Assistant Foreman) ____ (Certificate No.)

Countersigned [signature] (Mine Manager—Mine Foreman) 32476

____ (Assistant Foreman) ____

T. Mane 33359

Superintendent or Assistant

Russell Gunnoe 1536-A Scott Halstead 37567 Johnny Neely 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-23 - 2010 Section or Area Examined Pumps

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes ✓ no

By whom John Neely Time A.M 2:40 (P.M.)

Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH_4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH_4, 20.8% O_2, 0ppm CO at time of exam
Travelways, Power Centers, D-Boxes clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnoe (Preshift-Mine Examiner) 1536-A (Certificate No.) [signature] (Assistant Foreman) 32176 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33355 Scott Halstead 37567

Assistant Foreman Johnny Neely 33472

Superintendent or Assistant

[signature] 1539A [signature] 1536A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-23 2010 Section or Area Examined Pump

Time of Examination: from 900 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ✓

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	none observed	none
2.	Glory Hole	0%	none observed	none
3.	Ellis	0%	none observed	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O^2 Detected
Travelways, Pump, D-Box's all clean at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 13544 — [signature] Assistant Foreman — Certificate No. 32476

Countersigned [signature] Mine Manager—Mine Foreman — 33357

[signature] Assistant Foreman — 95594

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-24-10 2010 Section or Area Examined Pumps

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes ____ no —

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	none observed	none
2.	Glory Hole	0%	none observed	none
3.	Ellis	0%	none observed	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
Travelways, D-Box's, Pumps all clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 1354-A (Certificate No.) [signature] (Assistant Foreman) 32476 (Certificate No.)

Countersigned Terry Mane (Mine Manager—Mine Foreman) 33307 [signature] 1539A

Assistant Foreman

Superintendent or Assistant

Russell Gunnoe 1536-A
John G. Bickford 26171
Scott Halstead 37567
Johnny Neely 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-24- 2010 Section or Area Examined Pumps

Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Bickford, John Neely Time A.M 2:35 P.M

Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH_4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH_4, 20.8% O_2, 0ppm CO at time of exam

Travelways, power centers, D-Boxes clear at time of exam

[signature] 1536A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnoe (Preshift-Mine Examiner) 1536-A (Certificate No.) [signature] (Assistant Foreman) 32476 (Certificate No.)

Countersigned Terry Moore (Mine Manager—Mine Foreman) 33358 Scott Halstead 37567

(Assistant Foreman) John A. Bickford 26176

(Superintendent or Assistant) Johnny Neely 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____
Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____ Assistant Mine _____ Certificate No. _____ Mine Foreman-Mine Manager _____ Certificate No. _____ Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-24-10 20___ Section or Area Examined Pumps

Time of Examination: from 860 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no ___

By whom SKAGGS Time ___ A.M 1100 P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	North Mains CH4 O2	n/o	none
2.	Clay Hole O2	n/o	none
3.	Elk's O2	n/o	none
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airment			

Remarks: O2 CH4 O2 CO 20.8 6.02

Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 15394 Certificate No. [signature] Assistant Foreman 32476 Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-25-10 20___ Section or Area Examined Pumps

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes ___ no X

By whom Drag Wt out Time ___ A.M ___ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	N. Mains OZ Clay	None	none
2.	Clay Hole OZ	none	none
3.	Ellis OZ	none	none
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air			

Remarks: OZ Clay OZ CO 2018302

Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 15390 Certificate No. [signature] Assistant Foreman 32416 Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359

Assistant Foreman

Superintendent or Assistant

John A. Bickford 26176 Russell Gunnoe 1536-A Scott Halstead 37567

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-25- 2010 Section or Area Examined Pumps

Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Bickford Time A.M 2:30 P.M

Report received by Russell Dunmoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0 ppm CO at time of exam
Traveluays, Power Centers, D-Boxes OK at time of exam

Alan Ullman 1539A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Dunmoe (Preshift-Mine Examiner) Certificate No. 1536A

Countersigned Terry W. Moore (Mine Manager—Mine Foreman) Certificate No. 33559

Scott Halstead (Assistant Foreman) Certificate No. 34567

(Assistant Foreman)

John A. Bickford (Superintendent or Assistant) 26176

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-25-10 20___ Section or Area Examined Pumps

Time of Examination: from 800 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes_____ no X

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	N. Mains OB Cay	none	none
2.	Glory Hole OB	none	none
3.	Ellis OB	none	none
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air mont			

Remarks: OB Cay OB CO 20186 OR

Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 1534A Certificate No. _____ Assistant Foreman _____ Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33389

_____ Assistant Foreman

_____ Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-26-80 20___ Section or Area Examined Pumps

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes_____ no X

By whom Brought out Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	N. Mains OK CH4	None	none
2.	66ry Hole OK	None	none
3.	Ellis OK	None	none
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air mt			

Remarks: OK CH4 CB CO 20.8 OK

Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 1534 Certificate No. _____ Assistant Foreman _____ Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 73359

_____ Assistant Foreman _____

_____ Superintendent or Assistant _____

Russell Gunnoe 1536-A

Scott Halstead 37527

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-26 2010 Section or Area Examined Pumps

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes ____ no ____

By whom ____ Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelways, Power Centers, D-Boxes OK at time of exam

Glen Ullman 1539-A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnoe (Preshift-Mine Examiner) 1536-A (Certificate No.) — Assistant Foreman Scott Halstead — Certificate No. 37567

Countersigned T. Moore (Mine Manager—Mine Foreman) 35359 — William Campbell — 1354-A

Assistant Foreman — Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-26-10 20___ Section or Area Examined Pumps

Time of Examination: from 800 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes X no___

By whom Campbell Time ___ A.M 1100 P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	North Mains O6 CH4	none	none
2.	Glory Hole O6	none	none
3.	Ellis O6	none	none
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air moment			

Remarks: O6 CH4 O6 CO 20.8 O2

Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 1539A Certificate No. William Campbell Assistant Foreman 1354A Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 53359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-27-10 20____ Section or Area Examined Pumps

Time of Examination: from 3000 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes_____ no X

By whom Brought out Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	N. Mains CR Cby	N/O	none
2.	Cbry Hole CR	N/O	none
3.	Ellis CR	N/O	none
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Air [illegible]			

Remarks: CR Cby CR CO 2018602

Travel ways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 1539A Certificate No. William Campbell Assistant Foreman 1354A Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33359

Assistant Foreman

Superintendent or Assistant

Russell Gunnoe 1536-A

Johnny Neely 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-27- 20 10 Section or Area Examined Pumps

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes ✓ no

By whom John Neely, Scott Halstead Time A.M 2:30 (P.M.)

Report received by Russell Dunmoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	N. MAINS	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelways, Power Centers, D-Boxes OK at time of exam

Olen Allen 1534

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Dunmoe (Preshift-Mine Examiner) Certificate No. 1536-A

Countersigned T. Moore (Mine Manager—Mine Foreman) Certificate No. 35359

Assistant Foreman

Assistant Foreman: Scott Halstead Certificate No. 37567

Johnny Neely 33472

Superintendent or Assistant

William Campbell 1354-A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-27 2010 Section or Area Examined Pumps

Time of Examination: from 800 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes X no

By whom Campbell Time A.M 1100 P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None	None
2.	Glory Hole	0%		
3.	Ellis	0%		
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
Travelways, P.C's, D-Box's, all — Clear

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 15344 Certificate No. William Campbell Assistant Foreman 1354-19 Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman 33359

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-28 20 10 Section or Area Examined Pumps

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ____

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	N/O	None
2.	Glory Hole	0%	N/O	None
3.	Ellis	0%	N/O	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
Travelways, PC's, D-Box's, all - clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 1354-A (Certificate No.) [signature] (Assistant Foreman) 1941-A (Certificate No.)

Countersigned T. [signature] (Mine Manager—Mine Foreman) 3335-9

Assistant Foreman

Superintendent or Assistant

John A. Bickford 26176 Johnny Neely 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-28-10 20 Section or Area Examined Pumps

Time of Examination: from 1200 a.m. or p.m. to 300 a.m. or p.m.

Was this report phoned to outside: Yes ___ no ___

By whom J. Neely Time ___ A.M 210 P.M.

Report received by John A. Bickford 26176 (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Ch4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% Ch4 0% CO & 20.8% O2 detected at time of exam

Travelways, chargers, Power Centers & 'D' Box's clear at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By John A. Bickford 26176 Certificate No. [signature] 32476 Certificate No.

Preshift-Mine Examiner — Assistant Foreman

Countersigned T. Moore 33359

Mine Manager—Mine Foreman

Assistant Foreman

John J. Neely 33472

Superintendent or Assistant

William Campbell 135400

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 2-28 20[illegible] Section or Area Examined Pumps

Time of Examination: from 800 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes_____ no_____

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	*CH4*	*Violation or Hazardous Condition*	*Action Taken*
1.	North Mains	0%	N/O	none
2.	Glory Hole	0%	N/O	none
3.	Ellis	0%	N/O	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	*CFM*	*Location*	*CFM*
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
P.C's, D-Box's, Track/Travelways clean at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) Certificate No. 13544 — [illegible] (Assistant Foreman) Certificate No. 32476

Countersigned [illegible] (Mine Manager—Mine Foreman) 33359

_____ (Assistant Foreman) _____ _____ _____

_____ _____ _____ (Superintendent or Assistant) _____

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-1 20 10 Section or Area Examined Pumps

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes_____ no_____

By whom _____ Time _____A.M _____P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	N/O	None
2.	Glory Hole	0%	N/O	none
3.	Ellis	0%	N/O	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O^2 Detected
Travelways, D-Box's, P.C's Clearcut Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 1334-A (Certificate No.) [signature] (Assistant Foreman) 32476 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33339

_____ (Assistant Foreman) _____ _____ (Superintendent or Assistant) _____

Russell Gunnoe 1536-A Scott Halstead 37567 Johnny Neely 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-1- 2010 Section or Area Examined Pumps

Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Neely Time A.M 2:40 P.M.

Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH_4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH_4, 20.8% O_2, 0ppm CO at time of exam
Travelways, Power Centers, D-Boxes OK at time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnoe — Preshift-Mine Examiner — 1536-A Certificate No.

Countersigned T. Moore — Mine Manager—Mine Foreman — 33387

Assistant Foreman

[signature] — Assistant Foreman — 32474 Certificate No.

Scott Halstead — 37567

Johnny Neely — 33472

Superintendent or Assistant

William Campbell 1354-A

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-1- 20 CO Section or Area Examined Pumps

Time of Examination: from 800 a.m. or ~~p.m.~~ to 1100 a.m. or ~~p.m.~~

Was this report phoned to outside: Yes ✓ no

By whom J Skaggs Time A.M 1005 ~~P.M.~~

Report received by William Campbell 1354-A (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	N/O	
2.	Glory Hole	0%	N/O	
3.	Ellis	0%	N/O	
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
Travelways, D-Box's, P.C's all clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell 1354-A (Preshift-Mine Examiner, Certificate No.) [signature] (Assistant Foreman) 32476 (Certificate No.)

Countersigned T. Moore 33359 (Mine Manager—Mine Foreman)

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

_____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-2- 2010 Section or Area Examined Pumps

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ✓

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	N/O	none
2.	Glory Hole	0%	N/O	none
3.	Ellis	0%	N/O	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
Travelways, D-Box's, + P.C's all clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell (Preshift-Mine Examiner) 1354A (Certificate No.) [signature] (Assistant Foreman) 32476 (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33357

Assistant Foreman

Superintendent or Assistant

Russell Gunnar 1536A

Johnny Neely 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-2 2010 Section or Area Examined Pumps

Time of Examination: from 12:00 a.m. or p.m. to 3:00 a.m. or p.m.

Was this report phoned to outside: Yes ✓ no

By whom John Neely Time A.M 2:40 P.M.

Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelways, Power Centers, D-Boxes OK at time of exam

Dlen Wilman 1539A

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnoe (Preshift-Mine Examiner) 1536-A (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33359

Assistant Foreman

Scott Halstead (Assistant Foreman) 37567

[signature] 32476

Superintendent or Assistant

Willie Campbell 1354-A

Johnny Neely 33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

_____	_____	_____	_____	_____
Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-2-10 20___ Section or Area Examined Pumps

Time of Examination: from 800 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes X no ___

By whom Skaggs, Campbell Time ___ A.M 1100 P.M.

Report received by [signature] (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	North Mains Cky OC	none	none
2.	Gbry Hole OC	none	none
3.	Ellis OC	none	none
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Good Airment			

Remarks: OCky OC CO, 2018602

Travelways OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner 1530A Certificate No. [signature] Assistant Foreman 33476 Certificate No.

Countersigned T. Moore Mine Manager—Mine Foreman 33359 William Campbell 13547A

Assistant Foreman

Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-3 2010 Section or Area Examined Pumps

Time of Examination: from 300 a.m. or p.m. to 600 a.m. or p.m.

Was this report phoned to outside: Yes ____ no ✓

By whom Brought out Time ____ A.M ____ P.M.

Report received by ____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	Glory Hole	0%	N/O	None
2.	North Mains	0%	N/O	none
3.	Ellis	0%	N/O	none
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 0% CO, 20.8% O2 Detected
Travelways, D-Box's & Pumps all clear at Exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By William Campbell 1354A [signature] 32476
Preshift-Mine Examiner Certificate No. Assistant Foreman Certificate No.

Countersigned T. Moore 53359
Mine Manager—Mine Foreman

[signature] 1530A
Assistant Foreman

Superintendent or Assistant

John A. Bickford 26176 Scott Halstead [signature] 33472
Russell Gunnoe 15337567

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-3 2010 Section or Area Examined Pumps

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes ✓ no

By whom John Bickford, John Neely Time A.M 2:30 (P.M.)

Report received by Russell Gunnoe (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH_4	Violation or Hazardous Condition	Action Taken
1.	North Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH_4, 20.8% O_2, 0 ppm CO at time of exam
Travelways, Power Centers, D-Boxes OK At time of exam

Dan Ullman 15397

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Gunnoe (Preshift-Mine Examiner) 1536-A (Certificate No.)

Countersigned T. Moore (Mine Manager—Mine Foreman) 33389

Assistant Foreman

Scott Halstead (Assistant Foreman) 32476

John A. Bickford (Assistant Foreman) 37567

Johnny Neely (Superintendent or Assistant) 26176

33472

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-3-10 20___ Section or Area Examined Pumps

Time of Examination: from 800 a.m. or p.m. to 1100 a.m. or p.m.

Was this report phoned to outside: Yes_____ no X

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

Location	Violation or Hazardous Condition	Action Taken
1. MAINS OK	none	none
2. Gory Hole OK	none	none
3. Ellis OK	none	none
4.		
5.		
6.		
7.		
8.		
9.		
10.		

Air Measurements

Location	CFM	Location	CFM
Good Air			

Remarks: OK CH4 OK CO 20.8 O2
Travelway OK

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By _____ Preshift-Mine Examiner — Certificate No. 1534 — _____ Assistant Foreman — Certificate No. 32476

Countersigned T. Moore Mine Manager—Mine Foreman — 33359

_____ Assistant Foreman

_____ Superintendent or Assistant

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine)* _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-4-10 20___ Section or Area Examined Pump

Time of Examination: from 7:00 a.m. or p.m. to 6:20 a.m. or p.m.

Was this report phoned to outside: Yes_____ no ✓

By whom _____ Time _____ A.M _____ P.M.

Report received by _____ (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	Violation or Hazardous Condition	Action Taken
1.	NORTH MAINS	NONE OBSERVED	NONE
2.	Glory Hole	NONE OBSERVED	NONE
3.	Ellis	NONE OBSERVED	NONE
4.			
5.			
6.			
7.			
8.			
9.			
10.			

Air Measurements

Location	CFM	Location	CFM
Air Movement good AT TIME OF EXAM			

Remarks: 0% CH4 0% CO 20.8% O2 AT TIME OF EXAM.
TRAVELWAY & TRACK OK AT TIME OF EXAM

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By [signature] Preshift-Mine Examiner — Certificate No. 32476 — Assistant Foreman — Certificate No.

Countersigned [signature] Mine Manager—Mine Foreman — 33339

Assistant Foreman

Superintendent or Assistant

[signature] 15392

[signature] 15367 John A. Bickford 26176

Use Indelible Pencil or Ink

DAILY AND ONSHIFT REPORT
MINE FOREMAN OR ASSISTANT

Report shall be signed when made

Date _____ Shift _____ Area or Section _____

Violations and other Hazardous Conditions Observed and Reported

	Location	*Violation or Hazardous Condition*	*Action taken*
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			

Examinations for Methane in Working Places

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				11.			
2.				12.			
3.				13.			
4.				14.			
5.				15.			
6.				16.			
7.				17.			
8.				18.			
9.				19.			
10.				20.			

Examinations for Methane in Return Aircourses

	Location	*Time*	*Methane Content*		*Location*	*Time*	*Methane Content*
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Number of Bolts Tested _____

Number of Bolts Torqued Above Range _____ Below Range _____

If majority of bolts tested in any working place falls outside approved torque range, state what action was taken _____

Remarks (Statement as to General Conditions of Mine or Area of Mine) _____

Assistant Mine	Certificate No.	Mine Foreman-Mine Manager	Certificate No.	Superintendent or Assistant

Use Indelible Pencil or Ink

PRESHIFT-MINE EXAMINER'S REPORT

Report shall be signed when made

Date of Examination 3-4 2010 Section or Area Examined Pumps

Time of Examination: from 12:00 a.m. or (p.m.) to 3:00 a.m. or (p.m.)

Was this report phoned to outside: Yes ✓ no

By whom John Bickford Time A.M 2:30 (P.M.)

Report received by Russell Dunmore (Signed)

Violations and other Hazardous Conditions Observed and Reported

	Location	CH4	Violation or Hazardous Condition	Action Taken
1.	N. Mains	0%	None Observed	None
2.	Glory Hole	0%	None Observed	None
3.	Ellis	0%	None Observed	None
4.				
5.				
6.				
7.				
8.				
9.				
10.				

Air Measurements

Location	CFM	Location	CFM
Good Air Movement			

Remarks: 0% CH4, 20.8% O2, 0ppm CO at time of exam
Travelways, Power Boxes, D-Boxes OK At time of exam

This is to certify that: (a) This section of the mine was properly examined by me, (b) all violations of the Federal Coal Mine Health and Safety Act of 1969 and other unsatisfactory conditions and practices observed by me are listed in this report.

Signed By Russell Dunmore Preshift-Mine Examiner — Certificate No. 1536-A

Countersigned T. Moore Mine Manager—Mine Foreman — Certificate No. 33339

Assistant Foreman — Certificate No.

Assistant Foreman Scott Halstead — Certificate No. 32476

Superintendent or Assistant John A. Bickford — Certificate No. 37567

Certificate No. 26171