From: Sell, Robert [mailto:Robert.Sell@draeger.com]
Posted At: Thursday, January 08, 2009 1:22 PM
Posted To: Microsoft Office Outlook Embedded Message
Conversation: Federal Register/Vol. 73, No. 244 Dated Thursday, December 18, 2008: Comment on Program Policy Letter
Subject: Federal Register/Vol. 73, No. 244 Dated Thursday, December 18, 2008: Comment on Program Policy Letter

To Whom It May Concern:

Draeger Safety has reviewed the Program Policy Letter for Wireless Communications and Electronic Tracking Systems Guidance and we are providing the following comment for consideration as a modification to the proposed PPL:

Page 77071

2. Coverage Area
b. The system also generally should provide continuous coverage along the escapeways and a coverage zone both inby and outby strategic areas of the
mine, such as belt drives and transfer points, power centers, loading points, refuge alternatives, SCSR caches and other areas identified by the District
Manager. While a coverage zone of 200 feet (line of sight) inby and 200 feet (line of sight) outby strategic areas normally should be adequate, the District Manager may require longer or shorter distances given circumstances specific to the mine.

Substantiation: Radio communications are hampered by obstructions between the personnel operating the radios and the ideal situation is that there are no obstructions which would hinder the signal.

If there should be any questions concerning our comment, please do not hesitate to contact me.

Regards

Bob Sell

Sr. Project Engineer - Protection

Dräger Safety, Inc.
101 Technology Drive
Pittsburgh, PA 15275
Tel: (412) 788-5685
Fax: (412) 787-2207
Mobile: (412) 996-9344
Robert.Sell@Draeger.com
www.draeger.com

Dräger. Technology for Life®

This communication contains confidential information. If you are not the intended recipient please return this email to the sender and delete it from your records.

Diese Nachricht enthält vertrauliche Informationen! Sollten Sie nicht der beabsichtigte Empfänger dieser E-mail sein, senden Sie bitte diese an den Absender zurück und löschen Sie die E-mail aus Ihrem System.

COMM-12