Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

PR001 10/27/2026

1. Accident Type	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
F - Fatal Injury	09 - Handling Material	10/22/2026 6:07 PM	10/22/2026 06:07 PM	FAI-F03DCE8-1

6. Mine Information
a) Mining Company Name: Mountain Cement Company LLC
b) Mine Name: Mountain Cement Company
c) Parent of Mining Company: Eagle Materials Inc

7. Mine Location Information			8. Mine ID Number	9. Union
a) City	b) County	c) State		
LARAMIE	Albany	WY	48-00007	No

10. Primary Mineral Mined	11. Number of Employees				
	a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
Hydraulic Cement	127		24	95	8

12. Contractor Name	13. Contractor Union	14. Contractor ID Number
Irondale Industrial Contractors, Inc	No	7NM

15. Contractor Address			
a) City	b) County	c) State	d) Zip Code
Birmingham		AL	35210

16. Number of Contractor Employees				
a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
144			144	

17. Number of Persons in Mine at Time of Accident		18. Number of Persons Unaccounted for	
a) Mine Employees	b) Contractor Employees	a) Mine Employees	b) Contractor Employees
118	398	0	

19. Accident Location	20. Mining Height
30 - Mill/Prep Plant	0 Feet 0 Inches

21. Nonfatal Injuries	22. Fatal Injuries
0	1

23. Victims Information

a) First Name	a) MI	a) Last Name	b) Age	c) Regular Job Title	d) Activity at Time of Accident	Employee
Ricardo		Padilla	47	Millwright	Positioning fan shrouds for assembly	Contractor Employee

24. Mining Experience

a) Total Experience	b) Experience at the Mine	c) Experience at the Activity at the Time of the Accident	d) Experience with Contractor
2 Years 4 Weeks 0 Days	1 Years 12 Weeks 3 Days	0 Years 14 Weeks 3 Days	0 Years 14 Weeks 3

25. Autopsy Performed	If Yes, Location
Yes	

26. Mine Telephone No.
(307) 745-4879

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)
A contractor died after he was struck by a fan shroud.

The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding thecause of the accident.

28. Equipment Manufacturer	29. Model

30. District	32. Field Office	33. Event Number
M6000 - Denver District	M6642 - Denver CO Field Office	F03DCE8

34. Accident Investigator

First Name	MI	Last Name
Christopher		Bryant

35. MSHA Person Notified

First Name	MI	Last Name	Date/Time Notified
Dennis	J	Bellfi	10/22/2026 6:23 PM

36. Type of Report	37. Name of Preparer	
	Full Name	Date Prepared
Initial	Michael Tefertiller	10/26/2026

38. Reason for Amendment