

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 11/16/2023

1. Accident Type F - Fatal Injury		2. Accident Classification 17 - Machinery		3. Date/Time of Accident 11/13/2023 1:20 AM		4. Date/Time of Death 11/13/2023 5:11 AM		5. Fatal Case No FAI-6948601-1		
6. Mine Information										
a) Mining Company Name:		Stillwater Mining Company								
b) Mine Name:		STILLWATER MINE								
c) Parent of Mining Company:		Sibanye Stillwater Limited								
7. Mine Location Information					8. Mine ID Number		9. Union			
a) City Columbus		b) County Stillwater		c) State MT	24-01490		Yes			
10. Primary Mineral Mined Platinum Group Ore Mining				11. Number of Employees		c) Open Pit/Quarry		d) Mill/Prep Plant	e) Other	
				a) Total 1090		b) Underground 938		0	44	108
12. Contractor Name Moran Mining Usa Inc						13. Contractor Union No		14. Contractor ID Number 4MC		
15. Contractor Address					d) Zip Code					
a) City Nye		b) County Stillwater		c) State MT	59061					
16. Number of Contractor Employees					c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other	
a) Total 182		b) Underground 118		0		0		64		
17. Number of Persons in Mine at Time of Accident				18. Number of Persons Unaccounted for						
a) Mine Employees 183		b) Contractor Employees 13		a) Mine Employees 0		b) Contractor Employees 0				
19. Accident Location 01 - Underground							20. Mining Height 14 Feet 1 Inches			
21. Nonfatal Injuries 0		22. Fatal Injuries 1								
23. Victims Information										
Noah J Dinger										
a) First Name Noah		a) MI J	a) Last Name Dinger		b) Age 24	c) Regular Job Title Miner		d) Activity at Time of Accident Bolting	Employee Contractor Employee	
24. Mining Experience										
a) Total Experience 4 Years 6 Weeks 0 Days		b) Experience at the Mine 2 Years 46 Weeks 6 Days			c) Experience at the Activity at the Time of the Accident 0 Years 17 Weeks 0 Days			d) Experience with Contractor 2 Years 46 Weeks 6 Days		
25. Autopsy Performed No					If Yes, Location					
26. Mine Telephone No. (406) 373-8700 x 4										
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) The miner died when he was entangled in the drill steel of roof bolting machine. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>										
28. Equipment Manufacturer Komatsu					29. Model ZB21 Bolter					
30. District M6000 - Denver District					32. Field Office M6821 - Helena MT Field Office			33. Event Number 6948601		
34. Accident Investigator		MI	Last Name							
First Name Clayton		Johnson								
35. MSHA Person Notified					Date/Time Notified					
First Name Lee		MI	Last Name Hughes		11/13/2023 4:06 AM					
36. Type of Report Initial		37. Name of Preparer			Date Prepared					
		Full Name Lee A. Hughes			11/14/2023					
38. Reason for Amendment										