

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 06/14/2023

1. Accident Type F - Fatal Injury		2. Accident Classification 17 - Machinery		3. Date/Time of Accident 06/01/2023 12:47 PM		4. Date/Time of Death 06/01/2023 1:02 PM		5. Fatal Case No FAI-6932417-1			
6. Mine Information											
a) Mining Company Name:		Alleyton Resource Company, LLC.									
b) Mine Name:		Hockley Plant									
c) Parent of Mining Company:		Summit Materials LLC									
7. Mine Location Information			8. Mine ID Number			9. Union					
a) City		b) County		c) State		41-03491			No		
RICHMOND		Harris		TX							
10. Primary Mineral Mined					11. Number of Employees						
Construction Sand & Gravel Mining, N.E.C.					a) Total		b) Underground		c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
					3					3	
12. Contractor Name						13. Contractor Union		14. Contractor ID Number			
15. Contractor Address											
a) City			b) County			c) State			d) Zip Code		
16. Number of Contractor Employees											
a) Total		b) Underground			c) Open Pit/Quarry			d) Mill/Prep Plant		e) Other	
17. Number of Persons in Mine at Time of Accident					18. Number of Persons Unaccounted for						
a) Mine Employees		b) Contractor Employees			a) Mine Employees		b) Contractor Employees				
3					0						
19. Accident Location								20. Mining Height			
00 - Other Facility staging area								30 Feet 0 Inches			
21. Nonfatal Injuries				22. Fatal Injuries							
				1							
23. Victims Information											
Ricardo R Martinez											
a) First Name		a) MI	a) Last Name		b) Age	c) Regular Job Title		d) Activity at Time of Accident		Employee	
Ricardo		R	Martinez		61	Customer Truck Driver		Maintenance on Truck		Other Employee	
24. Mining Experience				b) Experience at the Mine				c) Experience at the Activity at the Time of the Accident		d) Experience with Contractor	
a) Total Experience		0 Years 4 Weeks 0 Days		0 Years 4 Weeks 0 Days		20 Years 0 Weeks 0 Days		Years		Weeks Days	
25. Autopsy Performed			If Yes, Location								
No											
26. Mine Telephone No.											
(936) 372-5988											
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)											
A customer truck driver died when he was struck by a component of his truck s air bag height/ride suspension system while performing maintenance.											
<i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>											
28. Equipment Manufacturer					29. Model						
Kenworth					T800 quad axel						
30. District					32. Field Office			33. Event Number			
M5000 - Dallas District					M5651 - Broussard LA Field Office			6932417			
34. Accident Investigator			MI			Last Name					
First Name		Homer		Pricer							
35. MSHA Person Notified			MI			Date/Time Notified					
First Name		Steven		Oates		06/01/2023 2:04 PM					
36. Type of Report		37. Name of Preparer			Date Prepared						
Initial		Full Name			06/01/2023						
		Homer Pricer									
38. Reason for Amendment											