




MSHA's Accident Prevention Program Safety Idea

Safety and
Health are
Values!

The Middle of the Remote Control Continuous Miner Is Not a Safe Place



The middle of the remote control continuous miner (pivot point) is not a safe place from which to reposition or tram the machine during a place change.

The pivot point moves as the machine moves and may cause you to be in a position to be crushed if the miner suddenly turns.

Never operate the continuous miner when anyone is in the Red Zone

Although some roof control plans prohibit tramping the continuous miner from within the turning radius of the machine, it is important for You to always remember to [Stay Out of the Red Zone!](#)

If you have a tip you would like to pass on, you can e-mail it to
zzMSHA-MinersTips@dol.gov.

If your tip is selected, you will receive credit in this space.

Issued:	03/15/2005
Tag #	AP2005