



Section I--Violation Data

1. Date Mo Da Yr 12/06/2011	2. Time (24 Hr. Clock) 0800	3. Citation/ Order Number 4900546
4. Served To Berman Cornett (Safety Director)	5. Operator Performance Coal Company, et al.	
6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436	(Contractor)
8. Condition or Practice		8a. Written Notice (103g) <input type="checkbox"/>

Improper overcurrent protection is being provided for the air compressor unit that was found loaded on the shield hauler (S# 636-1010) on the Headgate #21 area (inby spad 22637) of the Longwall section. The overloads for the 75 h.p. compressor are FH93-A and are approximately 25% larger than needed. The 4.6 amp blower motor does not have proper protection. 15 amp fuses are being used and cannot be used for the 480 volt 3 phase motor. Also a 53.9 amp (type H2017B) cutler hammer overload is being used in conjunction with the 15 amp fuses. These conditions were observed during an ongoing investigation of a fatal accident that occurred on April 5, 2010.

This citation is being issued to the following entities as a unitary operator:
 Performance Coal Company, Massey Coal Services, Inc., A.T. Massey
 See Continuation Form (MSHA Form 7000-3a)

9. Violation	A. Health <input type="checkbox"/> Safety <input checked="" type="checkbox"/> Other <input type="checkbox"/>	B. Section of Act	C. Part/Section of Title 30 CFR 75.518
--------------	--	----------------------	--

Section II--Inspector's Evaluation

10. Gravity:

A. Injury or Illness (has) (is): No Likelihood Unlikely Reasonably Likely Highly Likely Occurred

B. Injury or illness could reasonably be expected to be: No Lost Workdays Lost Workdays Or Restricted Duty Permanently Disabling Fatal

C. Significant and Substantial: Yes No D. Number of Persons Affected: 001

11. Negligence (check one) A. None B. Low C. Moderate D. High E. Reckless Disregard

12. Type of Action 104(a) 13. Type of Issuance (check one) Citation Order Safeguard Written Notice

14. Initial Action A. Citation <input type="checkbox"/> B. Order <input type="checkbox"/> C. Safeguard <input type="checkbox"/> D. Written Notice <input type="checkbox"/>	E. Citation/ Order Number	F. Dated Mo Da Yr
---	------------------------------	----------------------

15. Area or Equipment

16. Termination Due A. Date Mo Da Yr 01/05/2012	B. Time (24 Hr. Clock) 0800
--	--------------------------------

Section III--Termination Action

17. Action to Terminate

18. Terminated A. Date Mo Da Yr	B. Time (24 Hr. Clock)
---------------------------------------	------------------------

Section IV--Automated System Data

19. Type of Inspection (activity code) E16	20. Event Number 4440348	21. Primary or Mill
22. Signature Keith McElroy		23. AR Number 24153

MSHA Form 7000-3, Apr 08 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

Mine Citation/Order
Continuation

U.S. Department of Labor
Mine Safety and Health Administration



Section I--Subsequent Action/Continuation Data

1. Subsequent Action 1a. Continuation <input type="checkbox"/> <input checked="" type="checkbox"/>	2. Dated (Original Issue) Mo Da Yr 12/06/2011	3. Citation/Order Number 4900546
4. Served To Berman Cornett (Safety Director)	5. Operator Performance Coal Company, et al.	
6. Mine UPPER BIG BRANCH MINE-SOUTH	7. Mine ID 46-08436 (Contractor)	

Section II--Justification for Action

Continuation of 8. Condition or Practice
Coal Company, Inc., and Massey Energy Company.

See Continuation Form

Section III--Subsequent Action Taken

8. Extended To	A. Date Mo Da Yr	B. Time (24 Hr. Clock)	<input type="checkbox"/> C. Vacated	<input type="checkbox"/> D. Terminated	<input type="checkbox"/> E. Modified
----------------	------------------	------------------------	-------------------------------------	--	--------------------------------------

Section IV--Inspection Data

9. Type of Inspection E16	10. Event Number 4440348		
11. Signature Keith McElroy	AR Number 24153	12. Date Mo Da Yr 12/06/2011	13. Time (24 Hr. Clock) 0800