

Started 4-1-10

EXAMINATION OF BELT CONVEYORS

COMPANY Performance Coal Co
MINE UBB South Belts
LOCATION Naoma Ral WV
 Post Office County State

Re-order #9980 from

Quality Forms Printing
P.O. Box 861
Sophia, WV 25921
(304) 252-1363

EXAMINATION OF BELT CONVEYORS

the shift

DATE 4-1-10 SHIFT Day TIME OF EXAMINATION: FROM 1:00 OR P.M. TO 4:00 OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
#1 South 0% CH4	Needs some spot cleaning, Needs adding dusting 22-40Bk	Reported	JB
#1 North 0%	Needs dusted 3Bk - 20Bk, Needs wire mesh out down 36Bk	Reported	JB/LS
#2 North 0%	Needs spot dusting & cleaning	Reported	LS
#3 North 0%	Needs spot dusting, wet in places	Reported	LS
3 rec #1 & #2	out of service		
LBB 0%	pumps, vacuum lines, track ok at exam	Reported	LS/HT
Mainline 0%	pumps, vacuum lines, track, D-bow ok at exam	Reported	LS/HT
	0% CH4 0% CO 20.8% O ₂ detected track, travelways, choppers, power lines safe at exam Visual check of CO monitors ok at exam See record for notes		

SIGNED BY: Tom Bayne Belt Examiner Certificate No. 32261 Jay Stewart 39199 Harley Taylor 37002

COUNTERSIGNED BY: Bob [unclear] Mine Foreman Certificate No. 29734 Philetown 2961 Superintendent Certificate No. _____

EXAMINATION OF BELT CONVEYORS

ON SHIFT

DATE 4-1-10

SHIFT Day

TIME OF EXAMINATION:

FROM 6:00

A.M. OR ~~P.M.~~ TO 4:00

4:00

~~OR~~ P.M.

BELT CONVEYOR EXAMINED	Action Taken	EXAMINER
#1 South	cleaned & greased at tail	JB
#1 North	run dusted at head	JB
#2 North		
#3 North		
LS	Refuge chamber & phone ok at span at 97 link.	

SIGNED BY:

Tom Berger
Belt Examiner

32261

Certificate No.

COUNTERSIGNED BY:

Paul J. [unclear]
Mine Foreman

28738

Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

On Shift

4-1-10

SHIFT Zmr

TIME OF EXAMINATION:

FROM 8:00

A.M. OR P.M. TO

9:40

A.M. OR P.M.

BELT CONVEYOR EXAMINED

Action TAKEN

EXAMINER

Refuse chamber 97 rtk. clean & Phone at exam.

SIGNED BY:

[Signature]
Belt Examiner

2964

Certificate No.

COUNTERSIGNED BY:

[Signature]
Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

*Wul
4-5-10*

DATE 4-2-10 SHIFT Owl TIME OF EXAMINATION: FROM 110 A.M. OR P.M. TO 240 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER	
#1 south O ₂ CH ₄				
#2 North O ₂ CH ₄		Reported	TP BB	
#2 North O ₂ CH ₄		No HAZARDS FOUND CLEAR AT EXAM.		
#3 North O ₂ CH ₄				
#3 sec. #1+2	Out of Service No Power No Reshift	Reported	TP	
	Refuse Chamber's Phone at 97BK working ok at time of exam		BB	
	Track: Transluxy clear at time of exam			

SIGNED BY:

Ray Peterson 2/11/11
Eric Best
Belt Examiner

37079
Certificate No.

COUNTERSIGNED BY:

T. Moore
Mine Foreman

33357
Certificate No.

Superintendent

Jay Stewart 39199

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 4-2-10 SHIFT Day TIME OF EXAMINATION: FROM 12 A.M. OR PM TO 3 A.M. OR PM

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South	Belts Idle Powercenters, D-Boxes Clear At exam	Reported	LS/HT
1 North			
2 North			
3 North			
3 Section #1	NO Power, NO Preshift	Reported	LS
#2			
LBB	Powercenters, Pumps clear at exam	Reported	LS
Mainline	Powercenters, D-Boxes, Pumps Clear At exam	Reported	LS
	Track, Trawlway clear At Exam		

SIGNED BY: Jerry Stewart 39199
Belt Examiner Certificate No.

Harley Taylor 37002
Superintendent Certificate No.

COUNTERSIGNED BY: Rob Zata 28236
Mine Foreman Certificate No.

Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

Preshift

DATE 4-2-10 SHIFT EVE TIME OF EXAMINATION: FROM 800 A.M. OR PM TO 945 A.M. OR PM

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South ^{CH4} 0%	Track power center, D-Boxes: pumps on all belts clear at time of exam All Belts idle	Reported	BB
1 North 0%			
2 North 0%			
3 North 0%			
3 Section #1 Belt ^{CH4} 2 Belt 0%	NO Power NO Preshift	Reported	BB
2 BB ^{CH4} 0%	Track, power center, pumps OK at time of exam	Reported	BB
Mainline ^{CH4} 0%	Track, power center, D-Boxes pumps OK at time of exam	Reported	BB

SIGNED BY: *Bernie Bradet* 37074
Belt Examiner Certificate No.

COUNTERSIGNED BY: *Resk Foster* 28736
Mine Foreman Certificate No. Superintendent _____ Certificate No. _____

EXAMINATION OF BELT CONVEYORS

Preshift

DATE *4-3-10*

SHIFT *OWL*

TIME OF EXAMINATION: FROM *300*

A.M. OR P.M. TO *450*

A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
<i>1 South CH₄ 0%</i>	<i>Track powercentas D-Bayer pump or all belts all clear at time of exam</i>	<i>Reported</i>	<i>BB</i>
<i>1 North 0%</i>			
<i>2 North 0%</i>			
<i>3 North 0%</i>			
<i>3 Section #1 CH₄ 0%</i>	<i>No Power Not Preshifted</i>	<i>Reported</i>	<i>BB</i>
<i>#2</i>			
<i>LBB CH₄ 0%</i>	<i>Track, powercentas, pumps ok at time of exam</i>	<i>Reported</i>	<i>BB</i>
<i>Mainline CH₄ 0%</i>	<i>Track powercentas D-Bayer pumps all clear at time of exam</i>	<i>Reported</i>	<i>BB</i>
	<i>Little water on track 3BR's inside drift</i>	<i>Reported</i>	<i>BB</i>

SIGNED BY: *Bruce Buntin*
Belt Examiner

37074
Certificate No.

COUNTERSIGNED BY: *Reed Estlin*
Mine Foreman

28734
Certificate No.

Lucy Stewart 39199

Superintendent _____ Certificate No. _____

EXAMINATION OF BELT CONVEYORS

P.M. DATE 4-3-10 SHIFT OWL TIME OF EXAMINATION: FROM 300 A.M. OR P.M. TO 450 A.M. OR P.M.

Belt Conveyor Examined	Violations and other hazardous conditions observed	Action Taken	Examiner
<u>3 North</u>	<u>Bottom Roller Hanging down Hanger broken</u>	<u>Dropped roller down</u>	<u>BB</u>
<u>Main line</u>	<u>little water on track, 3B's inside drift</u>	<u>got pump off LBB & put pump beside water</u>	<u>BB</u>
	<u>Refuse Chomler 97B's phone</u>	<u>Reported</u>	<u>BB</u>
	<u>& at time of exam 590 CH4</u>		

SIGNED BY: Ernie Buelter Certificate No. 37074
Belt Examiner

COUNTERSIGNED BY: Reed Foster Certificate No. 28736
Mine Foreman Superintendent Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 4-3-10 SHIFT Day TIME OF EXAMINATION: FROM 12 A.M. OR (P.M.) TO 3 A.M. OR (P.M.)

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South	Belts Idle, Powercenters, D-Boxes Clear At exam	Reported	LS
1 North			
2 North			
3 North			
3 Section #1	Out of Service	Reported	LS
#2			
LBB	Powerbox, Pumps clear At exam	Reported	LS HT
Mainline	Powercenters, Pumps, D-Boxes clear At exam	Reported	LS HT
	Water on track 3 BKs inside Drift		
	0% CH ₄ , 0% CO, 20.8% O ₂		
	Track, Trayload clear At exam		

SIGNED BY: Joey Stewart
Belt Examiner

39199
Certificate No.

Harley Taylor 37002

COUNTERSIGNED BY: Rick Foster
Mine Foreman

28736
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

DATE 4-3-10 SHIFT EVE TIME OF EXAMINATION: FROM 600 A.M. OR P.M. TO 945 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South ^{CH4} 0%	Powerlooper - P. Boyer in Track all clear at time of exam Belt in place	Reported	BB
1 North 0%			
2 North 0%			
3 North 0%			
3 #1 #2	Out of Service	Reported	BB
LBB 0%	Powerlooper Pump Track all clear at time of exam	Reported	BB
Mainline 0%	Powercenter Pump D. Boxer Track, & Transferway clear at time of exam Water on track 38" inside Drift	Reported	BB
CH4 0% COO 0% O ₂ 20.8%			

SIGNED BY:

Gene Beal
Belt Examiner

37074
Certificate No.

COUNTERSIGNED BY:

Rich Foster
Mine Foreman

28736
Certificate No.

Superintendent

Certificate No.

EXAMINATION OF BELT CONVEYORS

Pre-shift

DATE 4-13-10 SHIFT EVE TIME OF EXAMINATION: FROM 800 A.M. OR P.M. TO 1000 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South CH ₄ 0%	Powercenters - D-Boxes, Track All clear At exam	None	BB
1 North 0%		None	BB
2 North 0%		None	BB
3 North 0%		None	BB
3 Section 1 & 2		OUT OF service no power	None
Mainline 0%	P.C.'S, Pumps, D-Boxes, Track, Travelways clear At exam	None	TP
LBB 0%	P.C.'S, Pumps, Track, clear At exam	None	TP
0% CH ₄ , 20.8% O ₂ , 0ppm C.O. Detected			

SIGNED BY:

Bruce Brubaker
Belt Examiner

37074
Certificate No.

Ray Peterson 29617

COUNTERSIGNED BY:

Rick Foster
Mine Foreman

28236
Certificate No.

Superintendent

Certificate No.

MOC/AL 1947-A

EXAMINATION OF BELT CONVEYORS

Pre-Shift

DATE 4-5-10 SHIFT OWL TIME OF EXAMINATION: FROM 300 A.M. OR P.M. TO 600 A.M. OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZAROUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South ^{CH4}	0% need some spot cleaning need add. Rock Dust 22-40 ftk.	Rep.	TP
1 North ^{0%CH4}	3-20 ftk. need dusted	Rep.	TP
2 North ^{0%CH4}	needs add dusting spot needs spot cleaning	Repairs	BB
3 North ^{0%CH4}	needs dusting & spot cleaning	Repairs	BB
3 Section 1 2	Belts idle no power	Rep.	BB
Mainline ^{0%CH4}	Powercentric Pump, D-Boxer, Truck, Traculwump clear at exam.	none	TP BB
LBB ^{0%CH4}	Powercentric Pump, Truck clear at exam.	none	TP BB
	^{0%CH4} 20802 COO% Visual on CO's clear at exam		

SIGNED BY: Bruce Smith 32074 Rory Peterson 29611
Belt Examiner Certificate No.

COUNTERSIGNED BY: Rock Foster 28736
Mine Foreman Certificate No.
Joan Stewart 39199

Superintendent Certificate No.
George Curry 27429

EXAMINATION OF BELT CONVEYORS

ON-SHAFT

DATE 4-5-10 SHIFT Oad TIME OF EXAMINATION: FROM 12:04 A.M. OR P.M. TO 2:30 A.M. OR P.M.

BELT CONVEYOR EXAMINED	Action Taken		EXAMINER
1 south	Bottom roller at V plow - leaving out -	changed roller	TP BB
2 North	cleaned on V-plows on 2N tail	cleaned on tail	TP BB
	Water on track 3 Bk. inside		
	Refuse Chandra 978t iPhone clear at exam.		
	Tracks transways clear at exam		

SIGNED BY: [Signature] 3754
Belt Examiner 29611 Certificate No.

COUNTERSIGNED BY: [Signature]
Mine Foreman 28736 Certificate No. Superintendent _____ Certificate No. _____

EXAMINATION OF BELT CONVEYORS

Pre shift

DATE 4-5-10 SHIFT Day TIME OF EXAMINATION: FROM 1:00 ~~A.M.~~ OR P.M. TO 4:00 ~~A.M.~~ OR P.M.

BELT CONVEYOR EXAMINED	VIOLATIONS AND OTHER HAZARDOUS CONDITIONS OBSERVED	ACTION TAKEN	EXAMINER
1 South CH4 D%	Needs some spot cleaning, Needs add dusting 22-40 R/L	Reported	JB
1 North D%	3-20 sub needs add dusting, walkways need spot cleaning	Reported	JB/LS
2 North D%	Needs Add Dusting, Spot cleaned	Reported	LS
3 North D%	Needs Dusted and Spot Cleaned. Tail needs Add cleaning	Reported	LS
3 sec 1 2	3 Belts idle (No power)		
Mainline	PC's, pumps, boxes, tracks, travelways clean at exam	none	DC
LBB	PC's - pumps clean at exam D% CH4 2% CO, 20.8% O2 detected, track, travelways, refer at exam Visual check of all mounted on at exam	none	DC TH

SIGNED BY: Tom Sawyer Belt Examiner Certificate No. 32261

Don Williams 1659-A
George Curry 27429
Jerry Davis 39127

COUNTERSIGNED BY: _____ Mine Foreman Certificate No. _____ Superintendent Certificate No. _____

EXAMINATION OF BELT CONVEYORS

ON shift

M. DATE 4-5-10 SHIFT Day TIME OF EXAMINATION: FROM 6:00 A.M. OR 4:00 P.M.

BELT CONVEYOR EXAMINED	Action Taken	EXAMINER
1 South	gilled from dust at tail, ^{hand} dusted behind startup - 2 Bch shuffled 45-46 Bch	JB
1 North	dusted around head area	JB
2 North	Landed from TAIL ROLLER AND FROM UFLOW TO	
3 North	15 ft out by, gilled from dust at head JB/LS	TW
3 Sec 1 2		
	Refuge chamber at 97 BIC OK at exam mine phone in working order	

SIGNED BY: George Curry Belt Examiner Certificate No. 27429

COUNTERSIGNED BY: _____ Mine Foreman Certificate No. _____ Superintendent Certificate No. _____

Jim H. Allen 1659-A
Jim Bauer 32261
Joer Ward 39199