


Remote Control Best Practices

The Middle of the Remote Control Continuous Miner Is Not A Safe Place to Tram



- The middle of the remote control continuous miner (pivot point) is not a safe place from which to reposition or tram the machine during a place change.
- The pivot point moves as the machine moves and may cause you to be in a position to be crushed if the miner suddenly turns.



MSHA challenges you to look closely at the operation of the remote control continuous miner the next time you are on the section