


Remote Control Best Practices

Tramming While Positioned Within The Turning Radius Of The Remote Control Continuous Miner Can Be Fatal



Tram the continuous mining machine from a safe location to avoid pinch points