




## Remote Control Continuous Mining Machine Safety Alert

***“NEVER ENTER THE RED ZONE”***



### *Best Practices*

- **Conduct training and assure that remote control units have safeguards against accidental tram activation.**
- **Ensure emergency stop and operational controls are functional before mining or tramming machine.**
- **De-energize electrical power to machine before servicing or setting bits. De-energize pump motor when making methane checks, extending ventilation devices, or positioning trailing cables.**
- **Use remote control units equipped with the design safeguards recommended in MSHA Program Information Bulletin No. P03-03, “Recommended Design Safeguards for Permissible Remote Controlled Mining Machines.”**

