

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Powered Haulage		3. Date/Time of Accident 09/16/2013 09:25 AM		4. Date/Time of Death 09/16/2013 09:25 AM		5. Fatal Case No 11				
6. Mine Information :												
a) Mining Company Name Con-Agg of MO, LLC			b) Mine Name Huntsville Quarry			c) Parent of Mining Company Summit Materials LLC						
7. Mine Location :		a) City Huntsville		b) County Randolph		c) State MO		8. Mine ID Number: 23-02004		9. Union: NO		
10. Primary Mineral Mined: CRUSHED & BROKEN LIMESTONE M			11. Number of Mine Employees:		a) Total 13		b) Underground 11		c) Open Pit/Quarry 2			
12. Contractor Name:						13. Union		14. Contractor ID Number:				
15. Contractor Address:												
a) City			b) County			c) State		d) Zip Code				
16. Number of Contractor Employees:												
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other				
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:							
a) Mine Employees: 13		b) Contractor Employees:			a) Mine Employees:		b) Contractor Employees:					
19) Location of Accident									20. Mining Height:			
<input type="checkbox"/> 01-Underground	<input checked="" type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)	Feet	Inches	<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility		
21. Nonfatal Injuries:			22. Fatal Injuries: 1									
23. Victim Information :												
a) Name David A. Gully					b) Age 58							
c) Regular Job Title: Truck driver					d) Activity at Time of Accident: Driving haul truck							
24. Experience :												
Years	Weeks	Days	Years	Weeks	Days	Years	Weeks	Days	Years	Weeks	Days	
a) Total:	25	42	3	b) at the mine:	25	42	3	c) at activity (23d):	14	16	0	d) with Contractor
25. Autopsy Performed: If Yes, Location YES Columbia Missouri								26. Mine Telephone No.: (660) 277-4419				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
After driving a loaded haul truck out of the quarry, the victim traveled through a berm and over a highwall.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar			29. Model: 773B		
30. District: M5000 South Central		32. Field Office: Rolla-Noth MO			33. Event Number: 6608678
34. Accident Investigator: Robert D. Seelke			35. MSHA Person Notified: Stephen Brill		Date 09/16/2013
Time 09:35 A	36. Type of Report: Initial				
37. Name of Preparer and Date Prepared: Mike Harcher <i>MH</i>			Date 09/17/2013		
38. Reason For Amendment:					