PR001 16-Sep-14

Preliminary Report of Accident

U.S. Department of Labor

Mine Safety and Health Administration

-//

1. Accident Type:		2. Accide	nt Classificat	tion		3. Date/Time of Accident 4. Date/			ime of De	5. Fatal Case No				
Fatal Injury		Machir	nery			09/15/20	14 12:4	40 PM	09/1	5/2014	02:04 PM		10	
6. Mine Information	ı :													
a) Mining Company Name				b) Mine Name				c)	f Mining Company					
Black Warrior Min	nerals In	С		Manchester N	/line			R	oger W	Perry; R	ance Perry	; Leah F	erry-H	laynie
7. Mine Location : a) City			ity	b) (c) State	c) State 8.			. Mine ID Number:			9. Union:		
Jasper				Walker	AL	AL			01-01362			NO		
10. Primary Minera	l Mined:		11	. Number of Mine	e a) Total	b) Underground	c) O	pen Pit/(Quarry	d) M	ill/Prep Plan	t e) Other	,
BITUMINOUS				Employees:	36	0			36		0		С	<u> </u>
12. Contractor Nam	e:							13. Uni	On		14. Contra	ctor ID Nu	ımber:	
15. Contractor Addr	ress:	9) City			b) County			c) Sta	ite	d) Z	ip Code		
16. Number of Contr	ractor Em	ployees:	a) T	otal b	Underground	c) Ope	en Pit/Qu	arry		d) Mill/Pre	p Plant	e) Oth	er	
					. <u>.</u> .									
17. Number of Perso	ons in Min				0	18. Number								0
a) Mine Employees:		28	b) Co	ntractor Employe	es: 0	a) Mine E	mployees	:	0	ь) Со	ntractor Em		ining H	0
19) Location of Accident			X 03-Op	en Pit	07-Advan	ce Mining	30-M	ill/Prep	Plant	Othe	er (specify)	Fee		:hes
02-Surface at U		nd	_	edge Mining	08-Retrea	t Mining	 99-0	ffice Fac	ility				2	4
21. Nonfatal Injuries			22. Fatal In	iuries:	T				· · · · · ·					
	••	0		1										
23. Victim Informati	ion :		a) Na Barry N. D			b) Age 53						-		
c) Regular Job Title:	•		Daily N. D		y at Time of Acc						X M	line Emp	lovee	
Bulldoze		or		,	,	Leveling B	ench				(25)		10,00	
Dana020	· opolac	01				Ec vening D	CHOH							
	Years We			Years We	eks Days	20101119		rs Weeks	Days		•	Years We	eks Day	/s
	Years We		b) at the		•	nt activity (23d)			Days O	d) with	Contractor		eks Day	
24. Experience :	Years We	eks Days					Year		0	e Telephon	Contractor ne No.:		•	
24. Experience : a) Total: 25. Autopsy Perform	Years We 28 (ned:	eks Days O O If Yes, I	ocation	mine: 15 () () c) a	nt activity (23d)	Year 12	2 0	0 26. Min	Telephon (205)	Contractor		•	
24. Experience : a) Total:	Years We 28 (ned: ccident (in tor was p	eks Days O O If Yes, I clude equi preparing forming a	pment involves a drill beno	red, the exact local h on top of an a	o o c) a cion in the mine, pproximately sed over the ed	and status of res 50 feet highwa	Year 12 cue and r	ecovery operator	0 26. Mino	(205) (305)	Contractor le No.: 527-5784	0 on the state of	o 0	
24. Experience : a) Total: 25. Autopsy Perform 27. Description of Ac A bulldozer operat of the highwall. W	Years We 28 (ned: ccident (in tor was p	eks Days O O If Yes, I clude equi preparing forming a	pment involves a drill beno	red, the exact local h on top of an a	o o c) a cion in the mine, pproximately sed over the ed	and status of res 50 feet highwa	Year 12 cue and r	ecovery operator	0 26. Mino	(205) (305)	Contractor le No.: 527-5784	0 on the state of	o 0	
24. Experience : a) Total: 25. Autopsy Perform 27. Description of Ac A bulldozer operat of the highwall. W	Years We 28 (ned: coldent (in tor was p thile perf st aid and	eks Days O If Yes, I clude equiporeparing forming a d CPR we	pment involv a drill bend push, the ere perform	e mine: 15 (et a the exact local the on top of an a buildozer traveled until the core	ion in the mine, pproximately ad over the edoner arrived ar	and status of res 50 feet highwa ge of the highwa nd pronounced	Year 12 cue and r ill. The c vall and if the vict	ecovery operator fell to thim deac	O 26. Minoperations was puse pit bots at 1404	e Telephon (205) s): shing cor tom. The hours.	Contractor le No.: 527-5784 asolidated me operator v	naterial o	o 0	
24. Experience: a) Total: 25. Autopsy Perform 27. Description of Ac A bulldozer operat of the highwall. W unresponsive. First	Years We 28 (ned: ccident (in tor was p thile perf st aid and	eks Days O If Yes, I clude equiporeparing a of CPR we this notice is	pment involv a drill bend push, the ere perform	e mine: 15 (et a the exact local the on top of an a buildozer traveled until the core	ion in the mine, pproximately ad over the edoner arrived ar	and status of res 50 feet highwa ge of the highwa nd pronounced	Year 12 cue and r ill. The c vall and if the vict	ecovery operator fell to thim deac	O 26. Minoperations was puse pit bots at 1404	e Telephon (205) s): shing cor tom. The hours.	Contractor le No.: 527-5784 asolidated me operator v	naterial o	o 0	
24. Experience: a) Total: 25. Autopsy Perform 27. Description of Ac A bulldozer operat of the highwall. W unresponsive. First	Years We 28 (ned: ccident (in tor was p thile perf st aid and	eks Days O If Yes, I clude equiporeparing a of CPR we this notice is	pment involved a drill bence push, the letter perform	e mine: 15 (et a the exact local the on top of an a buildozer traveled until the core	ion in the mine, pproximately ad over the edoner arrived ar	and status of res 50 feet highwa ge of the highwa nd pronounced	Year 12 cue and r ill. The c vall and if the vict	ecovery operator fell to thim deac	O 26. Minoperations was puse pit bots at 1404	e Telephon (205) s): shing cor tom. The hours.	Contractor le No.: 527-5784 asolidated me operator v	naterial o	o 0	
24. Experience: a) Total: 25. Autopsy Perform 27. Description of Ac A bulldozer operat of the highwall. W unresponsive. First	Years We 28 (ned: ccident (in tor was p thile perf st aid and	eks Days O O If Yes, I If Yes, I clude equi oreparing forming a d CPR we have been been been been been been been be	pment involved a drill bence push, the letter perform	e mine: 15 (et a), the exact local the on top of an a buildozer traveled until the cord	ion in the mine, pproximately ad over the edoner arrived ar	and status of res 50 feet highwa ge of the highwa nd pronounced	Year 12 cue and r ill. The c vall and if the vict	ecovery operator fell to thim deac	O 26. Minoperations was puse pit bots at 1404	e Telephon (205) s): shing cor tom. The hours.	Contractor le No.: 527-5784 asolidated in e operator v	onaterial o	o 0	
24. Experience: a) Total: 25. Autopsy Perform 27. Description of Ac A bulldozer operat of the highwall. We unresponsive. First The information proregarding the cause of th	Years We 28 (ned: ccident (in tor was p thile perist aid and of the acci ufacturer: Birmin	eks Days O O If Yes, I If Yes, I clude equi oreparing forming a d CPR we have been been been been been been been be	pment involved a drill bence push, the letter perform	e mine: 15 (et a), the exact local the on top of an a buildozer traveled until the cord	ion in the mine, pproximately ed over the ed oner arrived ar	and status of res 50 feet highwa ge of the highwa nd pronounced	Year 12 cue and r ill. The c vall and if the vict	ecovery operator fell to thim deac	O 26. Minoperations was puse pit bots at 1404	e Telephon (205) s): shing cortom. The hours. he nature of D9L 33. Even	Contractor te No.: 527-5784 asolidated in coperator w of the inciden t Number: 44970	onaterial ovas found	ver the	
24. Experience: a) Total: 25. Autopsy Perform 27. Description of Ac A bulldozer operat of the highwall. W unresponsive. Firs The information pro- regarding the cause of 28. Equipment Manual 30. District: C1100	Years We 28 (ned: ccident (in tor was p thile perf st aid and vided in the of the acci ufacturer: Birmin gator:	eks Days O O If Yes, I If Yes, I clude equi oreparing forming a d CPR we have been been been been been been been be	pment involved a drill bence push, the letter perform	e mine: 15 (et a), the exact local the on top of an a buildozer traveled until the cord	ion in the mine, pproximately sed over the edoner arrived ar NLY and does not ce: Bessen 35. MSHA Per	and status of res 50 feet highwa ge of the highwa nd pronounced	Year 12 cue and r ill. The c vall and if the vict	ecovery operator fell to thim deac	O 26. Minoperations was puse pit bots at 1404	e Telephon (205) s): shing cortom. The hours.	Contractor te No.: 527-5784 asolidated in coperator w of the inciden t Number: 44970	onaterial ovas found	ver the	
24. Experience: a) Total: 25. Autopsy Perform 27. Description of Ac A bulldozer operat of the highwall. W unresponsive. Firs The information pro regarding the cause of 28. Equipment Manual 30. District: C1100 34. Accident Investig	Years We 28 (ned: ccident (in tor was p thile perf st aid and vided in the of the acci ufacturer: Birmin gator:	eks Days O O If Yes, I clude equipreparing forming a d CPR we defend the control of the contr	pment involve a drill bence push, the lere performs	e mine: 15 (et a), the exact local the on top of an a buildozer traveled until the cord	ion in the mine, pproximately sed over the edoner arrived ar NLY and does not ce: Bessen 35. MSHA Per William	and status of res 50 feet highwa ge of the highw nd pronounced ot represent final mer AL rson Notified: n D. Harbin ed:	Year 12 cue and r ill. The c vall and if the vict	ecovery operator fell to thim deac	O 26. Minoperations was puse pit bots at 1404	e Telephon (205) s): shing cortom. The hours. he nature of D9L 33. Even	Contractor te No.: 527-5784 asolidated in coperator w of the inciden t Number: 44970	onaterial of vas found to conclusion of the conc	ver the	