PR001 28-Mar-11

Preliminary Report of Accident

U.S. Department of Labor Mine Safety and Health Administration



1. Accident Type:	2. Accident Classification			3. Date/Time of Accident 4. Date/T		4. Date/Time of De	ath	5. Fatal Case No	
Fatal Injury	Machinery			03/25/2011 08:10 AM 03		03/25/2011	09:01 AM	4	
6. Mine Information :	<u></u>	 ,							
a) Mining Company Name b) Mine Name c) Parent of Mining Company									
Matrix Energy LLC No. 1				James H Booth					
7. Mine Location : a) City) County c) State 8. 1			8. Mine ID Number:	Aine 1D Number: 9. Union:		
Lov	Martin		KY		15-18575	5-18575 NO			
10. Primary Mineral Mined:	11. Number of) Underground	c) Open Pit/Quarry		lill/Prep Plant	e) Other		
BITUMINOUS		Mine Employees:	200	190				10	
12. Contractor Name:			13. Union			14. Contractor ID Number:			
15. Contractor Address:		b) County			c) State d) Zip Code				
16. Number of Contractor Employees: a) Total b) Underground c) Open Pit/Quarry d) Mill/Prep Plant e) Other									
17 N									
17. Number of Persons in Mine at Time of Accident: 18. Number of Persons Unaccounted For:									
a) Mine Employees: 80 b) Contractor Employees: a) Mine Employees: 0 b) Contractor Employees:									
19) Location of Accident X 01-Underground 03-Open Pit 07-Advance Mining 30-Mill/Prep Plant							er (specify)	20. Mining Height: Feet Inches	
02-Surface at Undergrou	und	06-Dredge Mining				acility		6 0	
21. Nonfatal Injuries:		atal Injuries:		L.		•			
211 1 101111111111111111111111111111111	1	1							
23. Victim Information : a) Name b) Age Robert L. Cook 54									
c) Regular Job Title: d) Activity at Time of Accident: X Mine Employee									
Scoop Operator Continuous Miner Operator									
24. Experience: Years Weeks Days Years Weeks Days Years Weeks Days Years Weeks Days							Years Weeks Days		
a) Total: 35	О О ь) at the mine: 7	0 0 c) a	t activity (23d)	30 0	0 d) with	Contractor		
25. Autopsy Performed: If Yes, Location						26. Mine Telephone No.:			
NO					(606) 298-2597				
27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):									
At approximately 0810, a fatal accident occurred at this mine. The continuous miner operator was setting up the miner in the No. 2 left crosscut and was									
pinned between the coal rib and the boom of the machine.									
The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions									
regarding the cause of the accident.									
28. Equipment Manufacturer: Joy Machinery Co. (Joy Manufacturing Co) 29. Mode						14/	15		
			2. Field Office:			33. Event Number:			
C0600 Pikeville			Martin KY				4192439		
34. Accident Investigator:		35. MSHA Person Notified:			Da	ite	Time		
Dwight Bostic		Billy Meddings			03/25/	2011	08:50 A		
36. Type of Report: 37. Name of Preparer and Date					Date				
In	trong	03/25/2011							
38 Reason For Amendment								· ·	