

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Falling, Rolling or Sliding Rock /Materl		3. Date/Time of Accident 03/02/2011 04:51 PM		4. Date/Time of Death 03/02/2011 05:50 PM		5. Fatal Case No 2							
6. Mine Information :															
a) Mining Company Name PCS Phosphate Company Inc			b) Mine Name Lee Creek Mine			c) Parent of Mining Company Potash Corp Of Saskatchewan									
7. Mine Location :		a) City Aurora		b) County Beaufort		c) State NC		8. Mine ID Number: 31-00212		9. Union: NO					
10. Primary Mineral Mined: PHOSPHATE ROCK MINING			11. Number of Mine Employees:		a) Total 385		b) Underground 232		c) Open Pit/Quarry 123		d) Mill/Prep Plant 30				
12. Contractor Name: Trader Construction						13. Union NO		14. Contractor ID Number: IQ6							
15. Contractor Address:		a) City New Bern		b) County Craven		c) State NC		d) Zip Code 28562							
16. Number of Contractor Employees:		a) Total 152		b) Underground 79		c) Open Pit/Quarry 20		d) Mill/Prep Plant 53							
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:									
a) Mine Employees: 152		b) Contractor Employees: 79		a) Mine Employees: 0		b) Contractor Employees: 0									
19) Location of Accident										20. Mining Height:					
<input type="checkbox"/> 01-Underground		<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet Inches					
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility									
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1													
23. Victim Information :															
a) Name David E. Clark				b) Age 51											
c) Regular Job Title: Superintendent										d) Activity at Time of Accident: Placing pipe in fuser					
										<input checked="" type="checkbox"/> Contractor Employee					
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days							
a) Total:		24 0 0		b) at the mine:		20 0 0		c) at activity (23d)		10 0 0		d) with Contractor		24 0 0	
25. Autopsy Performed: If Yes, Location YES Beaufort Co., NC										26. Mine Telephone No.:					

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was attempting to join two ends of 24-inch pipe. An excavator bucket was being used to position the pipe in the saddle of a pipe fuser. The pipe slipped out of the saddle and struck him.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: McElory			29. Model: A3640101		
30. District: M3000 Southeastern		32. Field Office: Sanford NC		33. Event Number: 6528034	
34. Accident Investigator: Billy Ratliff		35. MSHA Person Notified: Doniece L. Schlick		Date 03/02/2011 05:14 P	
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>		Date 03/04/2011	
38. Reason For Amendment:					