## PR001 19-Nov-12

**Preliminary Report of Accident** 

## U.S. Department of Labor

Mine Safety and Health Administration

<b>(</b>
~//

1. Accident Type:	2. Accident Classification				3. Date/Time of Accident 4. Date/T		4. Date/Time	of Death	5. Fatal Cas	e No	
Fatal Injury	Machinery				11/17/2012 03:20 AM 11/1		<b>/</b> 11/17/20	12 04:40 AM	17		
6. Mine Information :		•									
a) Mining Company Name b) Mi			Mine Name c)				c) Parent of Mir	Parent of Mining Company			
Big Ridge Inc	Ridge Inc				Peabody			Energy			
7. Mine Location :		b) County				8. Mine ID Nu		9. Union:			
Equality			Saline		IL		<u> </u>	1-03054 YES			
10. Primary Mineral Mined: BITUMINOUS COAL UN	NDERGROUNE	11. Number o Employe		Total b) 1 410	Underground 395	c) Open P	it/Quarry	d) Mill/Prep Plant	e) Otl	ier 15	
12. Contractor Name:		ļ		410		13. 1	 Jnion	14. Contrac	tor ID Numbe		
15. Contractor Address:	a) City		*	b) (	County		c) State	d) Zi	p Code		
16. Number of Contractor Er	nployees:	a) Total	b) Under	rground	c) Ope	n Pit/Quarry	d) M	ill/Prep Plant	e) Other		
17. Number of Persons in Mi	no at Time of Acci	idanti			19 Number	of Darsons I In	accounted For:				
a) Mine Employees:	84	b) Contractor Er	nployees:	0	a) Mine Ei		0	b) Contractor Emp	oloyees:	0	
19) Location of Accident								-	20. Mining	g Height:	
X 01-Underground 03-Open Pit X 07-Advance					Mining	30-Mill/Pr	ep Plant	Other (specify)	Feet	Inches	
02-Surface at Undergro	und	06-Dredge Minin	g 🔲 0	8-Retreat M	1ining [	99-Office	acility		6	10	
21. Nonfatal Injuries:	0 22. Fa	tal Injuries:	1						-		
23. Victim Information :	Chad	a) Name W. Meyers			b) Age 30						
c) Regular Job Title:		d).	Activity at Ti	me of Accid	_			X N	line Employ	ee	
Underground pr					Continuou	s miner ope					
•	Veeks Days		ars Weeks Da	-		Years We			Years Weeks	-	
	If Yes, Locatio	at the mine:	3 20 0	) c) at a	ectivity (23d)	0 2		with Contractor	0 0	0	
25. Autopsy Performed: YES Watson Fu	neral Home, El						26. Willie Te	lephone No.:			
27. Description of Accident (i	nclude equipment	involved, the exa	ct location in	the mine, ar	nd status of res	cue and recov	ery operations):				
The victim was operating No. 5 entry. He was mir continuous miner into the into the crosscut, he was	ning the crosscue crosscut betw	ut straight on ir reen No. 4 and	nstead of tu I 3 entries t	rning it fro o set the r	om the No. 4 machine ove	entry. Afte r to slab the	r making the i right side of t	nitial cut, the vic	tim backed	the	
The information provided in regarding the cause of the ac-		d on preliminary	data ONLY a	nd does not	represent final	l determinatio	ns regarding the	nature of the incide	nt or conclusio	ons	
28. Equipment Manufacturer: Joy Machinery Co. (Joy Manufacturing Co						29. Model:		14CM15	<del></del>		
30. District: 33: C0800 Vincennes			Joy Manaila		-/ · I						
		32. Fie	eld Office:	Benton II	<u> </u>		33	. Event Number: 4252	111		
		32. Fie	eld Office:	Benton II	<u> </u>		33		111 Time		
C0800 Vince		32. Fie	eld Office:	Benton II	L on Notified:			4252			
C0800 Vinco  34. Accident Investigator: Dean R. Cripps  36. Type of Report:	ennes	32. Fig. 37. Name of Pre	35, Peparer and Da	Benton II  MSHA Perso  Marty G  ate Prepared	L on Notified: Gayer			Date 1/17/2012 Date	Time 04:07 A		
C0800 Vinco  34. Accident Investigator: Dean R. Cripps  36. Type of Report:			35, Peparer and Da	Benton II MSHA Pers Marty G	L on Notified: Gayer			4252 Date 1/17/2012	Time 04:07 A		