## PR001 06-Feb-12

## **Preliminary Report of Accident**

## U.S. Department of Labor

Mine Safety and Health Administration

1. Accident Type:	2. Accident Classification			3. Date/Time of Accident 4. Date/T			te/Time of Death		5. Fatal Case No	
Fatal Injury	Powered Haulage			01/27/201	5 PM 01/3	01/27/2012 05:05 PM		1		
6. Mine Information :	J									
a) Mining Company Name		b) Mine Name				c) Parent	of Mining C	Company		
Holcim (US) Inc. SECURIT			QUARRY			Holcim Ltd				
7. Mine Location : a) City		b) County		c) State		8. Mine	8. Mine ID Number:		9. Union:	
. Hag	gerstown	Washing	MD		1	18-00019		YES		
10. Primary Mineral Mined:		11. Number of Mine Employees:		Underground	c) Op	en Pit/Quarry	d) M	ill/Prep Plant	· ·	
HYDRAULIC CEMENT		Mine Employees.	91	0		9		82	0	
12. Contractor Name:						13. Union		14. Contra	ctor ID Number:	
15. Contractor Address:	a) City		b)	) County		c) S	state	d) Z	ip Code	
16. Number of Contractor Er	nployees:	a) Total b)	) Underground	с) Оре	en Pit/Quai	rry	d) Mill/Pr	ep Plant	e) Other	
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees:	a) Mine Employees: b) Contractor Employees:									
9) Location of Accident 01-Underground X 03-Open Pit 07-Advan				Mining 70 Mill/Down Dland Other (marife)					20. Mining Height: Feet Inches	
02-Surface at Undergro	und	06-Dredge Mining	08-Retreat	Mining	99-Off	ice Facility			Teet menes	
21. Nonfatal Injuries:	22. Fa	tal Injuries:								
23. Victim Information :		a) Name		b) Age						
	Herm	an L. Weaver, Jr		69					17.4.46	
c) Regular Job Title: Mobile Equipme	nt Operator	d) Activit	y at Time of Acci	dent: Operating	skid stee	r loader		X	Iine Employee	
	eeks Days	Years We	eks Days	+		Weeks Days			Years Weeks Days	
a) Total: 48	1 3 b)	at the mine: 48	1 3 c) at	activity (23d)	45	32 0	d) with	Contractor	-	
25. Autopsy Performed:	If Yes, Locatio	n ·				26. M	ine Telepho	ne No.:		
YES Hagerstown	n, MD						(301	) 739-1150		
27. Description of Accident (i	nclude equipment	involved, the exact loca	tion in the mine, a	and status of res	scue and re	covery operation	ons):			
The victim was cleaning a	a tailpiece with a	skid steer loader. H	le backed the lo	oader in a dito	ch, travele	d in reverse	about 150	feet, and w	ent into an 8-foot	
deep water filled hole.									T.	
								•		
The information provided in		l on preliminary data O	NLY and does no	t represent fina	l determina	ations regardin	g the nature	of the incide	nt or conclusions	
regarding the cause of the ac 28. Equipment Manufacture					29. Mo	del:				
Caterpillar					25.1.10		226	5		
30. District: M2000 North	· · · · · · · · · · · · · · · · · · ·			dale PA	33. Event Number: 6569991			9991		
34. Accident Investigator:			35. MSHA Per	rson Notified:	<del></del>	<del>.</del>	D	ate	Time	
Reecle C. Horn			Victor	C. Lescznske	9		01/27/	2012	05:05 P	
36. Type of Report:		37. Name of Preparer	-	- 1				Date		
	mended ——		Mike Hanche	M				02/06/20	12	
38. Reason For Amendment: Items No. 3 (time), 23(a										