PR001 16-Oct-13

Preliminary Report of Accident

U.S. Department of Labor

Mine Safety and Health Administration

((6)	
N/	

1. Accident Type:	2. Accident Cl	assification	sification			3. Date/Time of Accident 4. Date		Death	5. Fatal Case No	
Fatal Injury	Powered H	Powered Haulage			10/05/20 ⁻	10/05/2013 01:30 PM 10/0		01:59 PM	16	
6. Mine Information :	<u> </u>						•			
a) Mining Company Name b) Mine Name						c) Parent of Mining Company				
White County Coal, LLC Pattiki Alliance Resource Partners LP										
7. Mine Location :	a) City		b) (County	c) State		8. Mine ID Numb	er:	9. Union:	
Carmi			White		IL	IL 1		8	NO	
10. Primary Mineral Miner	d:		Number of Mine Employees:	e a) Total	b) Underground	c) Open Pit	/Quarry d)	Mill/Prep Plant	e) Other	
BITUMINOUS			Employees.	312	275	1 40 57		27	10	
12. Contractor Name:						13. Uı	NO	14. Contrac	tor ID Number:	
15. Contractor Address:	a) Cit	y			b) County		c) State	d) Zi	p Code	
16. Number of Contractor Employees: a) Total b) Underground c) Open Pit/Quarry d) Mill/Prep Plant e) Other										
17. Number of Persons in M	Mine at Time of Ac	cident:			18. Number	of Persons Unac	counted For:			
a) Mine Employees: 18 b) Contractor Employees: 0 a) Mine Employees: 0 b) Contractor Employees: 0										
19) Location of Accident		1							20. Mining Height:	
X 01-Underground		03-Open			nce Mining	30-Mill/Prej		ther (specify)	Feet Inches	
02-Surface at Underg			ge Mining	08-Retre	at Mining	99-Office Fa	acility		5 5	
21. Nonfatal Injuries:	0	Fatal Inju	nes:							
23. Victim Information :	Rob	a) Name ert E. Sr			b) Age 47					
c) Regular Job Title:				ty at Time of Ac				X M	ine Employee	
General Laborer Driving battery golf cart										
-	Weeks Days		Years We	•		Years Weel	•		Years Weeks Days	
a) Total: 15		b) at the n	nine: 15	6 c)	at activity (23d)	15 6		th Contractor		
25. Autopsy Performed: YES Campbell	If Yes, Locat Funeral home,		v II				26. Mine Telep	hone No.: 18) 382-2136		
•			•				`	10) 302-2130		
27. Description of Accident	• •					•	•			
The victim was driving a battery powered golf cart (company number 7) along the second 48 travel way at cross cut number 6-5, traveling in an outby direction. The golf cart turned over on top of him pinning him under the golf cart. A miner traveling behind the victim in a diesel vehicle (company number 7359) tried to remove the victim but couldn't move the cart. He called for help on the radio on his vehicle, and when help arrived, he and another miner pried the cart up enough to pull the victim from the cart. No pulse was found, the victim was not breathing, and his abdomen was swollen. CPR was started and										
continued to the surface				ao roaria, aro	Widami Wao ma	broatining, and	The abaement	ao o wonon . O	re was started and	
The information provided i		ed on preli	minary data O	NLY and does n	not represent final	determinations	regarding the natu	re of the inciden	t or conclusions	
regarding the cause of the						29. Model:				
28. Equipment Manufactur	rer:					29. Model:	G	C15		
30. District: C0800 Vin	icennes	Ţ	32. Field Off	fice: Marior	n IL		33. E	vent Number: 4254	623	
34. Accident Investigator:				35. MSHA P	Person Notified:			Date	Time	
Larry D. Morris				Micha	ael D. Rennie		10/0	5/2013	01:44 PM	
36. Type of Report: 37. Name of Prepar			ne of Preparer	•				Date		
	Amended	nded Larry D. Morris			rris		10/07/2013			

Correct contractor data.