

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Electrical		3. Date/Time of Accident 07/21/2014 03:50 PM		4. Date/Time of Death 07/21/2014 03:50 PM		5. Fatal Case No 15		
6. Mine Information :										
a) Mining Company Name Murray Mines Inc.			b) Mine Name Murray Mines Inc.			c) Parent of Mining Company James O Murray Jr				
7. Mine Location :		a) City Ridgeville		b) County Colleton		c) State SC		8. Mine ID Number: 38-00136		9. Union: NO
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M		11. Number of Mine Employees:		a) Total 10	b) Underground 0	c) Open Pit/Quarry 4		d) Mill/Prep Plant 6	e) Other 0	
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code		
16. Number of Contractor Employees:										
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other		
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 8		b) Contractor Employees:			a) Mine Employees: 0		b) Contractor Employees: 0			
19) Location of Accident								20. Mining Height:		
<input type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit	<input type="checkbox"/> 07-Advance Mining	<input type="checkbox"/> 30-Mill/Prep Plant	<input type="checkbox"/> Other (specify)				Feet	Inches	
<input type="checkbox"/> 02-Surface at Underground	<input checked="" type="checkbox"/> 06-Dredge Mining	<input type="checkbox"/> 08-Retreat Mining	<input type="checkbox"/> 99-Office Facility							
21. Nonfatal Injuries:		22. Fatal Injuries: 1								
23. Victim Information :										
a) Name Kyle R. Martin				b) Age 28						
c) Regular Job Title: Assistant Plant Manager				d) Activity at Time of Accident: Pulling Cable				<input checked="" type="checkbox"/> Mine Employee		
24. Experience :										
Years	Weeks	Days	Years	Weeks	Days	Years	Weeks	Days	Years	
a) Total:	11	8	0	b) at the mine:	11	8	0	c) at activity (23d)	11	
									d) with Contractor	
25. Autopsy Performed: If Yes, Location YES MUSC, Charleston, SC								26. Mine Telephone No.: (843) 835-2373		

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):
The victim was attempting to pull slack on the 480 volt power conductors feeding the dredge when the aluminum boat he was riding in contacted exposed conductors and he was electrocuted. First aid was performed and the victim was then transported to a medical facility where he was pronounced dead.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:			
30. District: M3000 Southeastern		32. Field Office: Columbia SC				33. Event Number: 0926482	
34. Accident Investigator: Stanley Stevenson			35. MSHA Person Notified: Patrick Sharp			Date 07/21/2014	Time 04:10 P
36. Type of Report: Initial		37. Name of Preparer and Date Prepared Mike Hancher <i>MH</i>				Date 07/24/2014	
38. Reason For Amendment:							