PR001 15-Aug-14	Pre	liminary Re	eport of	f Accident			nent of Labor ad Health Administra	ation 🕼
1. Accident Type:	2. Accident Classification			3. Date/Time of A	Accident 4. Date/Time of Death		5. Fatal Case No	
Fatal Injury	Failing, Rolling or Sliding Rock /Materl			08/02/2014	11:00 AM	08/02	/2014 11:00 AM	17
6. Mise Information :								
a) Mining Company Name		b) Mine Name			c) Parent of	Mining Company	
Fossum Ready Mix		Belzer Pit			S	teve Fos	sum; Scott Fossu	m; Carol Fossum
7. Mine Location :	a) City	b) Co	ounty	c) State		8. Mine ID	Number:	9. Union:
Gla	sgow	Valley		MT		24-00420		NO
10. Primary Mineral Mined: CONSTRUCTION SAND	& CRAVEL M	11. Number of Mine Employees:	7.5 V CANES	b) Underground	c) Open Pit/		d) Mill/Prep Plant	·
	D a GIVAVLL IVI		2	0	Low	2	0	0
12. Contractor Name:					13. Un	1041	14, Contrac	ctor ID Number:
15. Contractor Address:	a) City			b) County	<u> </u>	c) Stat	e d) Z	ip Code
17. Number of Persons in Mi	ne at Time of Accid	ent:		18. Number of l	Persons Unacc	counted For	и #	
a) Mine Employees:	1 b) Contractor Employee	s: 0	a) Mine Emp	loyees:	0	b) Contractor Emp	oloyees: 0
19) Location of Accident Ol-Underground	X 0.	3-Open Pit	07-Adva	nce Mining	30-Mill/Prep	Plant	Other (specify)	20, Mining Height: Feet Inches
02-Surface at Undergrou	and 🗌 0	S-Dredge Mining	08-Retre	at Mining	99-Office Fat	cility		
21. Nonfatal Injuries:	22. Fat	al Injuries: 1		a ta				
23. Victim Information :) Name L. Irwin		b) Age 53				
c) Regular Job Title:	TODDI	the second s	at Time of A	ccident:			X M	line Employee
Plant Operator				Working und	er raised tri	uck bed		
24. Experience : Years W	eeks Days	Years We	eks Days		Years Week	s Days		Years Weeks Days
a) Total: 25	4 2 b) a	it the mine: 25 4	2 c)	at activity (23d)	25 4	2	d) with Contractor Telephone No.:	

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim was working under the raised bed of a dump truck when the wooden block supporting the bed suddenly failed, pinning him. The victim was working alone and was not found until 10 a.m. on August 3, 2014.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Man	ufacturer: Intern	ational Harvester	29. Model: Loadstar				
30. District; M6000	Rocky Mountain	32. Field Off	ice: Rapid City SD		33. Event Number: 6692804		
34. Accident Investigator: David Small			35. MSHA Person Notified: Dustan Crelly		Date 08/03/2014	Time 01:21 P	
36. Type of Report:	Amended	37. Name of Preparer	37. Name of Preparer and Date Prepared Mike Hancher MH		D 08/15/	ate 2014	

38. Reason For Amendment:

Items 23 a, b