Preliminary Report of Accident

U.S. Department of Labor Mine Safety and Health Administrat



05-Jan-15		J			MIII	e Safety and Healt	n Administra	ation	
1. Accident Type:	2. Accident Classification			3. Date/Time of Accident		4. Date/Time of Death		5. Fatal Case No	
Fatal Injury	Powered Haulage			11/25/2014	1/25/2014 01:15 PM 11/25/2014 02		02:59 PM	22	
6. Mine Information :									
a) Mining Company Name		b) Mine Name				:) Parent of Mining (Company		
Edwards Sand & Stone		South Sterling	Quarry		(George F Edward	ds Jr		
7. Mine Location :	a) City	b) Co	ounty	c) State		8. Mine ID Number	:	9. Union:	
So. Sterling		Pike		PA		36-08183		NO	
10. Primary Mineral Mined: CRUSHED & BROKEN		11. Number of Mine Employees:	a) Total 15	b) Underground O	c) Open Pit	/Quarry d) M 7	lill/Prep Plant 5	t e) Other 3	
12. Contractor Name:		4			13. Ui	lion	14. Contra	ctor ID Number:	
15. Contractor Address:	a) City			b) County		c) State	d) Z	ip Code	
16. Number of Contractor E	mployees:	a) Total b)	Underground	c) Open I	Pit/Quarry	d) Mill/Pr	ep Plant	e) Other	
17. Number of Persons in M	ne at Time of Accid	ent:		18. Number of	Persons Unac	counted For:			
a) Mine Employees:	13 b) Contractor Employee	s: 0	a) Mine Emp	loyees:	0 b) Co	ontractor Emp	ployees: 0	
19) Location of Accident 01-Underground 02-Surface at Undergro		3-Open Pit 6-Dredge Mining	07-Advan	ice Mining	30-Mill/Prej 99-Office Fa		er (specify)	20. Mining Height: Feet Inches	
21. Nonfatal Injuries:	0 22. Fat	al Injuries: 1							
23. Victim Information :) Name P. Crane		b) Age 67					
c) Regular Job Title: d) Activity at Time of Accident: Truck Driver Truck Driver							XN	fine Employee	
24. Experience : Years Weeks Days Years Weeks Days Years Weeks Days									
a) Total: 10	27 2 b) а	at the mine: 10 27	2 c)	at activity (23d)	10 27	2 d) with	Contractor		
25. Autopsy Performed: If Yes, Location YES Dunmore, PA						26. Mine Telephone No.: (570) 676-3200			
28 D		and the second second	and Annual Concerning	1					

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim backed the truck he was driving to the edge of the overburden dumpsite and started to raise the truck's bed to dump a load of material. The bank failed and the truck overturned falling 30 feet below. The victim died in route to the hospital.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

d (Euc)	29. Model: R35				
30. District: 32. Field Office M2000 Northeastern 34. Accident Investigator:			33. Event Number: 6684450		
			Date	Time	
Thomas J. Shilling			11/25/2014	02:42 P	
37. Name of Preparer	and Date Prepared		Date		
Amended			12/01/2014		
		32. Field Office: Wyomissing PA 35. MSHA Person Notified:	32. Field Office: Wyomissing PA 35. MSHA Person Notified: Kevin T. Hardester 37. Name of Preparer and Date Prepared	d (Euc) R35 32. Field Office: Wyomissing PA 66 35. MSHA Person Notified: Date Kevin T. Hardester 11/25/2014 37. Name of Preparer and Date Prepared D	

38. Reason For Amendment.

Item #3 --- Time of Accident