



HEALTH ALERT

Mobile Mining Operations & Equipment

Best Practices:

- Control workplace environments to ensure compliance with the dust permissible exposure limits.
- Engineering controls reduce dust at its source.
 - Dust collector systems
 - Enclosures and booths
 - Use water for dust suppression
 - Sprays
 - Water Trucks
 - Environmental cabs
- Maintain equipment per manufacturer's recommendations.
- Provide respiratory protection and ensure it is worn.
- Have a compliant respiratory protection program (RPP).

Click below for more information on MSHA's
Silica Enforcement Initiative

Report accidents and hazardous conditions: 1-800-746-1553 [msha.gov](https://www.msha.gov) | askmsha@dol.gov | [@MSHA_DOL](https://twitter.com/MSHA_DOL)