### CAI-2013-01

## UNITED STATES DEPARTMENT OF LABOR MINE SAFETY AND HEALTH ADMINISTRATION

#### COAL MINE SAFETY AND HEALTH

### REPORT OF INVESTIGATION (Surface Coal Mine)

Fatal Accident (Machinery) January 26, 2013

Watts Welding & Fabricating (NXA) Slemp, Kentucky

at

Begley Resources, #1 T & T Energy, LLC Hyden, Leslie County, Kentucky MSHA ID No. 15-19550

Accident Investigator David A. Faulkner Surface Coal Mine Health and Safety Inspector

Originating Office Mine Safety and Health Administration District 7 3837 S. U.S. Hwy. 25 E, Barbourville, Ky. 40906

Irvin T. Hooker, District Manager

# **Table of Contents**

PHOTOGRAPH OF ACCIDENT SCENEii
OVERVIEW 1
GENERAL INFORMATION 1
DESCRIPTION OF ACCIDENT
INVESTIGATION OF ACCIDENT
DISCUSSION
TRAINING & EXPERIENCE4
ROOT CAUSE ANALYSIS
CONCLUSION
ENFORCEMENT ACTIONS7
APPENDIX A - List of Persons Participating in Investigation
APPENDIX B - List of Persons Interviewed9
APPENDIX C - 7000-50b Form (Victim Information)10
APPENDIX D – Overall Sketch of Accident Scene11
APPENDIX E – Detailed Sketch of Accident Scene

# PHOTOGRAPH OF ACCIDENT SCENE



#### **OVERVIEW**

On Saturday, January 26, 2013, at approximately 11:10 a.m., a machinery accident occurred at the T & T Energy, LLC, Begley Resources # 1 Mine, located near Hyden, Leslie County, Kentucky. Jerry A. Watts (victim), a 52 year old contract welder with 30 years of experience, received blunt force trauma injuries when he was struck by a metal liner (component of the push blade) being repaired on a Caterpillar D10R bulldozer's push blade. (See Appendix E for sketch). The victim died from injuries sustained in the accident. There were no eye-witnesses to the accident.

The accident investigation team determined that while conducting repairs on the bulldozer push blade's metal liner, the victim positioned himself partially between the metal liner and the push blade. A hydraulic jack used to support the metal liner slipped, allowing the metal liner to retract and strike the victim.

#### **GENERAL INFORMATION**

The Begley Resources # 1 mine is a surface coal mine that is located at 1081 Willie Begley RV Park Road, off Highway 421 in Hyden, Kentucky. The mine had 38 employees at the time of the accident, operating two production shifts daily, five to six days per week. The active work area is identified as Area 15, No. 8. The mine produces 1,000 tons of coal per day from the Hazard No. 8, Hazard No. 9, and Hazard No. 10 coal seams. Coal is mined with wheel loaders, haul trucks, and bulldozers. The coal is transported from the coal pit to delivery locations by contract trucking companies.

The principal officers for T & T Energy, LLC are:

Amy C. Hamilton	Managing Member
Mervin Anthony Hamilton	Superintendent

The last regular safety and health inspection (E01) conducted by the Mine Safety and Health Administration (MSHA) was completed on December 11, 2012. The mine's Non Fatal Days Lost (NFDL) incidence rate for 2012 was 0.0, compared to the national average of 1.04 for mines of the same type.

#### **DESCRIPTION OF ACCIDENT**

At approximately 7:15 a.m. on Saturday, January 26, 2013, Jerry A Watts, Contract Welder, arrived for work. Rodney D. Couch, Foreman, met Watts in the parking area of the mine identified as Area 15, No. 8. Couch informed Watts that the metal liner of the push blade on the Caterpillar D10R bulldozer, Co. # 104, was peeling up and needed repaired. At this time, the bulldozer was in operation, but was to be available for repairs shortly. Prior to beginning repairs on the push blade, Watts traveled to the oxygen and acetylene storage area to acquire a cylinder of acetylene for his welding truck. Upon return, Watts found the Caterpillar bulldozer parked and available for repairs.

Before beginning repairs on the push blade, Watts communicated by CB radio with James Thomas Elsea, Mechanic, and requested to use his service truck. The service truck was equipped with an air compressor needed for the operation of the air hammer. Elsea, who was operating a haul truck, instructed Watts to go ahead and use the truck. After parking the service truck adjacent to the bulldozer, Watts again communicated with Elsea requesting instruction on the operation of the hydraulic air compressor.

Shortly afterwards, Watts communicated again by CB radio with Kenneth Bowling, Excavator Operator, requesting instructions on the operation of the Caterpillar 365 excavator. At this time, Bowling was operating a haul truck in the pit area. Bowling was later instructed by the mine foreman to return the haul truck to the parking area and retrieve the excavator for use in the active pit area. Upon arrival to the parking area, Bowling found Watts operating the excavator. Watts was using the bucket attachment to remove dirt and materials from behind the damaged liner on the push blade of the bulldozer. While at this location, Bowling asked Watts if he need any assistance. Watts declined and completed his excavator work. Thereafter, Bowling assumed operation of the excavator and trammed the excavator to the pit area.

At approximately 10:50 a.m., Mervin Anthony Hamilton, Superintendent, drove by the parked bulldozer on his way to the mine office to pick up a blast hole drill bit. Hamilton observed Watts standing near the rear of his welding truck as he passed. At approximately 11:15 a.m., Hamilton was returning from the mine office. Hamilton stopped at Watts' location to obtain a wrench from the service truck and to ask Watts for assistance in changing the drill bit. Hamilton found Watts lying unresponsive in front of the bulldozer.

Hamilton contacted Couch by CB radio and told him to come quickly, because Watts had been injured. Jody Bowen, Loader Operator/Mine Emergency Technician (MET), and Elsea heard the call and responded to the location. Approximately two minutes later, Bowen arrived and began checking Watts for vital signs. Watts was unresponsive and lacked a pulse. Bowen was unable to perform CPR due to the extent of the injuries Watts had sustained. A call was made to the local 911 dispatch center and the local ambulance service responded to the accident scene. Watts was pronounced dead at the mine by the Leslie County Coroner at 1:00 p.m.

### **INVESTIGATION OF ACCIDENT**

Mervin Anthony Hamilton, Superintendent, called the National Call Center at 11:37 a.m. on January 26, 2013. The call center notified MSHA / Coal Mine Safety and Health (CMS&H) Special Investigation Supervisor, Kenneth McClung of the accident at 11:55 a.m. McClung contacted Clayton E. Sparks, Assistant District Manager, via telephone. Sparks called Samuel R. Creasy, Supervisor for the CMS&H Barbourville Field Office. Creasy then made contact with David A. Faulkner, Accident Investigator.

A 103(j) Order was issued verbally by Creasy at 1:45 p.m. to ensure the safety of the miners and to preserve the accident scene. Faulkner and Creasy then traveled to the accident scene. Upon their arrival, the 103(j) order was modified to a 103(k) order at 2:15 p.m. Preliminary information was gathered and the accident scene examined. The accident investigation was conducted in coordination with the Commonwealth of Kentucky Office of Mine Safety and Licensing (KOMSL).

Formal interviews were conducted on January 28, 2013, at the KOMSL Office in Hazard, Kentucky. For a list of those who participated in the interviews, see Appendix B.

#### DISCUSSION

The accident occurred while Watts was conducting repairs to the center portion of the metal liner on the push blade of the Caterpillar D10R bulldozer. A hydraulic jack was positioned between the push blade surface and the inside of the damaged metal liner. Watts was using an air hammer with a chisel attachment to remove dirt and contaminants from behind the metal liner in preparation to repair the push blade. The metal liner was extended outward enough to allow Watts to position his arm and a portion of his head behind the metal liner. The vibration caused by the air hammer against the metal liner and push blade allowed the hydraulic jack to slip. The metal liner recoiled, striking Watts in the head and pinning his arm. The hydraulic jack was found lodged on its side between the metal liner and the push blade.

#### MACHINE INFORMATION

The Caterpillar Model D10R Track-Type Bulldozer, serial number AKT00480, was identified as Company # 104.

#### BULLDOZER PUSH BLADE

The bulldozer was equipped with a universal push blade (U-Blade), serial number BHP00220. The push blade measured approximately sixteen feet, eight inches wide by six feet, nine and one half inches tall. The surface areas of the push blade and metal liner are manufactured in a concave (curving inward) manner.

The surface area of the damaged metal liner measured approximately nine feet, one and one half inches wide by six feet, two inches tall and three fourths of an inch thick. The estimated weight is 1,432 lbs.

## AIR HAMMER & HYDRAULIC JACK

The air hammer was an Ingersoll-Rand hand-held tool with a chisel attachment. The compressed air was supplied by a hydraulic air compressor mounted on the company service truck.

The hand operated hydraulic jack had an estimated capacity of sixteen tons. The base of the jack measured approximately five inches by five and one half inches. When recovered, the jack was extended approximately 12 inches.

### WEATHER CONDITIONS

Weather data obtained for the mine location at the approximate time of the accident indicated the temperature to be 28 degrees, the dew point 26 degrees, relative humidity 93%, winds 0 mph, with fog and visibility 4 miles. The weather was not a contributing factor to this accident.

The area underneath the hydraulic jack was dry where the jack was being used to support the metal liner and did not contribute to slippage of the jack.

#### TOXICOLOGY

Toxicology of the victim's blood was conducted post-mortem. The results of the toxicology indicated that the victim was positive for Cannabinoids and Methadone.

# **TRAINING & EXPERIENCE**

Training records indicated that Watts received experienced miner training on 06/27/2011. Task training records indicated that Watts had received task training as a welder on 06/27/2011. The last annual refresher training was received on 03/24/2012. Information obtained through the investigation, interviews and family liaison contacts determined that Watts had 30 years of experience as a welder.

A review of mine operator's training program was conducted. Deficiencies were found for the mine operator not completing training requirements as required by 30 CFR § 48.31, and 30 CFR § 48.27, which did not contribute to the accident. Violations were issued under a separate event for these deficiencies.

## **ROOT CAUSE ANALYSIS**

An analysis was conducted to identify the most basic causes of the accident that were correctable through reasonable management controls. During the analysis, a root cause was identified that, if eliminated, would have either prevented the accident or mitigated its consequences. The following root cause was identified and the corresponding corrective action was implemented to prevent a recurrence.

1. *Root Cause*: Mine Management failed to implement policies and procedures to ensure that the metal liner on the push blade of the bulldozer was blocked or secured against motion during repairs and failed to train the miners in these procedures.

*Corrective Action*: Mine Management has established and implemented written safety procedures and provided additional training to the affected miners for blocking and securing mobile equipment or components prior to repairs.

## CONCLUSION

The accident occurred because the mine operator failed to ensure that the contract welder blocked or secured the metal liner on the push blade of the bulldozer against motion. The accident investigation team concluded that the hydraulic jack used to support the metal liner slipped, creating a recoil action of the metal liner. The injuries received from the blunt force trauma caused the death of the victim.

Irvin T. Hooker District Manager

pril 23,2013 Date

# **ENFORCEMENT ACTIONS<sup>1</sup>**

Order No. 8388035 was issued to T & T Energy, LLC on January 26, 2013, under the provisions of Section 103(j) of the Mine Act:

An accident occurred at this operation on 01-26-2013, at approximately 11:20 a.m. As rescue and recovery work is necessary, this order is being issued, under Section 103(j) of the Federal Mine Safety and Health Act of 1977, to assure the safety of all persons at this operation. This order is also being issued to prevent the destruction of any evidence which would assist in investigating the cause or causes of the accident. It prohibits all activity at the entire mine site, until MSHA has determined that it is safe to resume normal mining operations in this area. This order applies to all persons engaged in the rescue and recovery operation and any other persons on-site. The order was initially issued orally to the mine operator at 13:45 and now been reduced to writing.

Modified Order No. 8388035 to 103(k) order at 14:15 p.m.

<u>104(d)1 Order No. 8388048</u> was issued to T & T Energy, LLC, for violation of 30 CFR § 77.405(b).

As a result of a fatal accident investigation at the T & T Energy, LLC, Begley Resources # 1 mine, it has been concluded that management failed to ensure the contract welder securely blocked in position the metal liner (component) measuring nine feet one and one half inches by six feet, two inches, located on the push blade of the Caterpillar D10R bulldozer, Co. # 104, S/N AKT00480. A hydraulic jack was used to raise the metal liner (component) away from the push blade. The jack slipped allowing the metal liner to strike the victim. No blocking was provided at the location of the bulldozer. This violation is an unwarrantable failure to comply with a mandatory standard.

<sup>&</sup>lt;sup>1</sup> Because the victim was the sole proprietor of the contracting entity, no enforcement actions were issued to the contractor.

# **APPENDIX A**

List of persons furnishing information and/or present during the investigation:

# T & T Energy, LLC Officials & Employees

James Thomas ElseaMecha	anic
Jamie CollettMine Office Mana	ager
Rodney D. CouchMine Forer	man
Bill Woods Chief Financial Off	
Mervin Anthony Hamilton Superintend	dent
Amy C. HamiltonManaging Mem	ıber

# Kentucky Office of Mine Safety & Licensing

Tracy Stumbo	Chief Accident Investigator
Greg Goins	
Tim Fugate	Deputy Chief Accident Investigator
Ricky Johnson	District Supervisor
Ralph Crawford	
Gene Adams	
Ronald Patrick Turner	Inspector
Ronnie Whitaker	-
	1

# Mine Safety and Health Administration

Steven L. Sorke	Accident Investigation Coordinator /Staff Assistant
David A. Faulkner	CMS&H Surface Specialist/Accident Investigator
Samuel R. Creasy	Supervisory CMS&H Inspector
Deborah B. Combs	Educational Field Service/Training
Lester Cox	Family Liaison
Clayton E. Sparks	Assistant District Manager
	District Manager

# **APPENDIX B**

# List of Persons Interviewed

David P. Ferguson	Drill Operator
Ronald Douglas Bray	Haul Truck Operator
Harold D. Howard	Haul Truck Operator
Kenneth Bowling Jr.	Excavator Operator
James Thomas Elsea	
Jody Paul Bowen	Wheel Loader Operator
Kevin Dean Spurlock	Equipment Operator
Rodney D. Couch	
Mervin Anthony Hamilton	Superintendent

# APPENDIX C MSHA Form 7000-50b


Accident Investigation Data - Victim Inform	ation	U.S. Depar	tment of Labor 🧥
Event Number: 6 4 2 8 1 3 4		Mine Safety a	and Health Administration
Victim Information: 1			
1. Name of Injured/III Employee: 2. Sex 3. Victim' Jerry A. Watts M 52			
		nd Time Started:	
a. Date: 01/26/2013 b. Time: 13:00		. Date: 01/26/2013 b.Time: 7:0	00
7. Regular Job Title:	8. Work Activity when Injured:		9. Was this work activity part of regular job?
121 Welder/blacksmith	039 Machine maintenance/repa	ir	Yes X No
10. Experience Years Weeks Days a. This b. Regula	Years Weeks Days	Years Weeks This	Days Years Weeks Days d. Total
Work Activity: 30 0 0 Job Title:		/line: 1 40	0 Mining: 30 0 0
11. What Directly Inflicted Injury or Illness?		Nature of Injury or Illness:	
086 Metal cover/guard/door/gate/mat/canopy 13. Training Deficiencies		170 Crushing	
Hazard: New/Newly-Employed Experier	ced Miner:	Annual:	Task:
14. Company of Employment: (If different from production oper			
Watts Welding and Fabricating	,	Independent Co	ontractor ID: (if applicable) NXA
15. On-site Emergency Medical Treatment			
	PR: EMT:	Medical Professional:	None:
16. Part 50 Document Control Number: (form 7000-1)	17. Union A	Affiliation of Victim: 9999	None (No Union Affiliation)
Victim Information:			
1. Name of Injured/III Employee: 2. Sex 3. Victim'	s Age 4. Degree of Injury:		
		17 01 1 1	
5. Date(MM/DD/YY) and Time(24 Hr.) Of Death:	6. Date a	and Time Started:	
7. Regular Job Title:	8. Work Activity when Injured:		9. Was this work activity part of regular job?
			Yes No
10. Experience: Years Weeks Days a. This b. Regul	Years Weeks Days	c: This Years Week	Days d. Total Years Weeks Days
Work Activity: Job Title		Mine:	Mining:
11. What Directly Inflicted Injury or Illness?	12	Making of Johnson Illingson	
	12.	Nature of Injury or Illness:	
· · · · · · · · · · · · · · · · · · ·	12.	. Nature of injury of liness:	
13. Training Deficiencies:			Testa
13. Training Deficiencies: Hazard: New/Newly-Employed Experies	nced Miner:	Annual:	Task:
13. Training Deficiencies:	nced Miner:	Annual:	1
13. Training Deficiencies:     Hazard: New/Newly-Employed Experie     14. Company of Employment: (If different from production open	nced Miner:		1
13. Training Deficiencies:         Hazard:       New/Newly-Employed Experier         14. Company of Employment:       (If different from production oper         15. On-site Emergency Medical Treatment:	ator)	Annual:	1
13. Training Deficiencies:         Hazard:       New/Newly-Employed Experie         14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment:	aced Miner:  ator)	Annual:	applicable)
13. Training Deficiencies:         Hazard:       New/Newly-Employed Experier         14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment:         Not Applicable:       First-Aid:         16. Part 50 Document Control Number: (form 7000-1)	aced Miner:  ator)	Annual:	applicable)
13. Training Deficiencies:         Hazard:       New/Newly-Employed Experie         14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment:         Not Applicable:       First-Aid:       CP	nced Miner:   ator) R:   EMT:     17. Union A	Annual:	applicable)
13. Training Deficiencies:       Hazard:       New/Newly-Employed Experier         14. Company of Employment: (if different from production oper         15. On-site Emergency Medical Treatment:         Not Applicable:       First-Aid:       CP         16. Part 50 Document Control Number: (form 7000-1)         Victim Information:	aced Miner:   ator) R:   EMT:     17. Union A	Annual:	applicable)
13. Training Deficiencies:       Hazard:       New/Newly-Employed Experier         14. Company of Employment: (if different from production oper         15. On-site Emergency Medical Treatment:         Not Applicable:       First-Aid:       CP         16. Part 50 Document Control Number: (form 7000-1)         Victim Information:	aced Miner:	Annual:	applicable)
13. Training Deficiencies: Hazard:       New/Newly-Employed Experie         14. Company of Employment:       If different from production oper         15. On-site Emergency Medical Treatment: Not Applicable:       First-Aid:       CP         16. Part 50 Document Control Number:       (form 7000-1)       Victim Information:         1. Name of Injured/III Employee:       2. Sex       3. Victim	aced Miner:	Annual:	applicable)
13. Training Deficiencies: Hazard:       New/Newly-Employed Experie         14. Company of Employment:       If different from production oper         15. On-site Emergency Medical Treatment: Not Applicable:       First-Aid:       CP         16. Part 50 Document Control Number:       (form 7000-1)       Victim Information:         1. Name of Injured/III Employee:       2. Sex       3. Victim	aced Miner:	Annual:	applicable)
13. Training Deficiencies:       Hazard:       Newl/Newly-Employed Experie         14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment:         Not Applicable:       First-Aid:       CP         16. Part 50 Document Control Number: (form 7000-1)         Victim Information:         1. Name of Injured/III Employee:       2. Sex       3. Victim'         5. Date(MIWDD/YY) and Time(24 Hr.) Of Death:	aced Miner:	Annual:	applicable) None:
13. Training Deficiencies:       Hazard:       New/Newly-Employed Experie         14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment:         Not Applicable:       First-Aid:       CP         16. Part S0 Document Control Number: (form 7000-1)         Victim Information:       1. Name of Injured/III Employee:       2. Sex       3. Victim'         5. Date(MM/DD/YY) and Time(24 Hr.) Of Death:         7. Regular Job Title:         10. Experience:       Years       Weeks       Days	aced Miner:	Annual:     Independent Contractor ID: (if Medical Professional:     Iffiliation of Victim: and Time Started: Years Week	9. Was this work activity part of regular job?
13. Training Deficiencies: Hazard:       Newl/Newly-Employed Experier         14. Company of Employment: (if different from production oper         15. On-site Emergency Medical Treatment: Not Applicable:       First-Aid:       CP         16. Part 50 Document Control Number: (form 7000-1)       Victim Information:       CP         10. Name of Injured/III Employee:       2. Sex       3. Victim'         5. Date(MM/DD/YY) and Time(24 Hr.) Of Death:       7. Regular Job Title:       10. Experience:       Years       Weeks       Days       b. Regular	aced Miner:	Annual:     Independent Contractor ID: (if Medical Professional:     Iffiliation of Victim: and Time Started: c: This Vears Week	9. Was this work activity part of regular job? Yes   No   Days d. Total
13. Training Deficiencies: Hazard:       Newl/Newly-Employed Experie         14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment: Not Applicable:       First-Aid:       CP         16. Part 50 Document Control Number: (form 7000-1)       Victim Information:       CP         16. Name of Injured/III Employee:       2. Sex       3. Victim'         5. Date(MM/DD/YY) and Time(24 Hr.) Of Death:       7. Regular Job Title:       Days         10. Experience:       Years       Weeks       Days         a. This       Uot Stridt       Job Title       Do Title	Aced Miner: Ace Miner Min	Annual:     Independent Contractor ID: (if Medical Professional:     Affiliation of Victim: and Time Started: and Time Started: Years Week Mine:	9. Was this work activity part of regular job?
13. Training Deficiencies: Hazard:       Newl/Newly-Employed Experier         14. Company of Employment: (if different from production oper         15. On-site Emergency Medical Treatment: Not Applicable:       First-Aid:       CP         16. Part 50 Document Control Number: (form 7000-1)       Victim Information:       CP         10. Name of Injured/III Employee:       2. Sex       3. Victim'         5. Date(MM/DD/YY) and Time(24 Hr.) Of Death:       7. Regular Job Title:       10. Experience:       Years       Weeks       Days       b. Regular	Aced Miner: Ace Miner Min	Annual:     Independent Contractor ID: (if Medical Professional:     Iffiliation of Victim: and Time Started: c: This Vears Week	9. Was this work activity part of regular job? Yes   No   Days d. Total
13. Training Deficiencies:       Hazard:       Newl/Newly-Employed Experie         14. Company of Employment: (If different from production oper       15. On-site Emergency Medical Treatment:         Not Applicable:       First-Aid:       CP         16. Part 50 Document Control Number: (form 7000-1)       Victim Information:       1. Name of Injured/III Employee:       2. Sex       3. Victim'         5. Date(MM/DD/YY) and Time(24 Hr.) Of Death:       7. Regular Job Title:       10. Experience:       Years       Weeks       Days       b. Regular         10. Experience:       Years       Weeks       Days       b. Regular         11. What Directly Inflicted Injury or Illness?       Job Titl       11. What Directly Inflicted Injury or Illness?	Aced Miner: Ace Miner Min	Annual:     Independent Contractor ID: (if Medical Professional:     Affiliation of Victim: and Time Started: and Time Started: Years Week Mine:	9. Was this work activity part of regular job? Yes   No   Days d. Total
13. Training Deficiencies: Hazard:       Newl/Newly-Employed Experie         14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment: Not Applicable:       First-Aid:       CP         16. Part 50 Document Control Number: (form 7000-1)       Victim Information:       CP         16. Name of Injured/III Employee:       2. Sex       3. Victim'         5. Date(MM/DD/YY) and Time(24 Hr.) Of Death:       7. Regular Job Title:       Days         10. Experience:       Years       Weeks       Days         a. This       Uot Stridt       Job Title       Do Title	aced Miner:     ator) R:   EMT:     17. Union A S Age 4. Degree of Injury: 6. Date 8. Work Activity when Injured: ar Years Weeks Days s:   12	Annual:     Independent Contractor ID: (if Medical Professional:     Affiliation of Victim: and Time Started: and Time Started: Years Week Mine:	9. Was this work activity part of regular job? Yes   No   Days d. Total
13. Training Deficiencies:         Hazard:       Newl/Newly-Employed Experie         14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment:         Not Applicable:       First-Aid:         16. Part 50 Document Control Number: (form 7000-1)         Victim Information:         1. Name of Injured/III Employee:       2. Sex         3. Victim'         5. Date(MIM/DD/YY) and Time(24 Hr.) Of Death:         7. Regular Job Title:         10. Experience:       Years         Work Activity:       Job Titl         11. What Directly Inflicted Injury or Illness?         13. Training Deficiencies:	Acced Miner: Accel	Annual:     Independent Contractor ID: (if Medical Professional:     dfiliation of Victim: and Time Started: and Time Started: Years Week Mine: 2. Nature of Injury or Illness: Annual:	applicable)       None:
13. Training Deficiencies:       Hazard:       New/Newly-Employed Experie         14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment:         Not Applicable:       First-Aid:       CP         16. Part 50 Document Control Number: (form 7000-1)         Victim Information:       2. Sex       3. Victim'         10. Experience:       2. Sex       3. Victim'         5. Date(MM/DD/YY) and Time(24 Hr.) Of Death:       7. Regular Job Title:         10. Experience:       Years       Weeks       Days         a. This       b. Regular Job Title:         13. Training Deficiencies:       Hazard:       NewlNewly-Employed Experience:         13. Training Deficiencies:       Hazard:       NewlNewly-Employed Experience:         14. Company of Employment: (If different from production oper       14. Company of Employment: (If different from production oper	Acced Miner: Accel	Annual:     Independent Contractor ID: (if Medical Professional:     fifiliation of Victim: and Time Started: and Time Started: Years Week c: This Week Mine: 2. Nature of Injury or Illness:	applicable)       None:
13. Training Deficiencies: Hazard:       New/Newly-Employed Experie         14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment: Not Applicable:       First-Aid:       CP         16. Part 50 Document Control Number: (form 7000-1)       Victim Information:       CP         16. Part 50 Document Control Number: (form 7000-1)       Victim Information:       2. Sex       3. Victim'         5. Date(MWDD/YY) and Time(24 Hr.) Of Death:       7. Regular Job Title:       0. Experience:       Years       Weeks       Days       b. Regu         10. Experience:       Years       Weeks       Days       b. Regu         work Activity:       Job Titl       11. What Directly Inflicted Injury or Illness?       13. Training Deficiencies:         Hazard:       New/Newly-Employed Experi       14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment:       14. Company of Employment: (If different from production oper	Age 4. Degree of Injury: 6. Date 6. Date 7. Weeks Days 7. Union 4. The format of the second	Annual:     Independent Contractor ID: (if Medical Professional:     Affiliation of Victim: and Time Started: and Time Started: C: This Week Mine: 2. Nature of Injury or Illness: Annual:     Independent Contractor ID: (if a	applicable)         None:         9. Was this work activity part of regular job?         Yes       No         Days       Years       Weeks         Mining:       Years       Years         Task:
13. Training Deficiencies: Hazard:         New/Newly-Employed Experie         14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment: Not Applicable:         First-Aid:         CP         16. Part 50 Document Control Number: (form 7000-1)       Victim Information:       CP         16. Part 50 Document Control Number: (form 7000-1)       Victim Information:       2. Sex       3. Victim'         5. Date(MWDD/YY) and Time(24 Hr.) Of Death:       7. Regular Job Title:       0. Experience:       Years       Weeks       Days       b. Regu         10. Experience: Years       Years       Weeks       Days       b. Regu         work Activity:       Job Titl       11. What Directly Inflicted Injury or Illness?       13. Training Deficiencies:         Hazard:         New/Newly-Employed Experi       14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment:       Not Applicable:         First-Aid:         ()	Acced Miner: Accel	Annual:     Independent Contractor ID: (if Medical Professional:     dfiliation of Victim: and Time Started: and Time Started: Years Week Mine: 2. Nature of Injury or Illness: Annual:	applicable)       None:
13. Training Deficiencies: Hazard:       New/Newly-Employed Experie         14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment: Not Applicable:       First-Aid:       CP         16. Part 50 Document Control Number: (form 7000-1)       Victim Information:       CP         16. Part 50 Document Control Number: (form 7000-1)       Victim Information:       2. Sex       3. Victim'         5. Date(MWDD/YY) and Time(24 Hr.) Of Death:       7. Regular Job Title:       0. Experience:       Years       Weeks       Days       b. Regu         10. Experience:       Years       Weeks       Days       b. Regu         work Activity:       Job Titl       11. What Directly Inflicted Injury or Illness?       13. Training Deficiencies:         Hazard:       New/Newly-Employed Experi       14. Company of Employment: (If different from production oper         15. On-site Emergency Medical Treatment:       14. Company of Employment: (If different from production oper	Inced Miner:         Image: Image	Annual:     Independent Contractor ID: (if Medical Professional:     Affiliation of Victim: and Time Started: and Time Started: C: This Week Mine: 2. Nature of Injury or Illness: Annual:     Independent Contractor ID: (if a	applicable)         None:         9. Was this work activity part of regular job?         Yes       No         Days       Years       Weeks         Mining:       Years       Years         Task:

MSHA Form 7000-50b, Mar 2008

Printed 03/13/2013 1:52:51 PM


# **APPENDIX D** Overall Sketch of Accident Scene

e



# **APPENDIX E**

Detailed Sketch of Accident Scene



Not To Scale

•