Preliminary Report of Accident

2. Accident Classification

Fall of Face, Rib, Pillar or Highwall

b) Mine Name

GHM #51

U.S. Department of Labor Mine Safety and Health Administration

03/30/2017 02:09 AM

4. Date/Time of Death

c) Parent of Mining Company

Laird T Orr Jr.

7. Mine Location : a) City b) County c) State 8. Mine ID Number: 9. Union: 44-07079 Rockholds Whitley KΥ NO 10. Primary Mineral Mined: 11. Number of Mine b) Underground c) Open Pit/Quarry d) Mill/Prep Plant e) Other a) Total **Employees:** BITUMINOUS 5 0 0 0 12. Contractor Name: 13. Union 14. Contractor ID Number: 15. Contractor Address: a) City b) County c) State d) Zip Code 16. Number of Contractor Employees: a) Total b) Underground c) Open Pit/Quarry d) Mill/Prep Plant e) Other 17. Number of Persons in Mine at Time of Accident: 18. Number of Persons Unaccounted For:

3. Date/Time of Accident

03/30/2017 02:09 AM

a) Mine Employees: 2			b) Contractor Employees:			0	a) Mine Employees: 0		0	b) Contractor Employ		es:	0	1		
19) Location of Ac				—	F	-				_			í	20. Min	ing Heig	ht:
01-Underground		03-Open Pit			dvance Mi	30-Mill/Prep Plant			X Other (specify)		Feet	Inches	i			
02-Surface at Underground		06-Dredge Mi	ning	08-Retreat M		ing	99-Office Facility		lity	Surface Auger Oper		54	0			
21. Nonfatal Injuries:			22. Fatal Injuries:													
		0			1											
23. Victim Information :		a) Name			b) Age											
				Joseph W. Partin				33								
c) Regular Job Title:				d) Activity at Time of Accident:				X Mine Em				Emplo	oloyee			
Auger Operator/Foreman				Auger Operator										•		
24. Experience : Years Weeks Days				ys Years Weeks D				Days	ys Years Weeks Days							
a) Total:	8	0	0	b) at the mine:	0 12	0	c) at acti	vity (23d)	1	0	0	d) with Contractor	C	0 (0	
25. Autopsy Performed: If Yes, Location								26. Mii	ne Telephone No.:							
YES Frankfort, Kentucky							(606) 521-1061									

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

While changing worn cutter head bits at the front of the Salem Multi-head coal auger machine, a Foreman was struck by a rock approximately 4 feet by 5 feet by 30 inches that fell from the bottom section of the highwall. The Whitley County coroner pronounced the victim deceased at the scene. An accident investigation is being conducted by MSHA and in conjunction with the Kentucky Division of Mine Safety (KDMS).

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufa	cturer: Salem	(McCarthy)	29. Model: Multi-head					
30. District: C0700	Barbourville	32. Field Offic	e: Barbourville KY		33. Event Number: 4454202			
34. Accident Investigate David A. Faulkne		•	35. MSHA Person Notified: William B. Sears		Date 03/30/2017	Time 02:45 AM		
36. Type of Report:	Amended	37. Name of Preparer a	nd Date Prepared: David A. Faulkner		Date 04/05/2017			

38. Reason For Amendment:

Modified Item 3, 4, and 19 based on new information obtained

PR001 06-Apr-17

1. Accident Type:

Fatal Injury

6. Mine Information : a) Mining Company Name

Green Hill Mining Inc



0

5. Fatal Case No

4