Preliminary Report of Accident PR001 06/18/2019

U.S. Department of Labor Mine Safety and Health Administration



1. Accident Type F - Fatal Injury	2. Accident Classification 12 - Powered Haulage	3. Date/Time of Accident 06/10/2019 11:10 AM	4. Date/Time of Death 06/10/2019 11:10 AM	5. Fatal Case No
6. Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	Vulcan Construction Materials, LI River Road Quarry Vulcan Materials Company	_c		
7. Mine Location Information a) City Brentwood	b) County Davidson	c) State TN	8. Mine ID Number 40-00104	9. Union No
10. Primary Mineral Mined 11. Number of Employees				
		a) Total b) Underg	ground c) Open Pit/Quarry	d) Mill/Prep Plant e) Other
12. Contractor Name Premier Power Professionals, le	nc.		13. Contractor Union Yes	14. Contractor ID Number L058
15. Contractor Address				
a) City Racine	b) County	c) State WI	d) Zip Code 53404	
16. Number of Contractor Employ a) Total	yees b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant 13	e) Other
17. Number of Persons in Mine at Time of Accident a) Mine Employees b) Contractor Employees 10 18. Number of Persons Unaccounted for a) Mine Employees b) Contractor Employees 0 0				
19. Accident Location 30 - Mill/Prep Plant		:		20. Mining Height Feet Inches
21. Nonfatal Injuries	22. Fatal Injuries			1
23. Victims Information	I			
0.111.0				
Collin Sawasky				
'		r Job Title d) Activity at Tir tice Electrician Leveling trend		Employee Contractor Employee
24. Mining Experience a) Total Experience b) Experience at the Mine 3 Years 8 Weeks Days C) Experience at the Activity at the Time of the Accident 3 Years 8 Weeks Days 3 Years 8 Weeks Days 3 Years 8 Weeks 0 Days				
25. Autopsy Performed If Yes, Location				
26. Mine Telephone No.				
(615) 352-0371	-d	la anti-ra to the order and at the con-		
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) The victim was leveling material in a trench made for laying electrical conduit for new plant construction while the Plant Manager was operating a Wacker Neuson WL 36 front-end loader above. The front-end loader was being used to back fill the trench when the bank collapsed causing the front-end loader to slide into the trench. The victim was fatally injured when he was pinned between the front-end loader and a jersey block.				
The information provided in this the cause of the accident.	s notice is based on preliminary data	ONLY and does not represent final de	termination regarding the nature of th	ne incident or conclusions regarding
28. Equipment Manufacturer Not listed Wacker Neuson		29. Model WL 36		
30. District M3000 - Southeast District - Bir	rmingham	32. Field Office M3811 - Franklin TN Field Offic	ee	33. Event Number 6848215
34. Accident Investigator		!		!
First Name Rory	MI Last Name M Smith			
35. MSHA Person Notified				
First Name	MI Last Name	Date/Time No		
David	H Allen	06/10/2019 11	:31 AM	
36. Type of Report Initial	37. Name of Preparer Full Name	Date Prepared		
	David H. Allen	06/11/2019		