

Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration



PR001 10/15/2020

1. Accident Type F - Fatal Injury		2. Accident Classification 12 - Powered Haulage		3. Date/Time of Accident 10/13/2020 8:37 PM		4. Date/Time of Death 10/13/2020 10:30 PM		5. Fatal Case No FAI-6484525-1	
6. Mine Information									
a) Mining Company Name:		Warrior Coal LLC							
b) Mine Name:		Cardinal							
c) Parent of Mining Company:		Alliance Resource Partners LP							
7. Mine Location Information						8. Mine ID Number		9. Union	
a) City MADISONVILLE		b) County Hopkins		c) State KY		15-17216		No	
10. Primary Mineral Mined Bituminous Coal Underground Mining				11. Number of Employees			d) Mill/Prep Plant		e) Other
				a) Total 438	b) Underground 402	c) Open Pit/Quarry	30		6
12. Contractor Name						13. Contractor Union		14. Contractor ID Number	
15. Contractor Address									
a) City		b) County			c) State			d) Zip Code	
16. Number of Contractor Employees									
a) Total		b) Underground			c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other
17. Number of Persons in Mine at Time of Accident				18. Number of Persons Unaccounted for					
a) Mine Employees 123		b) Contractor Employees 6		a) Mine Employees 0		b) Contractor Employees 0			
19. Accident Location 07 - Advance Mining								20. Mining Height 5 Feet 5 Inches	
21. Nonfatal Injuries 0		22. Fatal Injuries 1							
23. Victims Information									
Phillip T Ramsey									
a) First Name Phillip	a) MI T	a) Last Name Ramsey		b) Age 58	c) Regular Job Title Shuttle Car Operator		d) Activity at Time of Accident Shuttle Car Operator		Employee Mine Employee
24. Mining Experience									
a) Total Experience 30 Years 0 Weeks 0 Days		b) Experience at the Mine 2 Years 0 Weeks 0 Days		c) Experience at the Activity at the Time of the Accident 2 Years 0 Weeks 0 Days			d) Experience with Contractor 0 Years 0 Weeks 0 Days		
25. Autopsy Performed		If Yes, Location							
26. Mine Telephone No. (270) 249-3100									
27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations) A miner died from his injuries after being struck by a battery-powered scoop. The victim had parked his shuttle car in an intersection when a scoop went through a curtain in an adjacent crosscut and struck the victim exiting his shuttle car. <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>									
28. Equipment Manufacturer Not listed DBT				29. Model 488					
30. District C1000 - Madisonville District				32. Field Office C1001 - Madisonville KY Field Office				33. Event Number 6484525	
34. Accident Investigator									
First Name Matthew		MI B.	Last Name Stone						
35. MSHA Person Notified									
First Name Randall		MI T	Last Name Boyd			Date/Time Notified 10/13/2020 9:19 PM			
36. Type of Report Initial		37. Name of Preparer			Date Prepared				
		Full Name William L Barnwell			10/14/2020				
38. Reason for Amendment									