

APPENDIX AD

**BELT EXAMINATION BOOK
(3/16/2010 TO 4/1/2010)**

STARTED 3-16-10

Finished 4-1-10

EXAMINATION OF BELT CONVEYORS

COMPANY Performance Coal

MINE Upper Big Branch

LOCATION NAOMA WV Raleigh WV
Post Office County State

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-16-10 SHIFT: EVE AM OR PM TO 800 AM OR PM TO 1100 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes X No By Whom SKAGGS Campbell Time 1045 AM or PM

Report received by: Alan Miller
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
Ellis #4	needs Dusted	GU	✓		
Ellis #5	Needs spot cleaned, 27-Tail + 7-3, needs Ask	GU	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Takeup needs Add cleaning, Needs Dusted	GU	✓		
NORTH NO. 5	none observed	GU	✓		
NORTH NO. 6	needs Dusted, needs cleaned 87-Tail	BC	✓		
NORTH NO. 7	needs Dusted, Rib Roll 128 Brk, Damaged off	BC	✓		
LIWALL	Belt needs Dusted, Hd and Drives needs cleaned	JS	✓		
GLORY HOLE	D-Box Pump OK	WC	✓		
HG 22 #1	needs cleaned & dusted	JS	✓		
TG 22 #1	needs cleaned & dusted NEEDS CROSS OVER.	JS	—		
TG 22 #2	needs Dusted	JS	—		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OGCH4, OG CO, 20.8202

PC's, Chassis, D-Boxes, Track, Trave ways OK

SIGNED BY: Alan Miller 15397 William Campbell 13544

Belt Examiners and Certificate Numbers

Alan Miller 32476

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33357

Mine Foreman

Certificate No.

Superintendent

Certificate No.

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-16-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
NORTH 3		
NORTH 4	Ran Ouster at Drives, cleaned at Head Area	CU
NORTH 5	cleaned adjusted Fbw threw	CU
NORTH 6		
NORTH 7		
GLORY HOLE		

Checked outby Refuges 6,8,89 all OK

SIGNED BY:

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

T. Moore33354

Mine Foreman

Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-17-10 SHIFT: owl AM OR PM TO 300 AM OR PM TO 600 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes X No By Whom SKAGGS, Cambo II Time 530 AM or PM

Report received by: Renell

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
ELLIS 4	Needs Dusted	GU	—		
ELLIS 5	Needs Dusted, Needs Cleaned 27-Tail	GU	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Dusted Hd-258K Takep needs Add cleaning	GU	—		
NORTH NO. 5	Needs spot Dusted	GU	✓		
NORTH NO. 6	Needs Dusted, 87-Tail Needs Cleaned	WC	✓		
NORTH NO. 7	Needs Dusted/ Dangerous off at 12 88K Need 8 Jacks set	WC	✓		
EWING 11	Needs Dusted Drives and Hd wet & muddy	JS	✓		
GLORY HOLE	D-Box Pump OK	WC	✓		
LBB NO. 1					
LBB NO. 2					
H622	Needs cleaned & dusted	JS	—		
T622 #1	Needs cleaned & dusted	JS	—		
T622 #2	Needs Dusted	JS	—		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: 2 VIBRATORS

OG CH4 OG CO 20.8202

PCS, CHARGES, D-Boxes, Travelings OK

SIGNED BY: William Campbell 1354A Johnny Neely 33472
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359
Mine Foreman Certificate No.

Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Report received by: _____

Checked out by Refuges 6-8-89 all clear

46543—BJW Printing & Office Supplies

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-17-10 SHIFT Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☒ No ☐ By Whom J. Neely Time 250 AM or PM

Report received by: John A. Bickford 26176
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs dusted</u>	<u>JAB</u>	☒		
<u>Ellis 5</u>	<u>Needs dusted, Needs cleaned 27 to tail</u>	<u>JAB</u>	☒		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Take up needs add'l cleaning</u>	<u>JAB</u>	☒		
NORTH NO. 5	<u>Needs dusted Head to 20 Pul</u>	<u>JAB</u>	☒		
NORTH NO. 6	<u>Needs spot dusted</u>	<u>JAB</u>	☒		
NORTH NO. 7	<u>Needs cleaned, Needs cleaned 87th tail</u>	<u>JAB</u>	☒		
<u>Log Wall</u>	<u>Tail Needs Add Cleaning</u>	<u>SH</u>	☒		
<u>GLORY HOLE</u>	<u>Needs dusted, Dried off 128 Pul, Note Jack</u>	<u>SH</u>	☒		
	<u>DRIVE Needs Cleaned, Wet, Muddy, Belt needs Dusted</u>	<u>SH</u>	☒		
	<u>Pump & D'Box OK</u>	<u>SH</u>	☒		
LBB NO. 1					
LBB NO. 2					
<u>HG 22</u>	<u>Needs cleaned & dusted</u>	<u>JN</u>	☒		
<u>TG 22 #1</u>	<u>Needs cleaned & dusted</u>	<u>JN</u>	☒		
<u>TG 22 #2</u>	<u>None Observed</u>	<u>JN</u>	☒		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

Otoch4, O% CO + 20.8% O2 detected at time of exam.

Track, Travelways, PC's, chagers, D'Box's & Pumps
clear at time of exam

SIGNED BY: John A. Bickford 26176
Belt Examiners and Certificate Numbers

Allen Williams 15357

Scott Holstad 37567

J. Neely 22476

COUNTERSIGNED BY: T. Mance
Mine Foreman

33357
Certificate No.

Superintendent

Johnny Neely 33472
Certificate No.

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-17-10 SHIFT Day AM OR PM TO AM OR PM TO AM OR PM TO AM OR PM TO
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

BELTS	ACTION TAKEN	INT.
ELLIS 4	cleaned tail & Greased tail / Bobby	
ELLIS 5	cleaned tail & Greased tail / Bobby 7-12 5 pay cleaned	
NORTH 2		
NORTH 3		
NORTH 4	Cleaned at V. Plow	JAB
NORTH 5	Cleaned at flow thru	JAB
NORTH 6	Cleaned at tail	JAB
NORTH 7	cleaned on tail, Greased tail Roller	SH
NORTH 8	cleaned on Mud at Drive, Greased Drive Rollers	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
HG 22	Rock Dust from Drive Across both over cast Grease Drive	JN
TG 22#1	Dust from Discharge to Drive Dust off PCs	JN

Checked Refuges at 6, 8 + 89 Bels - OK, Phones - OK

SIGNED BY: John A. Buckford 26176
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 35359
Mine Foreman Certificate No.

Scott Halstead 37567
Johnny Kelly 33472
Superintendent Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAM. PRE-SHIFT EXAM.

Report received by: _____

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

06 CNY 061020.8202

PC's Charges O-Bears Transmissions

Belt Examiners and Certificate Numbers

[Signature]

Belt Examiners and Certificate Numbers

T. J. McNamee
Mine Foreman

Certificate No.

Superintendent

Certificãte No.

John A. Beckford 21176

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-17-10 SHIFT: EVE 6:00 AM OR PM TO 8:00 AM OR PM ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	<u>cleaned URB</u>	
NORTH 6		
NORTH 7	<u>set Jacks</u>	<u>CU</u>
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refuges 6-8890K

SIGNED BY: De Mh 1537A

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33359

Mine Foreman

Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-18-10 SHIFT: Day AM OR PM TO 600 AM OR PM TO 810 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☒ No ☐ By Whom _____ Time _____ AM or PM

Report received by: E. Hager Signed _____

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
4 FH15	needs spot dand dusted	MARVIN PERDUE	☒		
5 FH15	Clear called out by Russell Gunnore				
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	needs dusted head to take up add clearing ^{and to make don't}	BICKFORD	☒		
NORTH NO. 5	Tail needs add clearing called out by Russell Gunnore		☒		
NORTH NO. 6	needs spot dand dusted called out by Scott Haddock		☒		
NORTH NO. 7	7 north Belt + constructing area clear ^{called out}	Miller Kiplinger	☒		
WALL	63 spot to 63.50 needs spot dand dusted called out by Tim Davis				
GLORY HOLE	Clear + intake room				
LBB NO. 1					
LBB NO. 2					
HG 22	needs spot dand dusted	DEAN JONES			
TG 22 #1	needs spot dand dusted called out by Jeremy Burdett		☒		
TG 22 #2	Tail needs clear called out by JEREMY BURDET		☒		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH4 0% CO 20.6% O2

CHARGERS, POWER BOXES, TRAVELWAYS OK

SIGNED BY: M. K. Hager 33017

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Hager

Mine Foreman

33389

Certificate No.

Scott Haddock 37567

Jeremy Burdett 37567

E. Hager

Superintendent

26041

Certificate No.

7 North Road 37004

Use Indefinite Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3/18/10 SHIFT: 15T 6 AM OR PM TO AM OR PM TO AM OR PM TO AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☒ No ☐ By Whom _____ Time _____ AM or PM

Report received by: Eltagur Signed _____

BELTS	ACTION TAKEN	INT.
VENIS SOUTH 1	check for tail & groove tail shove 70 1 3/4 Bkt. Bots	
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	AGBK refuge clear called out by John Bickford	
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2	8 + 89 refuge clear called out by Scott Halstead	

SIGNED BY:

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

Mine Foreman

Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-18-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☒ No ☐ By Whom John Bickford Time 2:15 AM or PM ☒

Report received by: Russell Dunne
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Dusted, Needs spot cleaned 27-Tail	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up needs add. cleaning Needs cleaned Discharge to overcasts	RG	✓		
NORTH NO. 5	tail needs Added Cleaning	SH	✓		
NORTH NO. 6	Needs Spot Cleaned, Belt needs Dusted	SH	✓		
NORTH NO. 7	Needs cleaned & Dusted	JAB	✓		
Long Wall	Wet & Muddy DRIVE AREA Needs Cleaned, Belt needs Dusted	SH	✓		
GLORY HOLE	D-Box & Pump OK	JAB	✓		
T622NO.1	Needs spot cleaned & Dusted	JAB	✓		
T622NO.2	None Observed	JAB	✓		
HG22	Needs cleaned & Dusted.	JAB	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 20.8% O₂, 0ppm CO Detected at EXAM time
Powercenters, D-Box's, Changers, TRACK & TRAVELWAYS Clear at EXAM
Visual CK of C.O. Monitors Clear at EXAM

SIGNED BY: Scott Halstead 37567
Belt Examiners and Certificate Numbers

Russell Dunne 1536-A
Belt Examiners and Certificate Numbers

John Bickford 26171

John May 32475

COUNTERSIGNED BY T. Moore

Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-18-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☐ No ☐ By Whom _____ Time _____ AM or PM

Report received by: _____

Signed _____

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow	
Ellis 5		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	cleaned V-Plow at flow thru	SH
NORTH 6	cleaned V-Plow, cleaned at tail of QB	SH
NORTH 7		
Long wall	cleaned on Mud, Ran Duster	SH
GLORY HOLE		
TG-22 NO. 1	cleaned on Walkway & at tail	SAB
TG-22 NO. 2		
HG-22		

CKd Refuge Chambers 6, 8, 89 BK OK at EXAM
 All Phones Working

SIGNED BY: Russell Gunnar 1536-19

Belt Examiners and Certificate Numbers

John R. Buckner 2617

Belt Examiners and Certificate Numbers

Scott Halstead 37567

COUNTERSIGNED BY: T. M. Mone

Mine Foreman

33389
 Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes No ✓ By Whom Time AM or

Signed _____

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

0% CH₄ 0% CO 20.8% O₂

TRAILWAYS, TRACK AND POWER CENTERS OK AT TIME OF EXAM

Belt Examiners and Certificate Numbers

Mine Foreman

Superintendent

Certificate N

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3.18 SHIFT: EVE 6:00 AM OR PM TO 6:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	REPLACED WATER VALVE AT TAIL	60/JS
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

CHK REFUGE BOXES AT 8, 6, 89 OK AT TIME OF EXAM
ALL PHONES WORK

SIGNED BY: *John D. [Signature]* 32476
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY *T. M. [Signature]*
Mine Foreman

33359
Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-19-10 SHIFT: OWL AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
SOUTH NO. 1	NEEDS DUSTED	SW	✓		
NORTH NO. 1	NEEDS SPOT CLEANED AND DUSTED	SW	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	NEEDS CLEAN & DUSTED TAKEUP NEEDS CLEAN	SW	✓		
NORTH NO. 5	TAIL NEEDS CLEAN	SW	✓		
NORTH NO. 6	NEEDS SPOT CLEAN & DUSTED	JS	✓		
NORTH NO. 7	NEEDS DUSTED	JS	✓		
NORTH NO. 8					
GLORY HOLE	D-Box AND Pump OK.	JS	✓		
LBB NO. 1					
LBB NO. 2					
H/220	NEEDS CLEAN AND DUSTED	JS	✓		
LW	NEED SPOT CLEANED & DUSTED	JB	✓		
T6*22*1	NEEDS CLEAN AND DUSTED	JS	✓		
T6*22*2	NONE OBSERVED	JS	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄ 0% CO 20.8% O₂

TRAVELWAYS AND TRACKS OK AT TIME OF EXAM

SIGNED BY:

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Russell Dummar 1536-A John B. Bickel 26176

Scott Halstead
32567

Use Indellible Pencil or Ink

Was this report phoned to outside Yes___No___ By Whom_____ Time_____ AM or PM

Signed

[illegible]

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

Mine Foreman

Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-19-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☒ No ☐ By Whom John Bickford Time 2:00 AM or PM

Report received by: Russell Gunnar
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs spot cleaned 27-29, + Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned 29-Tail, Needs cleaned ^{Drive} Discharge	RG	✓		
NORTH NO. 5	tail needs cleaned	SH			
NORTH NO. 6	Needs Some Spot Cleaning, Needs Dusted	SH	✓		
NORTH NO. 7	Needs dusted	JAB	✓		
Longwall	mother Drive Area Needs Cleaned, Belt needs Dusted	SH	✓		
GLORY HOLE	D-Box + Pump OK	JAB	✓		
TG-22 NO. 1	Needs cleaned + Dusted	JAB	✓		
TG-22 NO. 2	Needs Last set up needs dusted	JAB	✓		
HG-22	Needs cleaned + Dusted	JAB	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

0% CH₄, 20.8% O₂, 0ppm CO at time of exam
 Tramways, Power Centers, D-Boxes, chargers OK at time of exam
 Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Gunnar 1536-A

Belt Examiners and Certificate Numbers

John Bickford 21171

Belt Examiners and Certificate Numbers

Scott Halstead 37567

COUNTERSIGNED BY T. Munro

Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-19-10 SHIFT: Day 6:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Cleaned from 32-33BK Shoveled V-plow S Hoveled Tail & Greased Tail / Bobby	RG
Ellis 5	Shoveled V-plow	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on Tail, RAN dusters at Tail + Drives	RG
NORTH 5	cleaned V-Plow, Cleaned on Tail SAB	SH
NORTH 6	Cleaned + dusted at Tail	SAB
NORTH 7		
Longwall	cleaned on Mud at Mother drive	SH
GLORY HOLE		
TG22NO. 1		
TG22NO. 2	Cleaned at tail	SAB
HG-22		

Refuge chambers at 6, 8th, 8 back 2 seat OK + phones working
at time of exam

SIGNED BY: Russell Guma 1536-A

Belt Examiners and Certificate Numbers

John A. Bullard 26176

Belt Examiners and Certificate Numbers

Seth Holstad 37567

COUNTERSIGNED BY T. Moore

Mine Foreman

33389
Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-19-10 SHIFT: EVC 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 11:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
E11.5#4	needs Dusted	GU	✓		
E11.5#5	needs cleaned 27-29 Needs Dusted	GU	✓		
Long wall	Henderson needs cleaned; belt needs Dusted	BC	✓		
NORTH NO. 3					
NORTH NO. 4	needs spot cleaned 29-tail Drives + Discharge needs cleaned	GU	✓		
NORTH NO. 5	tail needs cleaned	GU	✓		
NORTH NO. 6	needs spot cleaned & Dusted	GU	✓		
NORTH NO. 7	needs Dusted	BC	✓		
H622 #1	needs cleaned & Dusted	BC	✓		
GLORY HOLE	D-Box & Pump - Clear	BC	✓		
H622 NO. 1	needs cleaned & Dusted	BC	✓		
H622 NO. 2	Needs Dusted	BC	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 0 ppm CO, 20.8% O₂ Detected
 TRAC/Travelways, LHA, PCs, Pumps, D-Box's choppers, and
 visual check of CO monitors - all clear at Exam

SIGNED BY:

Walter Campbell 1354-A
 Belt Examiners and Certificate Numbers

Don Williams 1539-A
 Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

T. M. Morris
 Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

Use Indefible Pencil or Ink

Was this report phoned to outside Yes___ No___ By Whom_____ Time_____AM or PM

Signed

Checked Outby Refuges at #6, 8, 9 Trks all clear at Exam & phones are working

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

Mine Foreman

Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-20-10 SHIFT: owl AM OR PM TO 306 AM OR PM TO 6:00 PM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
NO. 1	Needs Dusted	GU	✓		
NO. 2	Needs cleaned & Tail needs Dusted	GU	✓		
NO. 3	Head Needs cleaned Belt needs Dusted	BC	✓		
NORTH NO. 4	Needs spot cleaned & Tail Head needs cleaned	GU	✓		
NORTH NO. 5	Tail needs cleaned	GU	✓		
NORTH NO. 6	Needs spot cleaned & Dusted	GU	✓		
NORTH NO. 7	Needs Dusted	BC	✓		
H622 NO. 1	Needs cleaned and Dusted	BC	✓		
GLORY HOLE	D-Box & Pump clear at Exam	BC	✓		
H622 NO. 1	Needs cleaned & Dusted	BC	✓		
H622 NO. 2	Needs added dusting	BC	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 0 ppm CO, 20.8% O₂ Detected
TRAIL/Trajectory, D-Box & KVIA's, Pumps, Pul's, and a visual
check of CO monitor clear at Exam.

SIGNED BY:

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY:

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-20-10 SHIFT: W 100 AM OR PM TO 300 AM OR PM TO AM OR PM
ON-SHIFT EXAM. **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
E/PS 4		
E/PS 5	change roller LC	
L. W. H.	change roller LC, Dusting on	
NORTH 4	change roller LC	
NORTH 5	change roller LC	
NORTH 6	Shoveled V plow	BC
NORTH 7	Shoveled V plow	BC
H622 #1		
GLORY HOLE		
T622 NO. 1		
T622 NO. 2		

checked out by Refrags 6-889 ok

SIGNED BY: [Signature] 1639A

Belt Examiners and Certificate Numbers

[Signature] 1354A

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore

Mine Foreman

33357

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Report received by: John H. Bickford 28176
Signed

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

Track, transducer, PC's, chargers, pumps & D. Bot's
clean at time of exam

46543—BJW Printing & Office Supplies

Mine Foreman

Certificate No.

Superintendent

Certificate No.

1. John Campbell 7250-1

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-20-10 SHIFT: Day AM OR PM TO AM OR PM TO AM OR PM TO AM OR PM TO
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by: Signed

BELTS	ACTION TAKEN	INT.
ELLIS 4	Cleaned at Tail & V' Plow	JAB
ELLIS 5	Cleaned at V' Plow	JAB
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Cleaned at V' Plow & Tail	JAB
NORTH 6	Cleaned at Tail	JAB
NORTH 7	cleaned on tail Raw Duster	SH
Log Wall	cleaned on Mud at Motherdrive	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
TAILGATE 22#1	CLEAN TAIL Piece	JN
HG 22#1	clean spillage of Discharge, Dust & Grease	JN

Checked Refuges 6, 8 & 89 Brks: OK Phone OK - 8 & 89

Refuge #6 Phone not Paging

SIGNED BY: John G. Bickford 28176
Belt Examiners and Certificate Numbers

Scott Halstead 37567
Johnny Neely 33472

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore

33389
Certificate No.

Mine Foreman

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes___ No___ **By Whom**_____ **Time**_____ **AM or PM**

Signed

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

0% CH₄, 0 ppm CO, 20.8% O₂ Detected

Trail/Travelways, KVA's, D 730's, Chargers, Pumps & Power centers
clear at Exam, Give a visual check of CD monitors clear at
Exam,

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

Mine Foreman

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes___ No___ By Whom___ Time___ AM or PM

Signed

Checked Outby Refugees at 6,8,89 brks - all clear, phones working

Belt Examiners and Certificate Numbers

Don Allen 1530A
Belt Examiners and Certificate Numbers

Mine Foreman

333.07
Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-21-10 SHIFT: 061 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
<u>2118 NO. 4</u>	<u>needs Dusted</u>	<u>GU</u>	<u>✓</u>		
<u>2118 NO. 5</u>	<u>needs added cleaning 27-29 brk, need Dusted</u>	<u>GU</u>	<u>✓</u>		
<u>NO. 6</u>					
<u>Longwall NO. 7</u>	<u>Belt needs spot cleaned</u>	<u>BC</u>	<u>✓</u>		
<u>NORTH NO. 4</u>	<u>Mother Drive needs cleaned</u>	<u>GU</u>	<u>✓</u>		
<u>NORTH NO. 5</u>	<u>needs spot cleaned 29 tail</u>	<u>GU</u>	<u>✓</u>		
<u>NORTH NO. 6</u>	<u>Drives - Discharge needs cleaned</u>	<u>GU</u>	<u>✓</u>		
<u>NORTH NO. 7</u>	<u>needs added cleaning at Take up</u>	<u>BC</u>	<u>✓</u>		
<u>NORTH NO. 8</u>	<u>needs spot cleaned at tail 87 tail & need Dusted</u>	<u>BC</u>	<u>✓</u>		
<u>NORTH NO. 9</u>	<u>needs dusted</u>	<u>BC</u>	<u>✓</u>		
<u>H622 #1</u>	<u>needs cleaned & Dusted</u>	<u>BC</u>	<u>✓</u>		
<u>GLORY HOLE</u>	<u>D-Box & Pump none observed</u>	<u>BC</u>	<u>✓</u>		
<u>T622 NO. 1</u>	<u>IDLE</u>	<u>BC</u>	<u>✓</u>		
<u>T622 NO. 2</u>	<u>IDLE</u>	<u>BC</u>	<u>✓</u>		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 0% ppm CO, 20.8% O₂ detected
TRACK/Travelways, KVIA's D-130's, Power center & Pump
clean at Exam, Visual check of CO's all clear at
Exam

SIGNED BY:

William Campbell 135412 Johnny Nelly 33472

Belt Examiners and Certificate Numbers

John Williams 15291

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore

Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes___ No___ By Whom_____ Time_____ AM or PM

Signed

Checked Out by Refugee at 6.8.89 looks all clear at Exam
and Phones are working

Belt Examiners and Certificate Numbers

Don. Allen 1536
Belt Examiners and Certificate Numbers

Mine Foreman

Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-21-10 SHIFT: _____ AM OR PM TO _____ AM OR PM 12:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☒ No _____ By Whom J. Neely Time 2:30 AM or PM

Report received by: John A. Bickford
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
ELLIS NO. 4	Needle ducted	JAB	✓		
ELLIS NO. 5	Needle ducted; Needle cleaned 27-29 Bsk	JAB	✓		
NORTH NO. 2					
NORTH NO. 3		JAB	✓		
NORTH NO. 4	Needle cleaned 29 to tail Drive to head needle add'l cleaning	JAB	✓		
NORTH NO. 5	Needle add'l cleaning at take-up & tail	JAB	✓		
NORTH NO. 6	Needle ducted & spot cleaned	JAB	✓		
NORTH NO. 7	Needle ducted	JN	✓		
LG Hall	Needle spots Ducted mld needle cleaned & cleaned	TD	✓		
GLORY HOLE	Pump & D'Box - OK	JN	✓		
TO 22 NO. 1	Falle PCs OK	JN			
TO 22 NO. 2	Falle PCs - OK	JN			
AG 22 #1	Needle cleaned & ducted	JN	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

070ch4, 070CO & 20.8% O2 detected at time of exam

Visual check of COs - OK

Track, travelways, PCs, chargers & Pump & D'Box's
clear at time of exam

SIGNED BY:

John A. Bickford 26176 Jim Davis 38322
Belt Examiners and Certificate Numbers

Johnny Neely 33472 John Davis 32476
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Murre

Mine Foreman

33357

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-21-10 SHIFT Day AM OR PM TO AM OR PM TO AM OR PM TO AM OR PM TO
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ___ No ___ By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
E4415 4	cleaned at V Plow	516
E4415 5	cleaned at V Plow	516
NORTH 2		
NORTH 3		
NORTH 4	cleaned at V Plow	516
NORTH 5	cleaned at V Plow & tail & floor thru	JN 516
NORTH 6	cleaned at tail	516
NORTH 7		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
H6221	cleaned Rib Rolls Dust around PC's trim splices	JN

Checked Refuges 6, 8 & 89 Bkrs. - OK; Phones OK

SIGNED BY:

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

T. Moore

Mine Foreman

33357

Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-21-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Brought out Time AM or PM

Report received by:

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
Eff. 1/3 #1	needs Dusted	BC	✓		
Eff. 3/5 #2	needs cleaned 27-29hrc, needs Dusted	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	needs cleaned from Drives - Discharge needs spot cleaned Tail needs added cleaning, from 32-tail	BC	✓		
NORTH NO. 5	Take up needs added cleaning	BC	✓		
NORTH NO. 6	need Dusted, needs spot cleaned from 87-tail & disl. out	BC	✓		
NORTH NO. 7	needs Dusted	BC	✓		
*Horry with #8	Mother Drive needs cleaned, needs spot cleaned & Dusted	JS	✓		
GLORY HOLE	D Box & Pump clear at Exam	BC	✓		
H622 #1	needs cleaned & Dusted	JS	✓		
7622 #1	needs cleaned & Dusted	JS	✓		
#2	needs Dusted	JS	✓		
*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS					

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 0 ppm CO, 20.8% O₂ Detected
Track / Travel ways, D-Box's, Power centers, KW's, Pumps, chargers
in a visual check of all CO monitors all clear at Exam

SIGNED BY: William Campbell 135419

Belt Examiners and Certificate Numbers

John [Signature] 32476

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Name

Mine Foreman

33357

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-21-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☐ No ☐ By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
CELL 1.5.4		
CELL 1.5.5		
NORTH 2		
NORTH 3		
NORTH 4	Shoveled on to V	BC
NORTH 5	Shoveled on V plow	BC
NORTH 6		
NORTH 7		
Wongrowell		
GLORY HOLE		
CELL 1.5.1		
CELL 1.5.2		

Checked out by Refugees at 6, 8, 89, belt all clear at exam and
phones working

SIGNED BY: William Campbell 1354
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore
Mine Foreman

33359
Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-22-10 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Brought out Time AM or PM

Report received by: _____

Signed _____					
BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
E11.3.4	needs Dusted	BC	✓		
E11.3.5	needs cleaned from 27-29 b/c needs Dusted	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs spot cleaned from 32-tail needs cleaned from Discharge-Drives, tail needs added cleaning	BC	✓		
NORTH NO. 5	tail up, needs added cleaning, Out by tail needs added cleaning	BC	✓		
NORTH NO. 6	needs spot cleaned at a/c out of 87-tail needs Dusted	BC	✓		
NORTH NO. 7	needs Dusted	BC	✓		
Longwall...	mother drive needs cleaned, belt needs spot cleaned	JS	✓		
GLORY HOLE	D-Box-Pump-clear cut Exam	BC	✓		
H622 #1	needs cleaned & Dusted	JS	✓		
E11.4					
T622 #1	needs cleaned & Dusted	JS	✓		
#2	needs Dusted	JS	✓		

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 0 ppm CO, 20.8% O₂ detected

Track/Trailways, D-Box's, pumps, KVA's, Powercenters, chargers
and a visual check of Co-monitors all cleared Exam

SIGNED BY: William Canalese 1354-12

Belt Examiners and Certificate Numbers

32476
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY *T. Merone*

Mine Foreman

33359

Certificate No

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes _____ No _____ **By Whom** _____ **Time** _____ **AM or PM**

Report received by: _____

Checked Out by Refugee at #6, 8, 89b11s, none observed at Exam

20.8% O₂, 0% CH₄, Oppm CO detected

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

Mine Foreman

Certificate No.

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-22-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☒ No ☐ By Whom John Neely Time 2:45 AM or PM ☒

Report received by: Russell Gunnoe
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
EN-13 14	Needs Dusted	RG	✓		
EN-15 15	Needs cleaned 27-29, Needs Dusted	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Needs Some Spot Cleaning, tail Needs Add Cleaning Needs cleaned Drive-Discharge	RG SH	✓		
NORTH NO. 5	takeup Needs Add Cleaning	SH	✓		
NORTH NO. 6	Needs Spot Cleaned at Airlock, 87-tail needs Dusted	SH	✓		
NORTH NO. 7	Needs Dusted	JN	✓		
Longwall	Needs Some Spot Cleaning, Added Dusting needed Area Blown Discharge & Drive Needs Cleaned	SH	✓		
GLORY HOLE	D-Box + Pump OK	JN	✓		
HG-22	Needs cleaned & Dusted	JN	✓		
TG-22 #1	Needs cleaned & Dusted	JN	✓		
TG-22 #2	Needs Dusted	JN	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 20.8% O₂, 0 ppm CO at time of exam

Travelways, Power Centers, D-Boxes, Chargers OK at time of exam

Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Gunnoe 153679

Belt Examiners and Certificate Numbers

Johnny Neely 33472

Belt Examiners and Certificate Numbers

Scott Halstead 37567

John Adams 32476

COUNTERSIGNED BY T. M. M...

Mine Foreman

Certificate No.

Superintendent

Certificate No.

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-22-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled v-plow Cleared tail + Greased, ^{Cleared from tail to 3rd BK} (Bobby)	RG
Ellis 5	Shoveled v-plow Cleared tail + Greased (Bobby)	RG
NORTH 2		
NORTH 3		
NORTH 4	Ran Duster At Drives, Cleared Sams on tail	RG
NORTH 5	Cleared V-Plows	SH
NORTH 6	Cleared V-Plows	SH
NORTH 7	Ran Duster at Head CLEAN TAIL	SH
Longwall	Cleared Mud at Mother Drive, chkb Splices	SH
GLORY HOLE		
HG-22	clean on Rib Roll clean v Plow at TAIL	JN
TG-22 #1	CLEAN TAIL Dust from Discharge To Drive Grease Drive ^{Discharge}	JN
TG-22 #2		

Resurge chambers, 6, 8, 99. clear at EXAM

Phones working in 8, 99 BK

6 BK Phone Needs Battery

SIGNED BY: Russell Dunne 1536-19
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore

Mine Foreman

33357

Certificate No.

Scott Halstead 37567

Johnny Neely

Superintendent

Certificate No.

Use Indelible Pencil or Ink

DATE 3-22-10 SHIFT: 815 600 AM OR PM 300 AM OR PM 1200 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Report received by: _____

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

0% CH₄, 0 ppm CO, 20.8% O₂ Detected
Track / Travelways, D-Boxes, chargers, Power centers, Pumps, KVAs
and a visual check of CO monitors were all clear at Exon

W.D. Little 2004.5

Belt Examiners and Certificate Numbers

Bell Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore
Mine Foreman

33389
Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-22-10 SHIFT: 6:00 AM OR PM TO 8:00 AM OR PM TO 11:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
4 & 11.5	Shoveled V-plow at tail	BC
5 & 11.5	worked on Mud at tail	BC
NORTH 4	Ramp pumps at 12 & 17 bks - shoveled on tail / worked on Mud at Discharge	BC
NORTH 5	shoveled V-plow 3 at Flow thru, & Tail	BC
NORTH 6	shoveled V-plow at tail	BC
NORTH 7		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
Longwell	Dusted P. Lat Storage unit	BC
H6 22 [#] 1	SHOVELLED ON TAIL V-PLOW	JS
J6 22 [#] 1	Work on Hangers LIFE LINE	JS

Checked Out by Refuges at #6 bck - Replaced butterfly in phone WORKING now
 section #8 bck - phone working - all cleared Exam
 #89 bck - phone not working 20.6% 100², 0% CH4, O₂

SIGNED BY: William Campbell 135417

Belt Examiners and Certificate Numbers

John 32470

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. M. M...

Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes No ☒ By Whom _____ Time _____ AM or PM

Signed _____

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

0% CH₄, 0ppm CO, 20.8% O₂ Detected
Track / Travel ways, D-Box's, Chargers, Power centers, LVA, Pumps
and a Visual check of CO monitors, all clear

Belt Examiners and Certificate Numbers

John Deely 33472
Belt Examiners and Certificate Numbers

T. Moore
Mine Foreman

33359
Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes___ No X By Whom_____ Time_____ AM or PM

Signed

46543—BJW Printing & Office Supplies

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-23-10 SHIFT: Day AM OR PM TO AM OR PM 12:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☒ No ☐ By Whom John Neely Time 2:40 AM or PM PM

Report received by: Russell Gurnee
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
<u>Elis 4</u>	<u>Needs Dusted</u>	<u>RG</u>	☒		
<u>Elis 5</u>	<u>Needs spot cleaned 27-29, Needs Dusted</u>	<u>RG</u>	☒		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Needs Spot Cleaned 35-tail</u> <u>Needs cleaned Drive-Discharge</u>	<u>RG SH</u>	☒		
NORTH NO. 5	<u>take up needs Add Cleaning, Needs Spot Cleaned 60-Flowthere</u>	<u>SH</u>			
NORTH NO. 6	<u>Needs Spot Cleaned 87-tail</u>	<u>SH</u>	☒		
NORTH NO. 7	<u>Needs Dusted</u>	<u>JN</u>	☒		
<u>Longwall</u>	<u>Mother Drive Area Needs Cleaned, Belt Needs Some Spot Clean</u>	<u>SH</u>	☒		
GLORY HOLE	<u>D-Box & Pump OK</u>	<u>JN</u>	☒		
TG-22 NO. 1	<u>Needs cleaned & Dusted</u>	<u>JN</u>	☒		
TG-22 NO. 2	<u>Needs Dusted</u>	<u>JN</u>	☒		
<u>HG-22 #1</u>	<u>Needs Dusted, Needs Rih Roll cleaned up in walkway</u>	<u>JN</u>	☒		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 20.8% O₂, 0 ppm CO at time of exam

TRAVELWAYS, Power Centers, D-Boxes, chargers OK at time of exam

Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Gurnee 1536-A
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Mune 33359

Mine Foreman

Certificate No.

Superintendent

Certificate No.

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-23-10 SHIFT: Day 6:00 AM OR PM TO 3:00 AM OR PM AM OR PM TO AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	shoveled v-plow, cleaned from tail to stop, cleaned & Greased on tail (Bobby)	RG
Ellis 5	shoveled v-plow, cleaned & Greased on tail (Bobby)	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned V-Plow	SH
NORTH 5	cleaned V-Plows CLEAN ON TAIL	SH JN
NORTH 6	cleaned V-Plow	SH
NORTH 7		
Longwall	cleaned on Mud at Mother Drive	SH
GLORY HOLE		
TG22NO. 1	CLEAN ON TAIL	JN
TG22NO. 2		
HG-22 #1	CLEAN ON Rib Rolls IN walkway CLEAN V Plow at Tail	JN

Refuge Chambers 6, 8, 89 BK Good at EXAM

Phones Working at EXAM

SIGNED BY: Russell Gunnel 1531-A
Belt Examiners and Certificate Numbers

Scott Halstead 37567

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Mame
Mine Foreman

33354
Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes _____ No _____ **By Whom** _____ **Time** _____ **AM or PM**

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

0% CH₄, 0% CO, O₂ 20.8% Defected

Track/Travelways, D Box's, chargers, Power centers, an a visual check of 10's

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-23-70 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☐ No ☐ By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
GLORY HOLE		
7633 NO. 1	<u>5/6x12 V-Plow</u>	<u>JS</u>
NO. 2		

Checked Outby Refuges at #6 - n/o - phones working

#8 - n/o - phones working

#89 - N/O - changed battery phone working

20.6%00, 0%0CH4, 0%pm CO

SIGNED BY: William Campbell 13842

Belt Examiners and Certificate Numbers

John Mann 1539A

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T Mann

33389

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

DATE 3-24-10 SHIFT: 8w/ AM OR PM TO AM OR PM 300 AM OR PM TO 600 AM OR PM

PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Broughton Time AM or PM

Report received by: _____

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

0644 0610 20.8307

PC's, Travelways, D-Rox, charger OK

SIGNED BY: Wm 1539-A 32476

Belt Examiners and Certificate Numbers

17th Dec 1384

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. J. [Signature] 38359

Mine Foreman

Certificate No.

Superintendent

Certificate No.

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-24-10 SHIFT: OW 1100 AM OR PM TO 300 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
<u>OW 4</u>	<u>cleaned & run</u>	<u>GU</u>
<u>Ellis 5</u>	<u>change roller</u>	
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	<u>cleaned Flow thru, made splice</u>	<u>GU</u>
NORTH 6	<u>shoveled & plugged Flow thru</u>	<u>BC</u>
NORTH 7	<u>change roller</u>	
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<u>7N Const</u>	<u>Set 3 Sacks near D Box & Power center</u>	<u>BC, JS</u>
<u>North Main</u>		<u>BC, JS</u>
<u>Intake Room</u>	<u>Moved pump in #4 up closer to Face where water is deeper</u>	

checked out by Relays 6-2-89 OK phones working

SIGNED BY:

15397
Belt Examiners and Certificate Numbers

133474
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. M. Lane

Mine Foreman

Certificate No. 33387

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-24-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☒ No ☐ By Whom John Bickford/John Neely Time 2:20 AM or PM

Report received by: _____

BELTS	Signed VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs Dusted</u>	<u>RG</u>	☒		
<u>Ellis 5</u>	<u>Needs spot cleaned + Dusted</u>	<u>RG</u>	☒		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>Needs cleaned Drive-Discharge, Needs spot cleaned 37-Tail</u>	<u>JAB RG</u>	☒		
<u>NORTH NO. 5</u>	<u>Take-up needs add. cleaning, Needs spot cleaned 60-Flow-Thru</u>	<u>JAB</u>	☒		
<u>NORTH NO. 6</u>	<u>Needs spot cleaned 87-Tail</u>	<u>JAB</u>	☒		
<u>NORTH NO. 7</u>	<u>Needs Dusted</u>	<u>SH</u>	☒		
<u>Longwall</u>	<u>Belt Needs Spot Cleaned Mother Drive Needs Add Cleaning</u>	<u>SH</u>	☒		
<u>GLORY HOLE</u>	<u>D-Box + Pump OK</u>	<u>SH</u>	☒		
<u>TG-22 NO. 1</u>	<u>Needs spot cleaned + Dusted</u>	<u>JN</u>	☒		
<u>TG-22 NO. 2</u>	<u>Needs Spot cleaned + Dusted</u>	<u>JN</u>	☒		
<u>HG-22 #1</u>	<u>Needs cleaned + Dusted, Rib Roll needs cleaned up in walkway</u>	<u>JN</u>	☒		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 20.8% O₂, 0ppm CO at time of exam

TRAVELWAYS, Power Centers, D-Boxes, Chargers OK at time of exam

Visual check of CO monitors OK at time of exam

SIGNED BY:

Russell Dumas 1536-19
Belt Examiners and Certificate Numbers

John A. Bickford 21/17
Belt Examiners and Certificate Numbers

John Sh 32476
Scott Holstead 37567

Johnny Dally 33472

COUNTERSIGNED BY

T. Marie
Mine Foreman

33389
Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes___ No___ By Whom_____ Time_____ AM or PM

Report received by: _____

Signed

Refuge chamber 6, 89, 89, 89 OK + phones working at time of exam

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

John Ruby 33472

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes _____ No _____ **By Whom** _____ **Time** _____ AM or PM _____

Signed

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

0% CO₂, 0 ppm CO, 20.8% O₂ Detected

TRACK/Travelways, KVM, Powercords, Chargers i2-Bos's, Pump, an
 advised check of CO monitors clean at Exam

Belt Examiners and Certificate Numbers

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes___ No___ By Whom_____ Time_____ AM or PM

Signed

Checked out by Refugee at # 6 w/o
8 w/o } and phony working
89 w/o } 20.6% O₂, 0% pmCO, ~~20~~ 0% CH₄

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-25-10 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom _____ Time _____ AM or PM

Report received by: _____

Signed					
BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
Ellis NO. 4	needs dusted	BC	✓		
Ellis NO. 5	needs spot cleaned & dusted	BC	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take up needs added cleaning, tail needs added cleaning Drives to Discharge needs cleaned, needs spot cleaned 87-tail	BC	✓		
NORTH NO. 5	needs from 60-flow thru, Take up needs added cleaning	BC	✓		
NORTH NO. 6	needs dusted needs spot cleaned 87-tail	BC	✓		
NORTH NO. 7	needs dusted Belt needs spot cleaned & dusted	BC	✓		
Longwell		JS	✓		
GLORY HOLE	D-Box & Pump cleared exam	BC	✓		
H622 NO. 1	needs spot cleaned & dusted	JS	✓		
H622 NO. 2	needs spot cleaned & dusted	JS	✓		
H622 #1	needs cleaned & dusted, Rib Rolls need cleaned up in work way	JS	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 0ppm CO, 20.8% O₂ Detected
Trench/Terminals, D-Box's, chargers, KVAs, Powercenters, an overall check
of components all clear at exam

SIGNED BY: William Campbell 13547

Belt Examiners and Certificate Numbers

32476
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. M. M. 33357

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-25-70 SHIFT: 001 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
ELTS 4	shoveled v plow change roller LC.	BC
ELTS 5		
NORTH 2		
NORTH 3		
NORTH 4	shoveled on tail shoveled v plow Run Duster change roller LC	BC
NORTH 5	shoveled v plow at Flow thru + tail, Shoveled on tail	BC
NORTH 6		
NORTH 7	shoveled on Flow thru	BC
Long wall	shoveled AT Airtack. change roller LC	JS
GLORY HOLE		
T622 NO. 1	SHOVELED V-Plow	JS
T622 NO. 2		
H622 #1	SHOVELED V-Plow	JS

Checked Outby Refuges at #16 - N/O

#8 - N/O

#89 - N/O

all Phones working

0% OCHM, Oppm 10, 20, 6% O

SIGNED BY:

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

Mine Foreman

Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-25-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☒ No ☐ By Whom John Bickford Time 2:25 AM or PM

Report received by: Russell Gurnee

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs Dusted</u>	<u>RG</u>	☒		
<u>Ellis 5</u>	<u>Needs Spot Cleaned + Dusted</u>	<u>RG</u>	☒		
<u>NORTH NO. 2</u>					
<u>NORTH NO. 3</u>					
<u>NORTH NO. 4</u>	<u>Takeup tail Needs Add Cleaning, Needs Spot Cleaned Needs cleaned Drive-Discharge</u>	<u>RG SH</u>	☒		
<u>NORTH NO. 5</u>	<u>Takeup Needs Add Cleaning, Needs Cleaned 60-Flowthen</u>	<u>SH</u>	☒		
<u>NORTH NO. 6</u>	<u>Needs Dusted, Needs Spot Cleaned 87-tail</u>	<u>SH</u>	☒		
<u>NORTH NO. 7</u>	<u>Needs Spot cleaned + Dusted</u>	<u>JAB</u>	☒		
<u>Longwall</u>	<u>Belt needs Spot Cleaned + Dusted</u>	<u>SH</u>	☒		
<u>GLORY HOLE</u>	<u>D-Box + Pump OK</u>	<u>JAB</u>	☒		
<u>TG-22 NO. 1</u>	<u>Needs spot cleaned + Dusted</u>	<u>JAB</u>	☒		
<u>TG-22 NO. 2</u>	<u>Needs spot cleaned, Water at tail</u>	<u>JAB</u>	☒		
<u>HG-22 #1</u>	<u>Needs add'l cleaning in Half-way water Needs add. spot cleaning + dusting, Accumulating at head</u>	<u>JAB</u>	☒		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 20.8% O₂, 0ppm CO at time of exam
Travelways, Power Centers, Chargers, D-Boxes OK at time of exam
Visual Check of CO monitors OK at time of exam

SIGNED BY: Russell Gurnee 1536-A

Belt Examiners and Certificate Numbers

John Bickford
Belt Examiners and Certificate Numbers

Scott Halatind 37567

JH Halatind 32476

COUNTERSIGNED BY: T. Moore

Mine Foreman

83359

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-25-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☐ No ☐ By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow, cleaned & Greased tail (Bobby)	RG
Ellis 5	Shoveled V-plow, cleaned & Greased tail (Bobby)	RG
NORTH 2		
NORTH 3		
NORTH 4	RAN Duster at Drive, cleaned some on tail SH	RG
NORTH 5	Cleaned V-Plow at tail & flow thru, RAN Duster	SH
NORTH 6	cleaned V-Plow, RAN Duster, cleaned & dusted tail & flow thru	SH
NORTH 7		
Longwa 11	cleaned spillage at Discharge Greased on Drive, dusted around Drive, Spot Cleaned at Box CK	SH
GLORY HOLE		
TC-22 NO. 1		
TC-22 NO. 2		
HC-22 #1		

Refuge Chambers 6, 8, 89 BK OK at EXAM
Phones Working at time of EXAM

SIGNED BY: Russell Gunnar 1536-A
Belt Examiners and Certificate Numbers
John R. Buckford 26176
Belt Examiners and Certificate Numbers

Scott Halstead 37567
J. J. Long 32476

COUNTERSIGNED BY T. M. Mune 32387
Mine Foreman Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Report received by: _____

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

PC's, Chargers, O-Bars, Pumps, Travelways etc

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes___ No X **By Whom** _____ **Time** _____ AM or PM.

Signed

Checked out by Refugers 6-8-89 OK

Belt Examiners and Certificate Numbers

Certificate No.

PRE-SHIFT

EXAMINATION OF BELT CONVEYORS

Use Indelible Pencil or Ink

DATE 3-26-60 SHIFT: 0wl AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☐ No ☒ By Whom _____ Time _____ AM or PM

Report received by: Brought out

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE-SHIFT	COUNT SIGN	*FIRE RUN
elli's #4	Needs Dusted	GLC	✓		
elli's #5	Needs spot cleaned and Dusted	GLC	✓		
Longwall	Needs spot cleaned and Dusted	JS	✓		
NORTH NO. 3					
NORTH NO. 4	Take up needs add cleaning Needs spot cleaned Needs cleaned Drive - Discharge	GLC	✓		
NORTH NO. 5	Take up Needs add cleaning Needs cleaned GOBRIN to flow then	GLC	✓		
NORTH NO. 6	Needs Dusted, Needs spot cleaned 87-Tail	GLC	✓		
NORTH NO. 7	Needs spot cleaned and Dusted	JS	✓		
NORTH NO. 8					
GLORY HOLE	D-Box pump ok	JS	✓		
TG NO. 1	Needs spot cleaned and Dusted				
TG NO. 2	Needs spot cleaned, water At Tail	JS	✓		
HG22 #1	Needs add cleaning walk ways Needs spot cleaned and Dusted	JS	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 20.8% O₂, Oppm C.O. Detected

PC's, chargers, D-Boxes, pumps, travelways, Track OK At Time of exam

Visual check of C.O. monitors OK At exam

SIGNED BY: Yves Cole 1947-A

Belt Examiners and Certificate Numbers

32476

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

T. Miner

Mine Foreman

33259

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-26-10 SHIFT: owl AM OR PM TO 3:00 AM OR PM TO 6:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No ☒ By Whom Time AM or PM

Report received by: Brought out
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1 <u>Ellis</u>	<u>change roller LC</u>	
NORTH 1 <u>Ellis</u>	<u>change roller LC</u>	
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	<u>cleaned Flow Thru V-Plow</u>	<u>GLC</u>
NORTH 6	<u>change roller LC</u>	
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
<u>Ellis #4</u>	<u>cleaned V-Plow</u>	<u>GLC</u>

Refuge At ^{GLC} 6BRK, 81BRK OK At time of exam

SIGNED BY:

Belt Examiner and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

Mine Foreman

Certificate No. 33259

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-26-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
<u>Ellis 4</u>	<u>Needs Dusted</u>	<u>RG</u>	<u>✓</u>		
<u>Ellis 5</u>	<u>Needs Spot cleaned + Dusted</u>	<u>RG</u>	<u>✓</u>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Takeup Needs Cleaned, Belt Needs Spot Cleaned</u> <u>Needs Cleaned Drive to Discharge</u>	<u>RG SH</u>	<u>✓</u>		
NORTH NO. 5	<u>Takeup Needs Add Cleaning, Needs Spot Cleaned 66 BK</u> <u>To Flow thru</u>	<u>SH</u>	<u>✓</u>		
NORTH NO. 6	<u>Needs Spot Cleaned 87-tail, Needs Dusted</u>	<u>SH</u>	<u>✓</u>		
NORTH NO. 7	<u>Belt Needs Spot Cleaned + Dusted</u>	<u>SH</u>	<u>✓</u>		
<u>Longwall</u>	<u>Needs Dusted 55+25, 56+50, 66+00, 66+50</u>	<u>TD</u>	<u>✓</u>		
GLORY HOLE					
<u>TG-22 NO. 1</u>	<u>Belt needs Additional Dusting, needs Spot Cleaned</u>	<u>TM</u>	<u>✓</u>		
<u>TG-22 NO. 2</u>	<u>Belt needs Additional Dusting, needs Spot Cleaned</u>	<u>TM</u>	<u>✓</u>		
<u>HG-22 #1</u>	<u>Belt needs Additional Dusting, needs Spot Cleaned</u>	<u>TM</u>	<u>✓</u>		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 20.8% O₂, 0ppm CO at time of exam

Travelways, Power Cables, D-Boxes, Chargers OK at time of exam

Visual Check of CO monitors OK at time of exam

Alan Ullman 1539-A

SIGNED BY: Russell Burnse 1536-A

Belt Examiners and Certificate Numbers

Tom Moore 33389

Belt Examiners and Certificate Numbers

Scott Halstead 37567

Jim Oliver 38,322

COUNTERSIGNED BY Tom Moore 33389

Mine Foreman

Certificate No.

Superintendent

Certificate No.

William Campbell 1354-A

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-26-10 SHIFT: Day 6:00 AM OR PM TO 3:00 AM OR PM AM OR PM TO AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow (shoveled + R) & Greased + R (Bobby	RG
Ellis 5	Shoveled V-plow (shoveled + R) & Greased + R (Bobby	RG
NORTH 2		
NORTH 3		
NORTH 4	Ran duster at Drive, cleaned on tailpiece	SH RG
NORTH 5	cleaned V-Plows at tail & Flow thru, Ran Duster at Head	SH
NORTH 6	cleaned V-Plow, Ran Duster at Head	SH
NORTH 7	cleaned on tail & Greased tail Roller	SH
Longwall	cleaned at Head, Hand Dusted Head & Drive Area, ckd Splices	SH
GLORY HOLE		
TG-22 NO. 1		
TG-22 NO. 2		
HG-22 #1		

Refuge Chambers 6, 8, 89 Bks were clear time of EXAM

All Phones working at Exam time

SIGNED BY: Russell Dunne 1536-19
Belt Examiners and Certificate Numbers

Scott Halsted 37567

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore

Mine Foreman

33389
Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes No X By Whom Brough + out Time AM or PM

Signed

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

0% CH₄, 0 ppm CO, 20.8% O₂ detected

Track Handing, D-Box's, Chargers, Powercenters, KVA, Pumps and
visual check of CO monitors were all clear at Exam.

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

3335-7

Certificate No.

Certificate No.

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-26-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
Cell's 4	Shoveled V-plow	BC
21135		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	Shoveled V-plow at flow + new + tail	BC
NORTH 6		
NORTH 7		
Longwall		
GLORY HOLE		
T622 NO. 1		
T622 NO. 2		
H622 #1		

Check out by Refuges at #6 - N/O all phones working

#8 - N/O

#89 - N/O

20.6% O₂, 0% CH₄, OppmCO

Checked Intake Room - 5 GV

SIGNED BY: William Campbell 135412

Belt Examiners and Certificate Numbers

Don M... 15397

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. M... 33789

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Report received by: _____

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

PC's, Charger, O.Bikes, Travel works OK

Certificate No.

Lohnd. Bickford 26176

Use Indelible Pencil or Ink

Was this report phoned to outside Yes No ☒ By Whom Time AM or PM

Signed

Checked Out by Refuges 6, 8, 89 OK
checked Intake Rooms OK

COUNTERSIGNED BY T. Moore 33389
Mine Foreman Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-27-10 SHIFT: Day AM OR PM TO 1200 AM OR PM TO 300 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
<u>ELLIS 4</u>	<u>Needs dusted</u>	<u>JAB</u>	<u>✓</u>		
<u>ELLIS 5</u>	<u>Needs dusted + spot cleaned</u>	<u>JAB</u>	<u>✓</u>		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	<u>Take up needs cleaned down to head needs cleaned</u>	<u>JAB</u>	<u>✓</u>		
NORTH NO. 5	<u>Take up needs add 3 cleaning needs spot cleaned 60 to Flow. Chw</u>	<u>JAB</u>	<u>✓</u>		
NORTH NO. 6	<u>Needs spot cleaned + dusted</u>	<u>JAB</u>	<u>✓</u>		
NORTH NO. 7	<u>Needs dusted + spot cleaned</u>	<u>SH</u>	<u>✓</u>		
<u>L Wall</u>	<u>Need more cleaning + dusting</u>	<u>HL</u>	<u>✓</u>		
GLORY HOLE	<u>D Box + Pump OK</u>	<u>SH</u>	<u>✓</u>		
LBB NO. 1					
LBB NO. 2					
<u>HG 22 #1</u>	<u>Needs add'l spot cleaning + dusting</u>	<u>SH</u>	<u>✓</u>		
<u>T6 22 #1</u>	<u>Idle PCs - OK</u>	<u>SH</u>			
<u>T6 22 #2</u>	<u>Idle PCs OK</u>	<u>SH</u>			

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OT. ch4 OT. CO + 2.0.8 to 0.2 detected

Track, Travelways, PCs, Chygen, D'Box's + Pumpers clear
at time of exam

SIGNED BY:

John A. Bickford 21174
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

T. Plume

Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-27-10 SHIFT: Day AM OR PM TO AM OR PM AM OR PM TO AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
SOUTH		
<u>Ext.</u>		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5	<u>Cleaned at tail & flow - then</u>	<u>SH, 5/10</u>
NORTH 6	<u>Cleaned at flow - then & tail</u>	<u>SH, 3/10</u>
NORTH 7	<u>Cleaned at tail</u>	<u>SH</u>
<u>HL wall</u>	<u>1 man cleaning on Belt.</u>	<u>HL</u>
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked Refuser 6, 8 & 89 Belts. - OK Phoned OK

SIGNED BY: John B. Buford 21176
Belt Examiners and Certificate Numbers

W.D. Lilly 28045

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Maune
Mine Foreman

33357
Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-27-10 SHIFT: EVE 800 AM OR PM TO 1100 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☐ No ☒ By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
ELIS 4	NEEDS Dusted	J.M	✓		
ELIS 5	Needs spot cleaned & dusted	JM	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Take-up needs cleaned, drive to head needs cleaned	BB	✓		
NORTH NO. 5	Take up needs add cleaning, ^{muck, spot cleaned} go to firehouse	BL	✓		
NORTH NO. 6	muck, spot cleaned & dusted	BL	✓		
NORTH NO. 7	muck, spot cleaned & dusted	BL	✓		
L.W. BELT	NEEDS add cleaning & dusting	JM	✓		
GLORY HOLE					
LBB NO. 1					
LBB NO. 2					
TG 22 #1	IDLE - P/C & chargers				
TG 22 #2	IDLE - cled time of exam	JM	✓		
HC #22 1	muck add spot cleaning & dusting	BL	✓		
*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS					

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% chg - 20.802, 0% CO

Track - travelways - P/C's - KWA's - D-Boxes - Pumps - all clear
Time of exam

SIGNED BY:

Jack Martin 37793
Belt Examiners and Certificate Numbers
Bobby L. Bell 37699
Belt Examiners and Certificate Numbers

Brian Collins 1543-A

COUNTERSIGNED BY

T. M. Moore
Mine Foreman

33309

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes___ No___ By Whom_____ Time_____ AM or PM

Signed

Refugees at C, 8, & 89 OK Phumes OK

Certificate No.

Use Indelible Pencil or Ink

Report received by: _____

46543-BJW Printing & Office Supplies

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-28-10 SHIFT: owl 1200 AM OR PM TO 600 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☐ No ☒ By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Refusers at C, 8, 89 ok Phumis ok

SIGNED BY: Brian Collins 1543-A

Belt Examiners and Certificate Numbers

Billy L. Kelly 38699

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. M. M...

Mine Foreman

33852

Certificate No.

Superintendent

Certificate No.

John A. Buckland 26176

Johnny Kelly 33472

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3.28.10 SHIFT: Day AM OR PM TO 1200 AM OR PM TO 300 AM OR PM

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☒ No ☐ By Whom J Neely Time 200 AM or PM

Report received by: John R. Bifford 26176
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
ELK NO. 4	Needs dusted	JAB	✓		
ELK NO. 5	Needs spot cleaned & dusted	JAB	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Tail needs cleaned Take up & drum to head needs cleaned	JAB	✓		
NORTH NO. 5	Take up needs add'l cleaning Needs spot cleaned & o to follow then	JAB	✓		
NORTH NO. 6	Needs spot cleaned & dusted	JAB	✓		
NORTH NO. 7	Needs spot cleaned & dusted	JN	✓		
Lg Hall	Needs spot & dusted	TD	✓		
GLORY HOLE	Pump & D'Box - OK	JN	✓		
TG 22 NO. 1	Folle PC - OK	JN			
TG 22 NO. 2	Folle PC OK	JN			
HG 22 #1	Discharge ^{one} needs add'l cleaning Needs add'l cleaning & dusting	JN	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

O₂ & CO₂ 20.8 to O₂ detected at time of exam

Visual check of CO's - OK

PC's, Tracks, Traversing, chasers, Pumps & D'Box

Dlm Mhm 15394

SIGNED BY:

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes___ No___ By Whom___ Time___ AM or PM

Signed

Checked Refuser at 6.8 x 89 Bnhs.; OK, Phones OK

Belt Examiners and Certificate Numbers

Mine Foreman

Certificate No.

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-28-10 SHIFT: EVE AM OR PM TO 800 AM OR PM TO 1100 AM OR PM
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Brought out Time AM or PM

Report received by:

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
ELIS NO. 4	needs Dusted	GV	✓		
ELIS NO. 5	needs Dusted & spot cleaned	GV	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Tail needs Add cleaning Take up and Drive to Hd needs cleaned	GV	✓		
NORTH NO. 5	TAKE UP needs Add cleaning Needs Spot cleaned Co-Flawmen	GV	✓		
NORTH NO. 6	Needs Spot cleaned & dusted	GV	✓		
NORTH NO. 7	needs spot cleaned & dusted	JS	✓		
LINCOLN NO. 8	needs spot Dusted	JS	✓		
GLORY HOLE	D-Box Pump OK	JS	✓		
TC22 NO. 1	needs spot cleaned & dusted	JS	✓		
TC22 NO. 2	needs spot cleaned & dusted	JS	✓		
HG22 #1	needs Spot cleaned & dusted	JS	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OK CH4 OK CO 2018202

PC's, chargers, D-Boxes, Pumps and Travelways OK

Phones Does NOT Page AT HG22 #1 Head

SIGNED BY:

Don Miller 15372
Belt Examiners and Certificate Numbers

Paul Miller 32476
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY

T. Miller
Mine Foreman

33354
Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAM.

Was this report phoned to outside Yes No X By Whom Time AM or PM

Signed

Checked out by Refugees G, J, J9 all OK

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

Certificate No.

Superintendent

Certificate No:

Use Indelible Pencil or Ink

Was this report phoned to outside Yes _____ No X **By Whom** _____ **Time** _____ **AM or PM**

Signed _____

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS: _____

of CH₄ : O₂CO 20,8202

PC's Charges, D-Bates, Pings, Travelways & K

SIGNED BY: [Signature] 15399

Belt Examiners and Certificate Numbers

32476
Bell Examiners and Certificate Numbers

By Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore

33359

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Scott Halstead
3756

Use Indelible Pencil or Ink

Was this report phoned to outside Yes _____ No X **By Whom** _____ **Time** _____ **AM or PM**

Signed

Checked out by Refs 6-8-89 OK

Belt Examiners and Certificate Numbers

John D. King John D. King
Belt Examiners and Certificate Numbers

T. Moore
Mine Foreman

Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-29-10 SHIFT: DAY AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☒ No ☐ By Whom J. Neely Time 2:47 AM or PM

Report received by: _____

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
ELIS # 4	Needs Dusted	SH	✓		
ELIS NO. 5	Needs Spot Cleaned & Dusted	SH	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	TAKUP, Drive - Head Needs Cleaned	SH	✓		
NORTH NO. 5	TAKUP Needs Add Cleaning Needs Spot Cleaned 60 BK - Flow thru	SH	✓		
NORTH NO. 6	Needs Spot Cleaned & Dusted	SH	✓		
NORTH NO. 7	Needs Dusted	JN	✓		
Long Wall	Needs Dusted from 8 BK to Storage Unit	TD	✓		
GLORY HOLE	D-BOX & Pump Clean	JN	✓		
LBB NO. 1					
LBB NO. 2					
TG 22 # 1	Needs Dusted, TAIL Needs ADD CLEANING	JN	✓		
TG 22 # 2	Needs Spot Cleaned & Dusted	JN	✓		
HG 22 # 1	Needs Dusted	JN	✓		

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 20.8% O₂, 0ppm CO Detected at EXAM time
Power Centers, D-Boxes, Chargers, TRACK & TRAVEL ways Clean at EXAM time
Visual CK of CO Monitors - Clean.

SIGNED BY:

J. Neely 38322
 Belt Examiners and Certificate Numbers
Johnny Neely 33472
 Belt Examiners and Certificate Numbers

Scott Halstead 37567
J. Neely 32476

COUNTERSIGNED BY

T. Moore 33389
 Mine Foreman Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-29-10 SHIFT: DAY AM OR PM TO AM OR PM TO AM OR PM TO AM OR PM TO
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☐ No ☐ By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
#4	cleaned tail & Greased & Dusted (Bobby)	
#5	cleaned tail & Greased & Dusted (Bobby)	
NORTH 2		
NORTH 3		
NORTH 4	cleaned on tail	SH
NORTH 5	cleaned V-Plow at tail & flow thru Ran Duster clean on TAIL	SH
NORTH 6	cleaned V-Plow Ran Duster	SH
NORTH 7	Ran Duster	SH
Long Wall	cleaned V-Plow at Head, Greased Discharge, cleaned & Dusted at Drive	SH
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
H622#1	Hand Dust Drive Area, Grease on Drive	JN
T622#1	clean on V Plow & TAIL, Dust from Discharge to Takeup ^{pump} water	JN
	Ran Trickle duster.	JN

CKd outby Refuge Chambers 6-8-89 BK -clean
All Phones Working

clean off PC's at H622 Drive + splitter clean off PC at 130 Brk

SIGNED BY: Scott Halstead 37567

Belt Examiners and Certificate Numbers

Johnny Nelly 33472

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore

Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes ☐ No ☒ By Whom _____ Time _____ AM or PM

Signed

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

Track/Handwriting, D-BOK's, Chargers, Power Centers
on a visual check of COMonitors will clear at Exam

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

Mine Foreman

Superintendent

Certificate No.

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-29-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM 800 AM OR PM TO 1100 AM OR PM
 ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:
 Signed

BELTS	ACTION TAKEN	INT.
E1115 41	shoveled v plow	BC
E1115 5		
NORTH 3		
NORTH 4	shoveled on v plow	BC
NORTH 5	shoveled v plow at Flow thru	BC
NORTH 6		
NORTH 7		
Longwall		
GLORY HOLE		
T622 NO. 1		
T622 NO. 2		
H622 #1		

Checked Entry Refuges at #6 - N/O

#8 - N/O

#89 - N/O

} all phones working

20.6% O₂, 0.7% CH₄, OppmCO Detected

SIGNED BY: Walker Complex 135414
 Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Mame
 Mine Foreman

32359
 Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes No X By Whom Time AM or PM

Signed

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

Trail/Travelways, chargers, D-Box, Powercenters, KVA's, & Pumps
and a visual check of all CO monitors all clear at Exam

Belt Examiners and Certificate Numbers

Paul H. [Signature] 32476
Belt Examiners and Certificate Numbers

33257

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Russell Dennis 1535-A

Scott Halsted 37567

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-30-70 SHIFT: 021 1100 AM OR PM TO 300 AM OR PM 300 AM OR PM TO 600 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
E11.34	Shoveled V-plow	BC
E11.35	change roll LC.	
NORTH 2		
NORTH 3		
NORTH 4	Shoveled V-plow + Worked on shoveling tail / working on Take up LC.	BC
NORTH 5	Shoveled V-plows at Flow thru tail	BC
NORTH 6	Shoveled V-plows at tail + Flow thru change roll input LC.	BC
NORTH 7		
Langwell	set 2 jacks at Powercenter at Storage unit	BC/JA
GLORY HOLE		
T622 NO. 1	SHOUL ON TAIL AND Airtack	JS
T622 NO. 2		
H622 #1		

Checked Out by Refuges at #6 - N/O

#8 - N/O

#89 - N/O

20.6% O₂, 0% CH₄, Oppmco & phones working

SIGNED BY:

William Campbell 1354-A

32476

COUNTERSIGNED BY

T. Moore

33357

Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-30-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom John Neely Time 2:50 AM or PM PM

Report received by: Russell Dunmore

Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs spot cleaned	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Tail Needs additional cleaning Drive to Head needs cleaned	RG SH	✓		
NORTH NO. 5	Takeup needs Add Cleaning, needs Spot Cleaned 60 ft further	SH	✓		
NORTH NO. 6	Needs Some Spot Cleaning	SH	✓		
NORTH NO. 7	Need Dusted	JN			
Longwall	Needs Dusted from 80K to Storage Unit	SH	✓		
GLORY HOLE					
TG-22 NO. 1	Needs Dusted, Tail needs add cleaning	JN			
TG-22 NO. 2	Needs spot cleaned + Dusted	JN			
HG-22 #1	Needs Dusted, 2 Belt Rails out 2 1/2 Bk. out by Drive	JN			

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% CH₄, 20.8% O₂, 0 ppm CO at time of exam

Travelways, Power Centers, Chargers, D-Boxes OK at time of exam

Visual check of CO monitors OK at time of exam

SIGNED BY: Russell Dunmore 1536-19

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: To Name

Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-30-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☐ No ☐ By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow (Shoveled tail & Greased tail) Bobby	RG
Ellis 5	Shoveled V-plow (shoveled BRK 27 to 24) Bobby	RG
NORTH 2		
NORTH 3		
NORTH 4	cleaned on tail	SH
NORTH 5	cleaned on V-Plows at tail & flow thru - CLEAN ON TAIL	SH
NORTH 6	cleaned on U-Plow	SH
NORTH 7	Ckd Splices CLEAN ON TAIL - GREASE	JN
Longwell	cleaned Mud on inby & outby Side of Drive Area, Greased Drive Brakes	SH
GLORY HOLE		
TG-22 NO. 1	CLEAN ON TAIL + V Plow - Grease TAIL	JN
TG-22 NO. 2	CLEAN under Drive Rollers	JN
HG-22 #1		

Refuge chambers 6, 8, 89 Bks clear at EXAM
Phones working at EXAM

SIGNED BY: Russell Lunn 1536-A

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: J. Munn

Mine Foreman

33359

Certificate No.

Scott Halstead 37567
Johnny Neely 33472

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-30-10 SHIFT: EVE AM OR PM TO 800 AM OR PM TO 1100 AM OR PM
ON-SHIFT EXAM. **PRE-SHIFT EXAM.**

Was this report phoned to outside Yes X No By Whom SKAGGS, Campbell Time AM or PM

Report received by: [Signature]
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Ousted	WC			
Ellis 5	Needs Ousted	WC	/		
Lwall	Needs Ousted 8BCK - Storage unit	JS	/		
NORTH NO. 3					
NORTH NO. 4	Tail Needs Add Cleaning Drive - Hd needs cleaned	WC	/		
NORTH NO. 5	Needs spot cleaned Co. Further Takeup Needs Add cleaning	WC	/		
NORTH NO. 6	Needs some spot cleaned	WC	/		
NORTH NO. 7	Needs Ousted	WC	/		
NORTH NO. 8					
GLORY HOLE	D-Box Pump OK	JS	/		
TG 2 NO. 1	Needs Ousted - Tail needs Add cleaning	WC/JS	/		
TG 2 NO. 2	Needs spot cleaned & dusted	JS	/		
		JS	/		
H6 22	Needs Ousted 2Belt Rails out 2' 2BCK & 4BCK	JS	/		

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

OB 64, OB 60, 208302

PC's, Chargers, 2 Box, Pump, Travel ways OK

SIGNED BY: [Signature] 1354-11

Belt Examiners and Certificate Numbers

[Signature] 32476

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: [Signature]

Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAM.

PRE-SHIFT EXAM.

Report received by: _____

[illegible]

Checked out by Refuges 6-8-89 all OK

Belt Examiners and Certificate Numbers

35307

Certificate No:

Use Indelible Pencil or Ink

Was this report phoned to outside Yes No By Whom Brought out Time AM or PM

Signed

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

0% CH₄ 0% CO 20.8802

PC's, chargers, D-Boxes, RINGS, Tracheas OK

Johny Neely 33472

Certificate No.

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-31-10 SHIFT: owl 1100 AM OR PM TO 300 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
ELISH SOUTH	cleaned Tail	CU
ELISH NORTH	cleaned Tail cleaned take-up LC	CU
NORTH 2		
NORTH 3		
NORTH 4	cleaned Tail (ground out) cleaned take-up LC	CU, BC
NORTH 5	cleaned Footman cleaned take-up LC	CU
NORTH 6	shoveled Tail	BC
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		
TL 22 #2	SHOVEL V-Plow	JS

Checked out by Refuges 6-8-89 OK

SIGNED BY: Don Miller 15397 John Smith 32476

Belt Examiners and Certificate Numbers

William Campbell 13547A
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. M. M...

Mine Foreman

33359

Certificate No.

Superintendent

Certificate No.

PRE-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-31-10 SHIFT: Day AM OR PM TO 12:00 AM OR PM TO 3:00 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☒ No ☐ By Whom John Beckford, John Neely Time 2:45 AM or PM

Report received by: Russell Hummer
Signed

BELTS	VIOLATION AND OTHER HAZARDOUS CONDITIONS OBSERVED	EXAMINER	PRE- SHIFT	COUNT SIGN	*FIRE RUN
Ellis 4	Needs Dusted	RG	✓		
Ellis 5	Needs Dusted + Spot cleaned	RG	✓		
NORTH NO. 2					
NORTH NO. 3					
NORTH NO. 4	Drive-Discharge needs Add. cleaning	RG JAB	✓		
NORTH NO. 5	Needs spot cleaned 60-Flow-Thru, ^{Take-up needs} Add. cleaning	JAB	✓		
NORTH NO. 6	Needs spot cleaned, Tail needs add. cleaning	JAB	✓		
NORTH NO. 7	Needs Dusting, Flowthru Needs additional Cleaning	SH	✓		
Longwall	Needs Dusted RBK-Storage Unit	SH	✓		
GLORY HOLE					
T6-22 NO. 1	Tail needs add. cleaning, Needs Dusted				
T6-22 NO. 2	Needs spot cleaned + Dusted, ^{Tail needs} add. cleaning				
HG-22 #1	Needs Dusted, 2 Bolt Rails out 2 1/2' back outby Drive				

*FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS

(ITEMS NOT A HAZARD BUT NEEDING ADDITIONAL ATTENTION) REMARKS:

0% Ch 4, 20.8% O₂, Oppm CO at time of exam
Travelways, Power Centers, Chargers, D-Boxes OK at time of exam
Visual Check of CO monitors OK at time of exam

Don Allen 1536A

SIGNED BY: Russell Hummer 1536-A

Belt Examiners and Certificate Numbers

John Beckford 26171

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY: T. Moore 33359

Mine Foreman

Certificate No.

Superintendent

Certificate No.

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-31-10 SHIFT: DAY 6:00 AM OR PM TO 3:00 AM OR PM ON-SHIFT EXAM. AM OR PM TO AM OR PM PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:

Signed

BELTS	ACTION TAKEN	INT.
Ellis 4	Shoveled V-plow shoveled tail & Greased tail / Bobby	RG
Ellis 5	Shoveled V-plow (Shoveled tail & Greased tail) / Bobby	RG
NORTH 2		
NORTH 3		
NORTH 4	Shoveled V-plow, R&D duster at Tail, cleaned tail & flow thru 5th	RG
NORTH 5	Cleaned at Tail & flow thru	SAB
NORTH 6	Cleaned & duster at Tail.	SAB
NORTH 7	Greased on tail Roller, R&D Duster	SH
Longwall	Cleaned around Drive Area, Greased on Drive Bearings	SH
GLORY HOLE		
TG-22 NO. 1	CLEAN TAIL & on Flow Thru - Grease Holdup Roller	JN
TG-22 NO. 2	CLEAN on TAIL	JN
HG-22 #1	Dust Drive Area - Work on Guards	JN

Refuge Chambers 6, 8, 9, 8 OK + phones working at time of exam

SIGNED BY: Russell Sumner 1536-19

Belt Examiners and Certificate Numbers

John G. Beckford 26176

Belt Examiners and Certificate Numbers

Scott Halstead 37567

Johnny Neely 33472

COUNTERSIGNED BY T. Plumer

Mine Foreman

30309

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

Was this report phoned to outside Yes _____ No ☒ By Whom _____ Time _____ AM or PM

Signed

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

0% CH₄, 0% CO, 20.8% O₂ AT TIME OF EXAM

TRAVEL ways, POWER CENTER, D-Box, CHANGING OFF AT TIME OF EXPAN

Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

T. Brown

Mine Foreman

Certificate No.

Superintendent

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT EXAMINATION OF BELT CONVEYORS

DATE 3-31-10 SHIFT: EVE 600 AM OR PM TO 800 AM OR PM AM OR PM TO AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes No By Whom Time AM or PM

Report received by:
Signed

BELTS	ACTION TAKEN	INT.
SOUTH 1		
NORTH 1		
NORTH 2		
NORTH 3		
NORTH 4	set Amp at Tail	GU
NORTH 5	Cleaned Tail + Flow from	GU
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Refuges 6-8-89 OK

SIGNED BY: John Miller 15394
Belt Examiners and Certificate Numbers

Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. M. M. 33307
Mine Foreman Certificate No.

Superintendent

Certificate No.

Use Indellible Pencil or Ink

Was this report phoned to outside Yes No By Whom Brought out Time AM or PM

Signed

***FIRE RUN EXAMINATION: AFTER LAST PRODUCTION SHIFT OF WEEK, BEFORE HOLIDAY AND VACATIONS**

02CH4 06 CO 20-8802

AC's, chargers, O-Box, Pump Travelings OK

Belt Examiners and Certificate Numbers

Certificate No.

Use Indelible Pencil or Ink

ON-SHIFT
EXAMINATION OF BELT CONVEYORS

DATE 4-1-10 SHIFT: a1 11a AM OR PM TO 300 AM OR PM
ON-SHIFT EXAM. PRE-SHIFT EXAM.

Was this report phoned to outside Yes ☐ No ☐ By Whom _____ Time _____ AM or PM

Report received by: _____

Signed

BELTS	ACTION TAKEN	INT.
<u>E1154</u>	<u>worked on E11.54 on Hd Hole</u>	<u>GL</u>
NORTH 2		
NORTH 3		
NORTH 4		
NORTH 5		
NORTH 6		
NORTH 7		
NORTH 8		
GLORY HOLE		
LBB NO. 1		
LBB NO. 2		

Checked out by Rodgers 6-8-89 OK

SIGNED BY: [Signature] 15394

Belt Examiners and Certificate Numbers

[Signature] 32476
Belt Examiners and Certificate Numbers

COUNTERSIGNED BY T. Moore 33309

Mine Foreman

Certificate No.

Superintendent

Certificate No.

APPENDIX AE

ADDITIONAL INFORMATION ON UBB MMU'S