

# Preliminary Report of Accident

U.S. Department of Labor  
Mine Safety and Health Administration



PR001 08/05/2021

<b>1. Accident Type</b> F - Fatal Injury		<b>2. Accident Classification</b> 16 - Inundation		<b>3. Date/Time of Accident</b> 08/01/2021 10:08 PM		<b>4. Date/Time of Death</b> 08/02/2021 11:30 AM		<b>5. Fatal Case No</b> FAI-6463481-1		
<b>6. Mine Information</b>										
<b>a) Mining Company Name:</b>		Gentry Mountain Mining LLC								
<b>b) Mine Name:</b>		Gentry Mine #3								
<b>c) Parent of Mining Company:</b>		Patrick Peterson								
<b>7. Mine Location Information</b>					<b>8. Mine ID Number</b>		<b>9. Union</b>			
<b>a) City</b> HUNTINGTON		<b>b) County</b> Emery		<b>c) State</b> UT		42-02263		No		
<b>10. Primary Mineral Mined</b> Bituminous Coal Underground Mining				<b>11. Number of Employees</b>		<b>d) Mill/Prep Plant</b>		<b>e) Other</b>		
				<b>a) Total</b> 122		<b>b) Underground</b> 110		<b>c) Open Pit/Quarry</b> 12		
<b>12. Contractor Name</b>						<b>13. Contractor Union</b>		<b>14. Contractor ID Number</b>		
<b>15. Contractor Address</b>										
<b>a) City</b>		<b>b) County</b>			<b>c) State</b>			<b>d) Zip Code</b>		
<b>16. Number of Contractor Employees</b>										
<b>a) Total</b>		<b>b) Underground</b>			<b>c) Open Pit/Quarry</b>		<b>d) Mill/Prep Plant</b>		<b>e) Other</b>	
<b>17. Number of Persons in Mine at Time of Accident</b>					<b>18. Number of Persons Unaccounted for</b>					
<b>a) Mine Employees</b> 16		<b>b) Contractor Employees</b>			<b>a) Mine Employees</b> 0		<b>b) Contractor Employees</b>			
<b>19. Accident Location</b> 02 - Surface at Underground								<b>20. Mining Height</b> 7 Feet 6 Inches		
<b>21. Nonfatal Injuries</b> 0		<b>22. Fatal Injuries</b> 1								
<b>23. Victims Information</b>										
Gary Nelson										
<b>a) First Name</b> Gary		<b>a) MI</b>	<b>a) Last Name</b> Nelson		<b>b) Age</b> 48	<b>c) Regular Job Title</b> Section Utility person		<b>d) Activity at Time of Accident</b> Riding in personnel carrier to mine portal		<b>Employee</b> Mine Employee
<b>24. Mining Experience</b>										
<b>a) Total Experience</b> 12 Years 41 Weeks 1 Days			<b>b) Experience at the Mine</b> 9 Years 41 Weeks 1 Days			<b>c) Experience at the Activity at the Time of the Accident</b> 9 Years 41 Weeks 1 Days		<b>d) Experience with Contractor</b> 0 Years 0 Weeks 0 Days		
<b>25. Autopsy Performed</b> No		<b>If Yes, Location</b>								
<b>26. Mine Telephone No.</b> (801) 486-1458										
<b>27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)</b> A miner drowned in a flash flood. As the personnel carrier was being engulfed by water, the miner exited the vehicle and the water carried him away.  <i>The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.</i>										
<b>28. Equipment Manufacturer</b> Jeep Personnel Carrier					<b>29. Model</b> Personnel Carrier					
<b>30. District</b> C0900 - Lakewood District					<b>32. Field Office</b> C0905 - Price UT, Field Office			<b>33. Event Number</b> 6463481		
<b>34. Accident Investigator</b>										
<b>First Name</b> Daniel		<b>MI</b>		<b>Last Name</b> Lyons						
<b>35. MSHA Person Notified</b>										
<b>First Name</b> Cord		<b>MI</b> D		<b>Last Name</b> Cristando			<b>Date/Time Notified</b> 08/02/2021 12:59 AM			
<b>36. Type of Report</b> Initial		<b>37. Name of Preparer</b>			<b>Date Prepared</b>					
		<b>Full Name</b> Daniel Lyons			08/03/2021					
<b>38. Reason for Amendment</b>										