Preliminary Report of Accident

U.S. Department of Labor Mine Safety and Health Administration

PR001 12/07/2021

1. Accident Type	2. Accident Classification 3. Date/Time of Accident		cident	4. Date/Time of Death	5. Fatal Case No	5. Fatal Case No	
F - Fatal Injury	17 - Machinery	12/04/2021 1:05 AM		12/04/2021 2:13 AM	FAI-6484598-1	FAI-6484598-1	
6. Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company:	River View Coal LLC River View Mine Alliance Resource Partners LP						
7. Mine Location Information				8. Mine ID Number	9. Union		
a) City Waverly	b) County Union	c) State KY		15-19374	No		
10. Primary Mineral Mined Bituminous Coal Underground M	fining	11. Number of Emp a) Total 726	loyees b) Underg 628	ground c) Open Pit/Quarry	d) Mill/Prep Plant	e) Othe	
12. Contractor Name Custom Staffing Industrial Service	ces	1 12		13. Contractor Union	14. Contractor ID Nu		
15. Contractor Address a) City Evansville	b) County		c) State IN	d) Zip Code 47715			
16. Number of Contractor Employo a) Total 87	ees b) Underground 87	c) Open Pit/Qua	arry	d) Mill/Prep Plant	e) Oth	ier	
17. Number of Persons in Mine at a) Mine Employees 211	Time of Accident b) Contractor Employees 50	18. Number of Pers a) Mine Employ		ted for b) Contractor Employees 0			
19. Accident Location 01 - Underground		'			20. Mining Height 5 Feet 7 Inches	S	
21. Nonfatal Injuries	22. Fatal Injuries				·		
23. Victims Information							
Lester Daugherty Jr.							
' ' '	, -	Regular Job Title d Mechanic	Activity at Tir Mechanic	me of Accident	Employee Mine Employe	e	
24. Mining Experience a) Total Experience 16 Years 0 Weeks 0 Days	b) Experience at the Mine 3 Years 0 Weeks 0 Days	c) Experience at the 12 Years 0 Weeks		Time of the Accident	d) Experience with Contractor 0 Years 0 Weeks 0 Days	or	
25. Autopsy Performed	If Yes, Location						
	Madisonville, KY						

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)

On a non production shift, a mechanic was performing maintenance duties on a continuous mining machine (CMM) when the raised CMM tail boom lowered resulting in fatal crushing

The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer Komatsu			29. Model 14CM15-11BX	
30. District			32. Field Office	33. Event Number
C1000 - Madisonville District			C1002 - Sturgis KY Field Office	6484598
34. Accident Investigator				
First Name	MI	Last Name		
Philip	A.	Carlisle		
35. MSHA Person Notified				
First Name	MI	Last Name	Date/Time Notified	
Irvin	R.	Wright	12/04/2021 1:29 AM	
36. Type of Report	37. Name of	Preparer		
Amended	Full Name)	Date Prepared	
	Curtis R Hardison		12/05/2021	

38. Reason for Amendment

Initially listed Louisville, Kentucky as the site of the autopsy. Report has been amended to reflect the correct location as Madisonville, Kentucky.